Paper weight-110# (minimum)

Black nonfading ink required

U.S. PUBLIC LAND SURVEY MONUMENT RECORD

			CODE IN:		1 22 23 24 25 _A	FULTON TWP
B C O	5	\	3	7	7	
D E						
FG	9	9	0			
H					G H	North Elev
K L	~	76	15	A	J K	East
M					N	TT TT
O P	9		2	-3-	A P	
Q						LATITUDE ELLIPS. H
S T	3	38	3	ΛÓ	S T	LONGITUDE
UV					U	**
WX	2	2	20	25	o v	V
Y					Y	
PLACE M	ONUMENT	SYMBOL	AT P	7 18 19 20 2 ROPER	1 22 23 24 25	BASED ON THE FOLLOWING CONTROL:
LOCATIO	N ON AB	OVE INDE	X. T			
(a)	N ON AB	OVE INDE	X. T		0	WITNESS MONUMENT

BEARINGS ARE BASED ON:___

FIELD BOOK _____ PAGE # ____ SHEET ___ OF SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.

PLANNING & ZONING COMMITTEE ADOPTED THIS FORM ON 12/2/1982

CORNER CODE

R-19(1)

Fu590^

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

1836 (JULY 11) BURNHAM EAST RANDOM BETW SECS 23 & 26 5270.1 INT EAST BDY 19.8' NORTH

> WEST 1/2 FIRST RATE BUR DAK; DAK DPENINGS GENTLY ROLLING- EAST 1/2 GOOD 2ND RATE W & BUR OAK OPENINGS BEING BROKEN

> > WEST CORRECTED BETWN SEC 23 & 26

2634.72 SET 1/4 SEC POST BUR DAK 12 N24W 19.8'; BUR DAK 12 S70E 11.88'

4660.26 BUR OAK 10 IN DI

5270.1 TO CORNERS JULY 11 1836

- 1885 RUGER VOL 2 PG 383 & #1332 FD REMAINS OF STUMP OF SE BT TOOK BT BLK OAK 9 S63W 21.62' VAR 5-41 2642.31 TO SE COR SEC 23, VAR 6-13 2654.52 TO CEN SEC 23, & 5308.05 TO N 1/4 COR SEC 23.943.8' SOUTH OF CENTERLINE OF HIGHWAY
- ???? #1332 NEW BT BL 0 9 S63W 21.62'; 943.8' SOUTH OF 18?? CENTER OF HIGHWAY
- 1966 SHIMEALL #1364 & 1365 3X7X12 SANDSTONE SURROUNDED BY HARD HEAD STONES. SO-19-W 1322.0 TO STONE @ $1/16^{TH}$ COR.
- 1967 SHIMEALL #1384 ANGLE 89-42-30 @ N 1/4 26 FROM L.S @ 1/16TH COR OF NW 1/4 OF SEC 26 TO NORTH LINE OF NW 1/4
- 1968 SHIMEALL #1365 3X7X12 STONE SURROUNDED BY HHs. SOUTHERLY 256.00 TO PIPE (PROPERTY COR), WESTERLY 306.00 TO PIPE (PROPERTY COR), 562.0' WESTERLY TO PROPERTY COR, WESTERLY 818.0' TO PROPERTY COR, & ANGLE 89-42-30 @ N 1/4 COR SEC 26 FROM N/S 1/4 LINE SEC 26 TO NORTH LINE OF NW 1/4 SEC 26.
- 1969 DOT #11190 CTH M STATES NOTHING ABOUT MON.
- 1972 COMBS #13245 FD MON STATES STATES NOTHING ABOUT MON. 2635.80 TO NE COR SEC 26 & ANGLE 90-03 @ NE COR SEC 26 FROM E $\frac{1}{4}$ COR SEC 26 TO N $\frac{1}{16}$ COR OF NE $\frac{1}{4}$ SEC 26, 1317.40 TO N 1/16TH COR OF NE 1/4 SEC 26, & 1318.40 FROM N 1/16TH COR OF NE 1 /4 SEC 26 TO NE COR SEC 26.
- 1972 LEE #1388 LEGEND CALLS FOR SETTING PIPE. 2650.67 TO NW COR SEC 26, 2635.88 TO NE COR SEC 26, 2654.51 TO CEN SEC 26, 5297.92 TO S 1/4 COR SEC 26, ANGLE 179-4136 @ N ¼ COR SEC 26 FROM NE COR SEC 26 TO NW COR SEC 26
- 1973 SHIMEALL CSM VOL 3 PG 78 STONE ANGLE 89-39-30 @ N 1/4 COR SEC 26 FROM N/S 1/4 LINE SEC 26 TO NORTH LINE OF NW 1/4 SEC 26.
- 1973 SHIMEALL CSM VOL 3 PG 290 STONE. SOUTHERLY 1322.0 ALONG N/S 1/4 LINE SEC 26 TO STONE.
- 1977 COMBS CSM VOL 7 PG 188 STATES NOTHING ABOUT MON.
- 1977 COMBS #12911 & 12912 CALLS FOR COR BUT STATES NOTHING ABOUT MON. MORTGAGE INSPECTION.
- 1977 BARNES VOL 5 PG 287 THERE IS A PROBLEM WITH THE CENTER OF SEC 26. MR. CLAYTON SHIMEALL SUPPOSEDLY SET THE CENTER AT THE INTERSECTION OF THE E/W & N/S 1/4 LINES. THE N 1/4 COR SEC 26 AGREES WITH THE SHORT TIES THAT MR. SHIMEALL HAD ON A PLAT OF SURVEY. MY COMPUTATIONS SHOW THAT THE INTERSECTION OF THE E/W AND N/S 1/4 LINE IS AS RECORDED BY MR. LEE ON THE PLAT OF SURVEY DATED OCT 30,1972.
- 1977 BARNES VOL 5 PG 288 FD C.I. 2652.79 TO FD PIPE AT CEN OF SEC 26
- 1984 BRANDT CSM VOL 11 PG 473 USED BUT STATES NOTHING ABOUT MON.
- 1985 COMBS #13622 STATES NOTHING ABOUT MON. SOUTHERLY 868.0 TO PIPE

PAGE 1 OF 3 CORNER CODE R-19(1)

Daral Poures 8-08-07

FU590

- 1990 BARNES VOL 6 PG 406 FD CI MON. 5301.51 TO N $^{1}\!\!\!/$ COR SEC 23, ANGLE @ N $^{1}\!\!\!/$ COR SEC 23 FROM NE COR SEC 23 TO S $^{1}\!\!\!\!/$ COR SEC 23 IS 89-43-30 & ANGLE @ N $^{1}\!\!\!/$ SEC 23 FROM S $^{1}\!\!\!/$ COR SEC 23 TO NW COR SEC 23 IS 90-00-13
- 1990 BARNES R-19 FD C.I. 1.3' NORTH OF E/W FENCE, 1.8' EAST OF N/S FENCE. PLACED CARSONITE POST 1.3' SOUTH OF CI. REFERENCED SAME.
- 1995 LATHROP CSM VOL 18 PG 102 CI 2636.80 TO NE COR SEC 26.

FD CI/CARSONITE POST & REFERENCE RERODS.

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED FD PERPETUATED LOCATION.

- D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.

 NDNE
- (E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location. \square

I, **Donald Barnes**, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Emboss

8-08-07

SHEET 2 OF 3

CORNER CODE R-19(1)

A.E. 7.08 REQUIREMENT

