__PAGE #

SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING

PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.

PLANNING & ZONING COMMITTEE ADOPTED THE ABOVE FORM ON 12/2/1982

SHEET _

CORNER CODE L-25

BE4029

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

1833 SEP MULLETT NORTH ON EAST SIDE SECTION 13

2211 STREAM 3.96' CROSSES S.W.

2640 SET QUARTER SECTION POST BUR OAK 18 S77W 280.5 & BUR

OAK 18 N71 1/2W 252.78'. (E 1/4 COR SEC 13).

4108.5 STREAM 3.96' CROSSES S.E 5148' LEAVE WET PRAIRIE & MARSH

5280 SET POST CORNER SECTIONS 12 & 13 BUR OAK 14 N13W 0.34,

BUR OAK 12 S7E 0.81

LAND MOSTLY LEVEL AND WET. 1871 COLLINS NEWARK REMONUMENTATION FIELD NOTES. NORTH ON EAST LINE OF

13. VARIATION 5

2293.5 BROOK

2447.94 BROOK

2456.52 BROOK 2488.2 BROOK

2488.2 BROOM

2547.6 BROOK

2560.8 BROOK

2663.76 SET 1/4 STONE

CONTINUED NORTH. SAME VARIATION

5327.52 SET STONE FOR CORNER 12 & 13 BY STUMP AND ROOTS OF WITNESS TREES.

1878 RUGER VOL 2 PG 260 2657.16 TO NW & SW CORNERS OF SEC 18. SHOWS E 1/4 COR SEC 13 AS NORTH OF W 1/4 COR SEC 18

19?? VOL 4 PG 109 SET CON MON. & REFERENCED SAME. 2664.40 TO NW & SW CORNERS OF SECTION 18.

LAND OWNER SAID DNR TRAPPED THE BEAVERS AND BLEW UP THEIR DAM LAST WINTER. FROM THE DIGITAL AIR PHOTOS IT APPEARS THAT THE WIDTH OF THE BROOK INCREASED SUBSTANTIALLY BECAUSE OF THE BEAVER DAM. CORNER FALLS IN THE BROOK. SEARCHED BROOK BOTTOM AND ALONG BANK AND DID NOT FIND CUT LIMESTONE. RESTORED CORNER ON LINE & MIDWAY BETWEEN THE NE & SE CORNERS OF SECTION 13 NEWARK TWP AS COLLINS DID.

- C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location? CORNER RESTORED THROUGH ACCEPTANCE OF OBLITERATED EVIDENCE LOCATION.
- D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.
- (E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.
- I, Donald Barnes, hereby certify that the corner points as identified by the corner code index were, in a field survey on, APRIL 1998, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with the regulations and rules as required in the current manual of survey instructions of the United States Department of Interior, Bureau of Land Management.

COS MO MINOR LA

COUNTY SURVEYOR FILING DATA

Date of computer entry

Date microfilmed

Number of included sheets _______ CORNER CODE /_ 24

EMBOSS LAND SURVEYOR SEAL.

A-E 7.08 REQUIREMENT