

Paper weight-110# (minimum)

Black nonfading ink required

U.S. PUBLIC LAND SURVEY MONUMENT RECORD

For Public Land Survey Corners In:

WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT

T. 4 N. R. 12 E. 4th P.M.

REV 10/23/2004

USMONREC.DWG

CORNER CODE INDEX

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	
A																									A
B																									B
C	6																								C
D																									D
E																									E
F																									F
G																									G
H	7																								H
J																									J
K																									K
L	18																								L
M																									M
N																									N
O																									O
P	19																								P
Q																									Q
R																									R
S																									S
T																									T
U	30																								U
V																									V
W																									W
X																									X
Y																									Y
Z																									Z
	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25

FULTON TWP
ROCK COUNTY WI

IF AVAILABLE
ROCK COUNTY COORDINATES PREFERRED

North _____ Elev. _____

East _____

Hor. Datum _____ Vert. Datum _____

LATITUDE _____ ELLIPS. HT. _____

LONGITUDE _____

NAD83(91) _____ NETWORK ADJ. YR _____

GPS (X) _____ TRAVERSE (X) _____

BASED ON THE FOLLOWING CONTROL:

PLACE MONUMENT SYMBOL AT PROPER LOCATION ON ABOVE INDEX

CORNER MONUMENT

WITNESS MONUMENT

(a)

BEARINGS ARE BASED ON: _____

FIELD BOOK _____ PAGE # _____

SHEET 1 OF 4

SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.

PLANNING & ZONING COMMITTEE ADOPTED THIS FORM ON 12/2/1982

CORNER CODE T-5

FU595

I FD A 1 1/2 " PIPE SURROUNDED BY 4 HH @ THE W 1/16TH CORNER OF THE SW 1/4 OF SEC 29. THE PIPE WAS LEANING A LITTLE TO THE SW. THE PIPE IS 0.24' TO THE WEST OF A LINE BETWEEN THE W 1/4 COR & THE SW CORNER OF SEC 29

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

I DID NOT FIND A RECORD FOR THE PLACEMENT OF THE CI MONUMENT. THE 1975 WPL ANGLE @ THE NW COR SEC 29 FROM THE N 1/4 COR SEC 29 TO THE W 1/4 COR SEC 29 IS 90-38-44. MY ANGLE IS 90-38-46. SINCE THE ANGLE DIFFERENCE IS ONLY 2" AND MY DISTANCE OF 2655.27 FROM THE NW COR SEC 29 TO THE W 1/4 COR SEC 29 IS 0.18' DIFFERENT THAN WPL'S GRID DISTANCE OF 2655.09, THE CI PROBABLY MONUMENTS THE LOCATION OF THE W 1/4 COR SEC 29 THAT WPL USED. SINCE THE CI IS IN HARMONY WITH RUGERS DISTANCES, OLD RECORD OCCUPATION, CLOSE TO THE DISTURBED LIMESTONE OF RECORD, AND LINE WITH THE PIPE FD AT W 1/16TH COR OF THE SW 1/4 OF SEC 29, I AM ACCEPTING THE FD CI.

D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.

BASED ON THE DIFFERENCE OF 0.23' BETWEEN THE MY DISTANCE AND RON COMB'S DISTANCE TO THE NW COR SEC 29 AND THE LOCATION OF THE TOP OF THE HORIZONTAL CI PIECE, I BELIEVE HIS LOCATION IS DIFFERENT THAN MINE. HIS LOCATION MAY BE THE EDGE OF THE TOP OF THE HORIZONTAL PIECE. BASED ON BELOW GROUND PHICAL EVIDENCE, I DON'T BELIEVE HE PLACED A PIN AS STATED IN HIS CSM. ALSO BASED ON THE RECORD DISTANCES, I BELIEVE THIS LOCATION IS NOT THE SAME AS SUNNY'S 1949 LOCATION. THE RECORD DISTANCES INDICATE HIS PIPE WOULD HAVE BEEN ABOUT 4' FARTHER SOUTH.

(E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.

I, **Donald Barnes**, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Seal
Donald Barnes
Emboss

9-12-07

SHEET 2 OF 4

CORNER CODE **T-5**

A.E. 7.08 REQUIREMENT

2X36" IRON PIPE

SUNNY 33

972 DEED BK2 PG295 204.44
FD R/R S3-04-04W 204.28
1989 SCHROEDER 204.44
1949 SUNNY 206
S00-07-34E 205.71

SUNNY 1227
BARNES 85-47-56
1949 SUNNY 85-50

S00-10-34E 238.91
1949 SUNNY 239.0

2007 BARNES 90-38-46

SEC 30

S00-04-41E 2655.27
1949 SUNNY 2659

SUNNY 660

S00-04-06E 2416.36
1949 SUNNY 2420

DID NOT SEARCH

SEC 29

1949 SUNNY N85-12E 1068.7

FD PIPE

1884 RUGER VAR 5-05 2658.32
N00-22-18E 2663.79

N89-27-15E 5277.05
1884 RUGER 5270.60

W 1/4 COR
SEC 29

N89-27-15E 2639.34
1884 RUGER VAR 5-30 2635.88

1319.67 N89-27-15E 1319.67
1317.94 RUGER 1317.94

1884 RUGER 1908.27
1949 SUNNY N/S FENCE 1914

(MINE) $1319.67 + (RUGER) 594 = 1913.67$

NO FENCE LINE

1884 RUGER VAR 5-30 2637.72
N89-27-15E 2637.72

INT. OF 1/4 LINES

SEC 30

N00-04-01E 2656.18
1975 WPL 2656.39
1884 RUGER VAR 6-02 2652.38

N00-04-39E 1330.58
1949 SUNNY 1326
1884 RUGER 1326.19

SUNNY 378

SEARCHED &
FD NOTHING
NO FENCE LINE

N00-22-18E 2667.88
1884 RUGER VAR 5-05 2654.42


SEC 29

024
WEST
LINE

N00-03-23E 1325.60
1884 RUGER 1326.19

SUNNY 194

FD 1 1/2" LEANING TO
SW PIPE SURROUNDED
BY 4 HH



HIGH VOLTAGE
TRANS. TOWER

1332.79 1989 COMBS

1884 RUGER VAR 5-05 5322.74
N00-22-18E 5331.67

1884 RUGER 5245.35
2007 BARNES 5251.91

1884 RUGER VAR 5-45 2621.19
1864 LOCKE VAR 7-45 2618.22
1999 GRENLIE 2625.11
N89-42-19E 2625.06

1884 RUGER VAR 5-55 2624.16
1864 LOCKE VAR 7-45 2614.26
1976 NORTHROP 2626.80
N89-16-34E 2626.85

1884 RUGER VAR 4-16 2654.85
1985 NORTHROP 2659.92
N00-36-31E 2659.91

EMBOSSED
SEAL
Donald Barnes
9-12-07

SHEET 4 OF 4

T-5