Paper weight-110# (minimum)

Black nonfading ink required

## U.S.

# PUBLIC LAND SURVEY MONUMENT RECORD

For Public Land Survey Corners In: T. \(\perp\)N. R. \(\frac{2}{-}\)E. 4th P.M.	WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT REV 10/23/2004 USMONREC.DWG
CORNER CODE INDEX  A 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24	FULTON TWP
	ROCK COUNTY WI  C D IF AVAILABLE  ROCK COUNTY COORDINATES PERFERRED  F G
H J K L M M M M M M M M M M M M M M M M M M	H North Elev.  K East L M How Date to Market Date Date Date Date D
NO PO O O O O O O O O O O O O O O O O O	M Hor. Datum Vert. Datum O P Q LATITUDE ELLIPS. HT
T 79 79 78 71 76 72	R   S   LONGITUDE
W X Y Z 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 PLACE MONUMENT SYMBOL AT PROPER	x GPS (X) TRAVERSE (X) z BASED ON THE FOLLOWING CONTROL:
LOCATION ON ABOVE INDEX  CORNER MONUMENT  (a)	WITNESS MONUMENT

MP

BEARINGS ARE BASED ON:\_\_\_\_\_

FIELD BOOK \_\_\_\_\_ PAGE # \_\_\_\_ SHEET \_\_\_ OF /\_\_\_\_ SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.
PLANNING & ZONING COMMITTEE ADOPTED THIS FORM ON 12/2/1982

CORNER CODE 5 - 18/1

#### FU M.P.638

(B)  $\overline{D}$ escribe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

1834 HARRISON

EAST BETWEEN SECS 11 & 14

2194.5 TRAIL CRS NE

2483.58 INT. RIGHT BANK OF ROCK RIVER SET MEANDER POST BEARINGS {W.O. 18 N74W 82.5' W.O. 18 S51W 132.00' LAND & SAME

1836 (JULY/AUG) BURNHAM WEST RANDOM BETWEEN SEC 11 & 14

1808.4 TO LEFT BANK ROCK RIVER

2534.4 INT RIGHT BANK 28.38' SOUTH OF M.P. FIRST RATE BUR OAK OPENINGS

CORRECTED BETWN 14 & 11

726 SET MP ON LEFT BANK BUR OAK 8 S211/2E 19.8'

BUR DAK 8 N46E 67.98'

858 BUR DAK 10 IN DIA

2534.4 TO CORNERS

1836 (JULY/AUG) BURNHAM WEST RANDOM BETWEEN SEC 11 & 14

1808.4 TO LEFT BANK ROCK RIVER

2534.4 INT RIGHT BANK 28.38' SOUTH OF M.P. FIRST RATE

BUR DAK OPENINGS

CORRECTED BETWN 14 & 11

726 SET MP ON LEFT BANK BUR OAK 8 S211/2E 19.8'

BUR DAK 8 N46E 67.98'

858 BUR DAK 10 IN DIA

2534.4 TO CORNERS

1984 BARNES J18/19 SET POLY MON. & REFERENCED SAME. POLY
43 WEST OF BANK OF ROCK RIVER & 2' SOUTH OF SOUTH FACE
OF HSE #10056 PROJECTED TO THE EAST. CORNER WAS
REESTABLISHED BY LOST CORNER PROPORTIONATE METHODS.
THE PRORATED DISTANCE IS IN THE RIVER. I DID VERY LITTLE
FIELD SEARCH FOR THE CORNER. IT IS VERY UNLIKELY THAT
THE 1833 WOOD POST SURVIVED THE LAWN WORK. ON LINE
WITH NW & NE CORNERS OF SEC 14. S89-28-10W 2440.00 TO
NW COR SEC 14 & N89-28-10E 829.80 TO MP ON THE LEFT
BANK. BEARINGS ARE BASED ON GRID NORTH. GRID NORTH IS
0-39-35 EAST OF TRUE NORTH.

### FD POLY & REFERENCE MONUMENTS.

 $\Box$ ) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

### ACCEPTED FD MON.

D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.

## NONE

(E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.

YES

I, **Donald Barnes**, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

SHEET 1 OF 1

Barnes

CORNER CODE J-18/19 (/ )

A.E. 7.08 REQUIREMENT

11/07/07