Paper weight-110# (minimum)

Black nonfading ink required

CORNER CODE

U.S. PUBLIC LAND SURVEY MONUMENT RECORD

Public Land Survey Corners In: WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT T. 4 N. R. 10 E. 4th P.M. REV 10/23/2004 CORNER CODE INDEX UNION ROCK COUNTY WI В C D C D IF AVAILABLE E ROCK COUNTY COORDINATES PERFERRED E F G H North Elev. K East L M ____ Vert. Datum Hor. Datum o P **LATITUDE** Q ELLIPS. HT. Q R S LONGITUDE T U NAD83(91) _____NETWORK ADJ. YR GPS (X) TRAVERSE (X) BASED ON THE FOLLOWING CONTROL: 9 10 11 12 13 14 15 16 2 3 4 5 6 7 8 9 PLACE MONUMENT LOCATION ON ABOVE INDEX **♦ CORNER MONUMENT** WITNESS MONUMENT \circ (a) BEARINGS ARE BASED ON: ASSUMED Datum S89 *25 · 51 "E 48.65 (REC. 48.56°) 50. **BULLARD** Set Railroad 61.0 ROAD 53 Found 1" Iron Pipe Disturbed, 72.43 S82 °27 '23 "W Set 7/8" X 24" Iron Rebar Sign FIELD BOOK PAGE # SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.

PLANNING & ZONING COMMITTEE ADOPTED THIS FORM ON 12/2/1982

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

Set railroad spike at the intersection of a straight line extended, from the W14 corner of Section 15-4-10, to a point 33 feet South of an iron pipe found hear the SE Corner of Combs Survey No. 88-240, at a distance of 57.88 feet from the NW reference pipe of County Surveyor Records, Volume 4, Page 440.

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

Obliterated Evidence Location - See above

D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.

believe the 50 foot dimension shown to the 1st reference monument on County Surveyor Record Volume 4, Page 440 to be wrong.

(E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.

I, Rouald J. Com by hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

May 5, 2009 SHEET 2 OF Z

CORNER CODE

A.E. 7.08 REQUIREMENT