Paper weight-110# (minimum)

Black nonfading ink required

## U.S.

## LAND SURVEY **PUBLIC** MONUMENT RECORD

WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT For Public Land Survey Corners In: USMONREC.DWG T. 4 N. R. 10 E. 4th P.M. CORNER CODE INDEX UNION **TWP** ROCK COUNTY WI C  $\mathbf{C}$ IF AVAILABLE D D ROCK COUNTY COORDINATES PERFERRED E E F G G North Elev. H J K East L M Hor. Datum \_\_\_\_\_ Vert. Datum N O P **LATITUDE** ELLIPS. HT. Q R S T LONGITUDE NETWORK ADJ. YR 2010 NAD83(91) \_\_\_\_ GPS (X) \_\_\_\_ TRAVERSE (X) X BASED ON THE FOLLOWING CONTROL: 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 T SYMBOL AT PROPER 2 3 4 5 6 7 8 9 PLACE MONUMENT LOCATION ON ABOVE INDEX **♦ CORNER MONUMENT** WITNESS MONUMENT

(a) ROCK COUNTY PROJECTION BEARINGS ARE BASED ON:\_

FIELD BOOK PAGE #		2
OR OBSERVATION SHEET	SHEETOF	2
SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUME		
PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DI	EPTH.	
PLANNING & ZONING COMMITTEE ADOPTED THIS FORM ON 12/2/1982	,	

## E1/4CORSEC13

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

- BRINK & MULLETT (SEP)T4N R10E VAR 8-15 NORTH ON EAST SIDE OF SECTION 13
  - 1393.92 BUR OAK 16 IN DIAMETER
  - 2640.0 SET QUARTER SECTION POST BURR OAK 24 N10W 120.78';

BURR DAK 16 S9W 219.12'

- 2772.0 **ENTER PRAIRIE**
- 3762.0 ROAD @ EAST
- 5280.00 SET POST CORNER SECTIONS 12 & 13 IN PRAIRIE AND MADE A MOUND LAND ROLLING SECOND RATE FIRST 1/2 TIMBERED WITH WHITE BLACK AND BUR DAK LAST 1/2 PRAIRIE
- ORIG GOV PLAT NW COR SEC 18 PORTER TWP IS 122.00 1833 NORTH OF NE COR SEC 13 UNION TWP
- ORIG GOV PLAT NW COR SEC 19 PORTER TWP IS 66.00 1833 NORTH OF NE COR SEC 24 UNION TWP
- 1870 RUGER (SEP) REMONUMENTATION PG 103 SOUTH ON EAST LINE OF NE 1/4 SEC 13 (T4N R1OE) ON A VAR 6-55; OFFSET EAST 7.26' AT
  - INTERSECTED QUARTER LINE AT QUARTER 2661.12 CORNER. FOUND OLD STAKE AT CORNER. ALSO FOUND STUMPS OF BOTH BEARING TREES. COR VAR 7-05 SEPTEMBER 1, 1870

SOUTH ON EAST LINE OF SE 1/4 SEC 13 ON A VAR 7-00' OFFSET WEST 3.30'; OFFSET WEST 9.24' AT

- 2657.16 INTERSECTED SOUTH BOUNDARY LINE 10.89'?? WEST OF CORNER COR. VAR 6-53'
- 1961 BATTERMAN VOL 4 PG 112 FD 6X6 CUT STONE MON. AT THE WEST 1/4 COR OF SEC 18-4-11 OR THE EAST 1/4 COR OF SEC 13 UNION TWP. REFERENCED COR.
- BARNES VOL 6 PG 346 SOO-43-58W 2662.99 TO SW COR 1985 SEC 18; N89-49-29E 2498.54 S 1/4 COR SEC 18.
- BARNES VOL 6 PG 360 NO-27-42E 2698.97 TO NW COR 1986 SEC 18, SD-43-59E 2698.97 TO POLY @ SW COR SEC 18, 589-30-05E 1202.97 TO FD 1/16TH COR AS RECORDED IN VOL 4 PG 112 129' SOUTH OF E/W LINE, S89-40-29E 5165.84 TO FD ALUM @ E 1/4 COR SEC18. PLACED POLY
- BARNES L-1 DID NOT FIND ANY RECORD OF THE CORNER 1986 BEING ESTABLISHED. PLACED POLY MON ON LINE WITH SW & NW SEC 18 AT MID DISTANCE. PLACED CARSONITE POST NEXT TO MON. 1' EAST OF N/W FENCE & 100' NORTH OF CENTER OF PVMT.
- COMBS #9871 & #9870 E 1/4 COR SEC 13 UNION TWP FD 1993 POLY. N89-17-35W ALONG SEC LINE.
- COMBS #9873 CALLS FOR E 1/4 COR SEC 13 UNION TWP 1993 BUT STATES NOTHING ABOUT MON.
- COMBS #7381 FD ALUM, MON @ E 1/4 COR SEC 13, S88-1999 53-50W TO CI @ W 1/4 COR SEC 13.
- COMBS CSM 25 131 FD POLY @ E 1/4 COR SEC 13 UNION 2002 TWP. N89-31-15W 5231.59 TO SET PK @ @ 1/4 COR SEC 13

FOUND ALUM/ CARSONITE POST @ THE W 1/4 COR SEC 18, 3 REFERENCE MONUMENTS, & POLY MON 0.6' DEEP @ THE E 1/4 COR SEC 13. THE POLY MON. IS 2.5 SOUTH OF THE CENTER PVMT. PLACED MAGNETS ON THE SOUTH SIDE. THE TOP OF THE POLY MON IS BROKEN OFF. I PLACED A MAGNET ON THE NE SIDE & THE SOUTH SIDE OF THE POLY. OrelBane Nov1,2011

SHEET 1 OF 3 CORNER CODE L-25(2) C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED ALUM. MON. & POLY MON WHICH IS OVER THE CUT LIMESTONE @ E 1/4 COR SEC 13 UNION TWP.

D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.

IN 1961 BATTERMAN (VOL 4 PG 112) FD HARD HEAD 14X9X4 AT THE SOUTHEAST COR OF THE SOUTHWEST 1/4 OF THE NORTHWEST 1/4 OF SEC 18. HE REFERENCED THE CORNER & IN 1986 I PLACED A 1/2 X 24 REROD FROM THE TIES. THIS POINT DOESN'T SEEM TO FIT ANYTHING. IT IS 50.91 OFF A LINE BETWEEN THE E 1/4 COR SEC 13 & THE E 1/4 COR SEC 18. IT IS 129.28 OFF A LINE BETWEEN THE W 1/4 COR SEC 18 & THE E 1/4 COR SEC 18

(E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.

I, **Donald Barnes**, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

SHEET 2 OF 3

CORNER CODE L-25(1)

Baines

CORNER O

NOVI, ~ COII A.E. 7.08 REQUIREMENT

