Paper weight-110# (minimum)

Black nonfading ink required

## **PUBLIC** U.S. LAND SURVEY MONUMENT RECORD

For Public Land Survey Corners In:  T. N. R. OE. 4th P.M.  CORNER CODE INDEX  A	C
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 PLACE MONUMENT SYMBOL  AT PROPER LOCATION ON ABOVE INDEX  CORNER MONUMENT  (a)	WITNESS MONUMENT

FIELD BOOK PAGE # SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.

PLANNING & ZONING COMMITTEE ADOPTED THIS FORM ON 12/2/1982

BEARINGS ARE BASED ON:\_\_\_

## UN528 S1/4CORSEC3

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

1833 HARRISON

EAST ON RAND. BET SECS 3 & 10

2640 TEMPY 1/4 SEC COR.

5237.76 INT. E BDY 13.2' N OF POST. LAND LEVEL 2ND RATE TIMBER RED BURR & W.O. MOSTLY GRUB? GRASS & WEEDS

WEST COR. BET SECS 3 & 10

2618.88 QUARTER SEC COR. {BURR O 10" S3W 42.9', BURR O 10" N26W 28.38' BURR O 10 BURR O 10} MARKED

5237.76 INT. SEC COR.

1870 RUGER REMONUMENTATION (SEPTEMBER)

PG 112 WEST ON NORTH LINE OF NE 1/4 SEC 10 ON A VAR 7-10, AT

2648.25 INTERSECTED QUARTER LINE 13.86' SOUTH OF QUARTER CORNER FOUND STUMPS OF BOTH BEARING TREES AND ESTABLISHED CORNER FROM THEM. COR VAR 6-52. SEPTEMBER 5,1870

PG 111 WEST ON NORTH LINE OF NW 1/4 SEC 10 ON A VAR 7-15; OFFSET NORTH 1.32 AT

- 2636.04 INTERSECTED WEST BOUNDARY LINE 18.48 SOUTH OF CORNER. FOUND OLD STAKE AT CORNER ALSO FOUND STUMP OF SOUTH BEARING TREE. COR VAR 6-49
- 1942 SUNNY #5115 STATES NOTHING ABOUT COR. S86-17W 2626.5 FROM SET R/R @ N 1/16TH COR OF NW 1/4 TO SET R/R @ N 1/16TH COR OF NE 1/4 SEC 10
- 1972 BATTERMAN VOL 5 PG 75 SET CI.

Pershapernes 8-08-2009

- 1975 SCHROEDER VOL 5 PG 75 FB #1 PG 3 NOTES CI MON AT COR SET BY R.B. & M.L. (1972) PREVIOUS COUNTY SURVEYOR. CI MON 4' NORTH OF CENTER OF PVMT. REFERENCED CI. REFERENCED WITH 1" PIPES 1'+/- FROM FENCE LINES.
- 1975 WILHELM VOL 5 PG 162 & #7007 SET 5/8" REBAR 3' SOUTH OF CENTER OF PVMT. 40.0 SOUTH EASTERLY TO 36" OAK & 39.6' SOUTHWESTERLY TO 4" OAK. N89-27-57W 2641.91 TO STONE @ SW COR SEC 3 & S89-27-57E 2641.91 TO REBAR @ SE COR SEC 3.
- 1975 GRENLIE CSM VOL 4 PG 360 COUNTY SURVEYOR FD STONE. N/S 1/4 LINE TO S 1/4 COR SEC 10.
- 1996 KARNS CSM VOL 19 PG 269 COUNTY SURVEYOR COR @ SW & S 1/4 COR SEC 3. 1317.72 FROM 1/16TH COR TO SW & SE COR SEC 3
- 2000 COMBS CSM VOL 24 PG 204 FD PK @ S 1/4 COR SEC 3 & SET PK FROM TIES @ SE COR SEC 3. 2651.08 BETWEEN SE & S 1/4 COR SEC 3. EAST 361.97 TO SW LOT COR. 50.00 $^{\rm l}$  R/W

PRIOR TO RESURFACING, I SEARCHED AND FOUND NOTHING AT THE SURFACE. I DID DETECT A STRONG METAL SOUND, WHICH SOUNDED LIKE A GI. NEED TO UNCOVER THE GI EITHER PRIOR TO OR AFTER RESURFACING. FD NE, NW REFERENCE PIPES. FD BADLY BENT SW REF. PIPE. NEED TO SEARCH FOR SE REFERENCE PIPE BY OCCUPING THE NE REFERENCE PIPE. RECORD CALLS FOR THE GI AS 4' NORTH OF CENTER OF PVMT. ALSO NEED TO FIND AND REFERENCE WILHELM'S SET REBAR.

SHEET 1 OF 3 CORNER E-15

## UN528 S1/4CORSEC3

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

BATTERMAN EMPLOYEE SEARCHED THEIR RECORDS AND WAS UNABLE TO FIND ANY EVIDENANCE OF THE CUT STONE BEING FOUND. FIELD NOTES INDICATES THE CI WAS PLACED ON LINE WITH THE SE & SW CORNERS OF SEC 3 AND PRORATED WITH RUGER'S DISTANCES.

SW COR TO S 1/4 COR TO SE COR SEC 3
RUGER REMON VAR6-49 2636.04 RUGER REMON VAR6-52 2648.25
197? BATTERMAN 2635.74 BATTERMAN
2647.95

1996 KARNES 2651.08 2635.44 2000 COMBS

SW TO SE SEC 3

RUGER 5284.29 BATTERMAN 5283.69

THE UNION TOWNSHIP PROJECT SHOULD BE USED TO REEVALUATE THIS LOCATION.

D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.

THERE IS A DISCREPANCY. RECORD CALLS FOR 2 DIFFERENT MONUMENTS.

(E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.

I, DONALD BARNES, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Seal

SHEET 2 OF 3

Links Faires 808-2009

CORNER CODE E-15

