

U.S. PUBLIC LAND SURVEY MONUMENT RECORD

For Public Land Survey Corners in:

WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT

T. 2 N., R. 12 E

CORNER CODE INDEX

A	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25
B																									
C	6																								
D																									
E																									
F																									
G	1																								
H																									
J																									
K																									
L	18																								
M																									
N																									
O																									
P	19																								
Q																									
R																									
S																									
T	30																								
U																									
V																									
W																									
X	31																								
Y																									
Z																									

ROCK TWP

ROCK COUNTY WI

IF AVAILABLE
ROCK COUNTY COORDINATES PREFERRED

North _____ Elev. _____

East _____

Hor. Datum _____ Vert. Datum _____

LATITUDE _____ ELLIPS. HT. _____

LONGITUDE _____

GPS (X) _____ TRAVERSE (X) _____

BASED ON THE FOLLOWING CONTROL:

PLACE MONUMENT SYMBOL AT PROPER LOCATION ON ABOVE INDEX

CORNER MONUMENT

WITNESS MONUMENT

(a)

BEARINGS ARE BASED ON:

FIELD BOOK _____ PAGE # _____

SHEET 1 OF 3

SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.

PLANNING & ZONING COMMITTEE ADOPTED THE ABOVE FORM ON 12/2/1982

CORNER CODE E-23(1)

RO532

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

- 1836 LYON EAST RANDOM BETWEEN SECTIONS 1 & 12
1320 ENTERED PRAIRIE BEARS NE & SW
1989.24 INDIAN TRAIL LEADING N & S
5173.08 INTERSECTED RANGE LINE 68.64' NORTH OF POST
FIRST HALF LEVEL & 2ND RATE. LAST HALF HILLY &
2ND RATE. PRAIRIE GROWTH GRASS.
WEST CORRECTED BETWEEN SECTIONS 1 & 12
2533.08 SET QUARTER SECTION POST & MADE MOUND OF
EARTH AND SOD 4 FEET SQUARE & 2 1/2 FEET
HIGH.
5173.08 TO SECTION COR.
- 1870 RUGER VOL 2 PG 40 & 3683 FOUND OLD STAKE. SET
LIMESTONE 17X6X4 AND SURROUNDED IT WITH SEVERAL
SMALL LIMESTONES. CORNER IS 1.98' WEST OF N/S BOARD
FENCE-CUT BOARDS TO SHOW THE LINE. 2548.92 TO SE COR
SEC 2 & 2636.7 TO SW COR SEC 2.
- 1870 RUGER VOL 2 PG 41 & #3941 SEC SEC 1 PG 27. 2636.70 VAR
5-15 TO NW COR SEC 12, 2548.92 VAR 5-10 TO NE COR SEC
12, VAR 6-40 TO S 1/4 COR SEC 12,
- 1891 BLEEDORN VOL 2 PG 454 & #3928 FOUND CORNER & SHOWS
2644.84 TO SW COR SEC 1.
- 1920 KERCH #3908 CALLS FOR AN ANGLE OF 91-32 FROM THE E 1/4
COR TO THE N 1/4 COR OF SEC 12 @ THE NE COR.
- 1937 SUNNY #6349 "WILCOX SUB" UNRECORDED CALLS FOR AN
ANGLE OF 91-36-00 @ THE NE COR SEC 12 FROM THE E 1/4
COR TO THE N 1/4 COR SEC 12.
- 1937 SUNNY #6843 CALLS FOR THE COR A DISTANCE OF
1323.0 TO THE N 1/16TH COR OF THE NW 1/4 OF SEC 12
- 1944 SUNNY #3909 FD STONE. CALLS FOR AN ANGLE OF 88-33-00
@ N 1/4 COR SEC 12 FROM THE NE COR TO CENTER OF SEC 12,
2651.6 TO CENTER OF SEC 12, ANGLE OF 91-30 @ CENTER OF
SEC 12 FROM N 1/4 COR SEC 12 TO PT ON E/W 1/4 LINE
- 1956 SUNNY #3927 FD 6X6X30 STONE MON AT THE N 1/4 COR SEC
12 AND THE N 1/16TH COR OF THE NW 1/4 OF SEC 12. SOUTH
329 A PIPE, 2652.4 TO A SET PIPE AT CENTER OF SEC 12.
- 1956 SUNNY 3902 FD 6X6X30 STONE MON. SOUTH 330' TO A PIPE,
1359 SOUTH OF N 1/4 COR SEC 12 TO PIPE, EASTERLY 251.0
TO A PIPE, EASTERLY 331 FROM N 1/4 COR SEC 12 TO A PIPE.
- 1962 THOM #6355 & 6351 FD CUT STONE AT THE N 1/4 COR SEC 12
AND N 1/16TH COR OF THE NW 1/4 OF SEC 12.
WESTERLY 1323.56 TO FD STONE @ 1/16TH COR, 1358.20 TO
E 1/16TH COR OF NW 1/4 OF SEC 12, SOUTHERLY 329.0 & 330.0
TO 2 PIPES. ANGLE 88-32-00 @ N 1/4 COR SEC 12 FROM NE
COR TO CENTER OF SEC 12, ANGLE 91-26-45 @ N 1/4 COR SEC
12 FROM CENTER TO NW COR OF SEC 12, EASTERLY 251.0 TO
PIPE WHICH IS 80.03 WEST OF ANOTHER PIPE, ANGLE 88-31-
30 @ N 1/16TH COR OF NW 1/4 SEC 12 FROM N 1/4 COR SEC 12
TO CENTER OF NW 1/4 OF SEC 12.
- 1970 LEE #3922 CALLS FOR AN ANGLE OF 91-32-30 FROM THE E 1/4
COR TO THE N 1/4 COR SEC 12 AT THE NE COR OF SEC 12.
- 1985 LEUNBURGER #13699 STARTS AT THE COR BUT STATES
NOTHING ABOUT IT
- 1989 COMBS #13699 1322.97 FROM THE NW COR TO THE N 1/16TH
COR OF THE NW 1/4 OF SEC 12.

SHEET 1 OF 3

CORNER CODE E-23(1)

Donald Kanes
Aug 11 2004

RO532

1991 BARNES E-23 IT IS APPARENT FROM THE IMPROVEMENTS THAT THE CORNER WAS EITHER DESTROYED OR BURIED MANY YEARS AGO. DUG AND FOUND FILL. PLACED ALUM. MON. CORNER IS IN ASPHALT PAVEMENT. USED THOM'S SURVEY TO RESTORE THE CORNER. THE LOCATION IS IN HARMONY WITH ALL ANGLES AND DISTANCES IN THE SURVEY.

1991 BARNES REMON. MAP. S88-55-48E 2554.06 TO NE COR SEC 12, S0-24-18E 2652.48 TO CENTER OF SEC 12, N89-02-04W 2656.90 TO NW COR SEC 12, N88-54-15W 1323.53 TO N 1/16TH OF NW 1/4 SEC 12, & N88-59-53W 1323.37 FROM N 1/16TH OF NW 1/4 SEC 12 TO NW COR SEC 12.

1994 LATHROP BK 32 PG 217 "LAFAYETTE PARK FIRST ADD." FD 3" ROUND ALUM. MON. N87-04-48W 1323.55 TO 1/16TH COR. N88-06-35W 1322.97 FROM 1/16TH COR TO PIPE 2 NW COR SEC 12

1997 COMBS CSM VOL 21 PG 4 FD ALUM. 2646.52 TO NW COR SEC 12.

ACCEPTED ALUM. MON

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

YES. CORNER REVIEWED AFTER A SURVEYOR'S CONCERN THAT IS MIGHT BE NOT BE IN THE CORRECT POSITION. ANGLES CHECK VERY WELL AND DISTANCES CHECK FAIRLY WELL.

D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.

THE FOUND REC & MEASURED DISTANCES GIVE AN OVERVIEW AS COMPARED TO DIFFERENCES:

N 1/4 COR TO MON	1944 SUNNY	1962 THOM	1956 SUNNY
250.22 (0.78 SHORT) E/W	251.0		
330.21 (0.82 SHORT) E/W		331.03	
1323.55 (.05 SHORT) E/W	1323.6		
1323.55 (0.17 LONG) E/W		1323.38	
160.53 (0.19 LONG) N/S		160.34	
2652.43 (0.83 LONG) N/S	2651.6		
2652.43 (0.03 LONG) N/S			2652.4

(E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.

NO

I, Donald Barnes, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Donald Barnes

SHEET 2 OF 3

Emboss

Aug 11 2004

CORNER CODE E-23(1)

A.E. 7.08 REQUIREMENT

