

Bench	Back Sight	Instr. 4	Fore Sight	Reg	Inter Sight	Height	Remarks
	19.628						
					16.030	3.598	S.W. cor of float section of East flume of Ford's Mill.
					16.040	3.588	1 st inter East
					16.045	3.583	Average 2 nd
					16.085	3.543	3 rd
					16.130	3.498	S.E. cor.
					16.020	3.608	West side Middle line of float section of East flume Ford's Mill.
					16.030	3.598	1 st inter East
					15.965	3.663	Average 2 nd
					16.000	3.628	3 rd
					16.020	3.608	East Side
					16.040	3.588	N.W. cor of float section of East flume of Ford's Mill
					16.080	3.548	1 st inter East
					16.075	3.553	Average 2 nd
					16.080	3.548	3 rd
					16.160	3.468	N.E. cor.
					3.575		Mean average of bottom of float section of East flume of Ford's Mill. There is a sill 4 by 4 inches at foot of East side of flume to be taken from the above.
16.217	4.334	20.537					cut bench on upper surface of point of stone ice-break East side of chute.
			3.950	16.601			
	5.213	21.814					
15.034			6.780				cut bench on upper surface of North stone abutment to flume of Hodson's Mill.
	2.912	17.946					
6.982			10.964				Bench in North "float section" of flume of Hodson's Mill.
7.036			10.910				" " South " " " " " "
15.034							cut bench on upper surface of North stone abutment to flume of Hodson's Mill.
	4.613	19.647					
7.995			11.652				Bench on North side of float section of flume of Harvey's Mill.
8.991			10.656				" " South " " " " " "
15.034							cut bench on upper surface of North stone abutment to flume of Hodson's Mill.
	3.052	18.086					
			11.615	6.471			
	1.990	8.461					
2.981			5.480				Bench on dump. South of Bower City Mill's

COUNTY SURVEYOR
RECORD 1859-1906