TRAVERSE (X) ___

U.S. PUBLIC LAND SURVEY MONUMENT RECORD

FOR Public Land Survey Corners in:

T. N., R. E

CORNER CODE INDEX

A1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 2021 22232425

ROCK COUNTY WI

IF AVAILABLE

ROCK COUNTY COORDINATES PERFERRED

North East

Hor. Datum Vert. Datum

LATITUDE ELLIPS. HT.

(a) **CORNER MONUMENT**

PLACE MONUMENT

LOCATION ON ABOVE INDEX

O WITNESS MONUMENT

GPS (X) ___

BASED ON THE FOLLOWING CONTROL:

BEARINGS ARE BASED ON:

OBSERVATION Shepts 4014403			,
FIELD BOOKPAGE #	SHEET	OF	
SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND	SURROUNDING		
PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.			
PLANNING & ZONING COMMITTEE ADOPTED THE ABOVE FORM ON 12/2/1982			
	1 -		

NE556

(B)Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

1834 MILLER

PG 28

NORTH BETWEEN 16 & 17

172.92 BUR OAK 14 IN

313.5 CREEK 6.6 S.E.

2640 SET 1/4 SEC POST IN CREEK BOTTOM. TOO WET TO MOUND

5280 SET POST CORNER OF SEC 8,9,15,17
BUR OAK 12 IN S79E 366.96', YELLOW OAK 10 IN N82-30E 288.42'
LAND MARSHY & POOR 2ND RATE, ASPEN WILLOW U.G. (UNDER GROWTH)

1871 COLLINS REMONUMENTATION NOTES

PG 18

NORTH BETWEEN 16 & 21 VARIATION 4-45

313.5 **CREEK**

2638.68 SET 1/4 STONE IN MARSH IN LINE WITH FENCES EAST AND WEST AND ON WEST SIDE OF NORTH AND SOUTH DITCH.

CONTINUED NORTH VARIATION 5-30

5293.86 INTERSECT SECTION LINE 5.94' EAST OF CORNER. SET STONE FOR CORNER OF 8,9,16,17 BY STUMP OF WITNESS TREE. CORRECTED VARIATION 5-22

1989 BARNES VOL 6 PG 401 S0-10-19W 2637.76 TO SW COR SEC 16 & N0-02-55E 2656.68 (N0-04-50E 2646.55 ERRONEOUS) TO THE NW COR SEC 16

1989 BARNES L-9 FOUND BROKEN STONE AND WOOD HUB. THIS IS IN HARMONY WITH THE EAST/WEST CENTER LINE OF SECTION 16 THAT BATTERMAN ESTABLISHED. IT IS ALSO IN HARMONY WITH COLLINS DISTANCE TO THE SOUTHWEST AND NORTHWEST CORNERS OF SECTION 16. PLACED BERNTSEN 72" GPS 3 DIMENSIONAL MONUMENT WITH DRILL HOLE IN TOP. PLACED 2 MAGNETS AT A DEPTH OF 6 INCHES. PLACED YELLOW CARSONITE NEXT TO MONUMENT. REFERENCED SAME. IN WETLANDS.

USED RECORD OBSERVATIONS FROM 1989 SURVEY

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED FOUND PERPETUATED LOCATION

- D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.
- (E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.
- I, Donald Barnes, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

seal

Number of included sheets 1

Jordd Burs emboss 6-29-01

CORNER CODE L-9(1)