Paper weight-110# (minimum)

Black nonfading ink required

U.S.

PUBLIC LAND SURVEY

MONUMENT RECORD	
For Public Land Survey Corners In: T. N. R. ZE. 4th P.M. CORNER CODE INDEX A	B
LOCATION ON ABOVE INDEX CORNER MONUMENT (a)	O WITNESS MONUMENT
BEARINGS ARE BASED ON:	
	*

SHEET OF SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.

PLANNING & ZONING COMMITTEE ADOPTED THIS FORM ON 12/2/1982

CORNER CODE

FU534

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

1833 (SEP 20) MULLETT & BRINK NORTH ON EAST SIDE SEC 12 T4N RIIE

957 ENTER PRAIRIE

1538.46 INDIAN PATH @ NW & SE

2131.8? LEAVE PRAIRIE

2180.64 BURR DAK 10 IN DIAMETER

SET QUARTER SECTION POST BUR DAK 18 S23W 9.9' BUR DAK 10 N4 1/4W 165'

3993.66 BUR DAK 10 IN DIAMETER

5280 SET POST CORNER SECTIONS 1 & 12 BLACK DAK 8 S 1 1/2 W 55.44' BUR OAK B N57W 9.9' LAND ROLLING SECOND RATE FIRST 1/2 SOME PRAIRIE LAST 1/2 TIMBERED WITH WHITE BLACK AND BUR DAK

1871 RUGER VOL 2 PG 63 CORNER LOST, ESTABLISHED IT FROM SECTION CORNERS. SET HARD HEAD STONE 20X9X6 ON TOP OF ANOTHER HARD HEAD STONE SURROUNDED IT WITH 3 HARDHEAD STONES & ON LIMESTONE. VAR 7-27 TO NW & SW CORNERS SEC 7. VAR 5-55 2589.18 CENTER SEC 12.

- 1871 RUGER VOL 2 PG 79 & 1069 FD THAT THE TOP STONE & STONES SURROUND IT IN A FORMER SURVEY HAD BEEN DUG UP. BUT THE BOTTOM STONE HAD NOT BEEN DISTURBED DRIVE STAKE DEEP & PUT LIMESTONE ON TOP OF IT & PUT ON TOP LIMESTONE 21X9X6 SURROUNDED BY 4 HH STONES. SEE SECTION 12 PORTER PAGE 39. VAR 7-18 2686.86 TO CEN SEC 7, VAR 7-18 5344.68 TO E 1/4 COR SEC 7
- 1937 SUNNY VOL 3 PG 359 DUG 8X8X7 DEEP FD. NO MON. ON LINE E/W FENCE LINE ON EAST SIDE OF RD.
- 1965 BATTERMAN VOL 4 PG 223 PK NAIL BY WP&L 2642.90 WP&L TO SW COR SEC 7, 2642.9 BY WP&L TO NW COR SEC 7
- 1966 BATTERMAN VOL 4 PG 256 DUG & FD 6"X5" HH SURROUNDED BY HHS SET 3/4" PIN & REF. SAME. R/R SPIKES - 10.7 TO THE EAST & SOUTH.
- 1981 BARNES VOL 6 PG 211 FD REBAR OF REC. REPLACED WITH ALUM. & REF. 6' WEST OF N/S CENTER STH 184 PVMT..
- 1995 BARNES G-1 & G-25(PORTER TWP) FD MON. AS SHOWN IN DRAWING. FD POLY WITH TOP BROKE OFF. 6' EAST OF THE WEST EDGE OF STH184. 57 NORTH OF CENTER OF STH 59
- 2000 NORTHROP CSM VOL 24 PG 45 STATES NOTHING ABOUT MON. 2643.01 TO NW COR SEC 7 & ANGLE 90-22-23 @ NW COR SEC 7 FROM N $\frac{1}{4}$ COR SEC 7 TO W $\frac{1}{4}$ COR SEC 7

FD POLY WITH TOP BROKE OFF. ALSO FD REFERENCE MONUMENTS.

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED FD MON.

D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above. NONE

I, **Donald Barnes**, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

SHEET 1 OF 1

CORNER CODE 6-/

///03/07 A.E. 7.08 REQUIREMENT

Emboss