Paper weight-110# (minimum)

Black nonfading ink required

U.S.

BEARINGS ARE BASED ON:

## PUBLIC LAND SURVEY MONUMENT RECORD

For Public Land Survey Corners In: T. A. R. 12 E. 4th P.M.	WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT REV 10/23/2004 USMONREC.DWG
CORNER CODE INDEX	FULTON TWP
A 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 3 B C	ROCK COUNTY WI
D E F	D IF AVAILABLE E ROCK COUNTY COORDINATES PERFERRED F
G A G S S	G H North Elev
K B A B A	K East
M O O O O O O O O O O O O O O O O O O O	M Hor. Datum Vert. Datum
	P LATITUDE ELLIPS. HT
R S T 20 29 20 27 20 27	R S LONGITUDE
v	U NAD83(91)NETWORK ADJ. YR
x y y y y y	X GPS (X) TRAVERSE (X) $Y$ BASED ON THE FOLLOWING CONTROL:
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 2 PLACE MONUMENT SYMBOL AT PROPER LOCATION ON ABOVE INDEX	DASED ON THE POLLOWING CONTROL:
♦ CORNER MONUMENT	O WITNESS MONUMENT
!	

FIELD BOOK \_\_\_\_\_ PAGE # \_\_\_\_ OF \_\_\_ OF \_\_\_ SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.

PLANNING & ZONING COMMITTEE ADOPTED THIS FORM ON 12/2/1982

```
FU561^
(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or
any other material evidence you considered, and whether the monument was found or placed.
1833 (SEP 26) MULLETT & BRINK
                                 NORTH ON EAST SIDE OF
              SECTION 24 T4N R11E
     2640
              SET QUARTER SECTION POST BUR DAK 18 S61W
              60.72' BUR DAK 20 N26W 110.22'
     3762
              TRAIL @ NW
     3810.84 BUR OAK 14 IN DIAMETER
     5280
              SET POST CORNER SECTIONS 13 & 24 BUR DAK 12
              N83W 54.12' BLACK OAK 10 S12W 51.48'
              LAND ROLLING SECOND RATE FIRST HALF ON WEST
              SIDE OF LINE PRAIRIE EAST SIDE TIMBERED WITH
              WHITE BLACK AND BUR DAK ELM AND WHITE MAPLE
              LAST 1/2 TIMBERED WITH WHITE AND BLACK & BUR
              DAK.
1833 (SEP 20) MULLETT & BRINK NORTH ON EAST SIDE SEC 13 T4N
              RIIE
     82.5
              DESCEND TO RIVER BOTTOM
     363
              CATFISH CREEK 108.9' @ NE
     1320
              CATFISH CREEK 108.9' @ NW
              CATFISH CREEK 108.9' @ NE
     2112
     2442
              LEAVE RIVER BOTTOM
     2640
              SET QUARTER SECTION POST BUR DAK 20 S48W
              87.78' BUR DAK 10 N36W 125.4'
     4369.86 WHITE DAK 20 IN DIAMETER
     5280
              SET POST CORNER SECTIONS 12 & 13 BLACK DAK 8
              540W 23.1' BLACK DAK 8 N55W 12.54'
1833 (OCT 29 NOV 4) HARRISON EAST ON RAND BET SECS 13 & 24
                   T4N R11E 4TH MER
     144.54
              CATFISH CRK RIGHT BANK SET GUIDE POST CRS S.E.
              LEAVE CAT FISH SET MEANDER GUIDE POST ON LEFT
     290.4
              BANK
     2640
              TEMPY 1/4 SEC COR
     3019.5
              TRAIL NORTH
     3321.78 NORTHERN BEND OF CATFISH SET G.P
     4224
              LEAVE CAT FISH SET G.P. CRS SE
              CAT-FISH CRS NE SET GUIDE P
     4504.5
     4711.08 LEAVE CAT-FISH SET GUIDE P
              INT. E BDY 3.3?(330'?) N OF P LAND ROLLING 2ND
     5313
              RATE WITH RED BURR & WO TIMBER
                   COR. WEST BET SECS 13 & 24
     601.92
              SET M.P. ON RIGHT BANK OF CATFISH RED O 10
              S41E 75.9'
     808.5
              LEAVE CATFISH SET MEAN, P RED D 12 N45W
              405.9'?
     1089
              BEND OF CAT-FISH SET MEAN. P. BURR O 10 NORTH
              264'
     1993.2
              LEAVE CAT-FISH SET MEAN P. RED 0 12 N33E 39.6'?
     2656.5
              QUARTER SEC COR {W.O. 10 S42E 479.82' W.O. 12
              S80W 29.04'
              LEFT BANK OF CAT-FISH SET MEAN P. W.O.
     5022.6
     5168.46 LEAVE CATFISH SET MEAN. P. WO. 15 N82W 77.88'
              BURR 0 20 S3E 77.88'
     5313
              SEC COR.
```

1834 (APR) HARRISON WEST ON RANDOM BET 18 & 19

2467.08 TRAIL N

2640 TEMPY 1/4 SEC COR & ENTER BOTTOM OF CREEK

3729 INT. LEFT BANK OF CATFISH CREEK SET GUIDE P

3861 LEAVE SAME SET GUIDE P & LEAVE BOTTOM

4712.4 TRAIL N.E.

5295.84 INT. WEST BDY 11.88' N OF P LAND & SAME AS BEFORE

PAGE 1 OF 3 CORNER CODE N-1(1)

Wald Banes

## COR EAST BET 18 & 19

- 1419 SET MEAN POST RIGHT BANK OF CATFISH {BURR O 12 544W 143.88' RED O 8 N2OW 126.72'
- 1551 LEAVE SAME SET MEAND P. ON LEFT BANK {BURR O 18 S45E 143.88'
- 2655.84 QUARTER SEC. CORNER (BUR O 8 N9E 66' BURR O 12 572E 126.72'

5295.84 INT. SEC COR.

- 1847 CRAVATH "VILLAGE OF FULTON" BK 10 PG 27 THE SW COR OF SEC 18 IS THE SW COR OF LOT #2 BLOCK 15 AS STRUCK BY ALLANSON VAUGHN THEN COUNTY SURVEYOR.
- 1875 RUGER VOL 2 PG 200 FD REMAINS OF OLD STAKE AT COR.
  ALSO FD STUMP OF NW BT & WHERE STUMP OF SW BT HAD
  BEEN DUG UP. DROVE NEW STAKE IN PLACE OF OLD ON E
  SURROUNDED IT BY 1 HH & 3 LIMESTONES. 2691.48 TO N 1/4
  COR SEC 19, 2640 TO W 1/4 COR SEC 19
- 1944 SUNNY #6184 STATES NOTHING ABOUT TYPE OF MON.
- 1950 WIDOT #655 CTH M STATES NOTHING ABOUT MON.
- 1959 ELY #1271 CALLS FOR BUT STATES NOTHING ABOUT IT.
  WESTERN R/W LINE OF FULTON ST. IS 501.6 EAST OF COR.
- 1960 ELY #1268 STATES NOTHING ABOUT MON.
- 1966 BATTERMAN VOL 4 PG 293 SET 1" PIPE. WEST OF STH 184.
- 1968 LEE #M14337 & M14336 SIZE 2, SEC 18 "VILLAGE OF FULTON" CONSIDERED OBLITEREATED & WAS REST BY PROPORTION MEASUREMENT OF OCCUPATION OF LINES IN THE NW 1/4 OF SEC 18 & BY TESTIMONY THAT THE WEST LINE OF SECTION 19 PASSED THROUGH THE KITCHEN OF A HOUSE 800' SOUTH OF SAID CORNER. N89-09-06E 2666.86 TO FD CONC. MON @ S 1/4 COR SEC 18 & N00-55-40W 2656.77 TO FD 24X12X4 POINTED HH @ W 1/4 COR SEC 18.
- 1968 LEE #1286 WAS CONSIDERED OBLITERATED & WAS RESET BY PROPORTIONATE MEASUREMENT OF OCCUPATION LINES IN THE NW 1/4 OF SEC 18 & BE TESTIMONY THAT THE LINE PASSED THROUGH THE KITCHEN OF A HOUSE 800 FEET SOUTH OF SAID COR. 2666.86 TO S 1/4 COR SEC 18, 2656.77 TO W 1/4 COR SEC 18, ANGLE 90-04-46 @ SW COR SEC 18 FROM W 1/4 18 TO S 1/4 COR SEC 18
- 1971 SCHROEDER #1294 CALLS FOR COR. BUT STATES NOTHING ABOUT IT.
- 1973 LEE #1286 SET CONC. MON N89-25-23E 2665.36 TO S  $\frac{1}{4}$  COR SEC 18, NO-37-28W 2657.35 TO W  $\frac{1}{4}$  COR SEC 18
- 1978 BARNES #1275 SHOWS RECORD DISTANCES.
- 1992 BARNES N-1 POLY MON. REF. SAME. N88-31-57E 2666.75 TO S 1/4 COR SEC 18 & N1-32-20W 2656.96 TO W 1/4 COR SEC 18. FD 1 1/2" PIPE 1' NORTH AND DID NOT FIND THE CONCRETE MON. ALSO FD THE REFERENCE POINTS THAT LEE CALLED FOR IN HIS 1968 SURVEY. ACCEPTED OBLITERATED EVIDENCE LOCATION. PERPETUATED THE LOCATION THAT LEE ESTABLISHED IN 1973 FROM RUGER'S CALL LINE IN THE HOUSE.
- 1992 COMBS N-1 STATED THAT HE REMEMBERED PLACING THE CONCRETE MONUMENT WHILE WORKING FOR LEE IN 1973 AND THE LAND OWNER LATER REMOVED IT AND TOSSED IT IN THE RIVER. ALSO THE CORNER WAS ESTABLISHED BY USING RUGER'S CALL FOR LINE IN A WINDOW OF A HOUSE THAT WAS TO THE SOUTH.
- 1993 JOHNS #10195 & 10113 2657.04 TO E  $\frac{1}{4}$  COR SEC 13. ALUM. MON. TOP ON SURFACE. USED STEM & MAGNETIC PART OF MON.
- 2002 CARLSON CSM VOL 25 PG 411 FD POLY. MON.

11/07/07 Dovald Baines PAGE 2 OF 3 CORNER CODE N-1(1)

## USED 1992 FIELD DBSERVATIONS.

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED POLY MON.

- D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.
- (E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.

I, **Donald Barnes**, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Seal

Cure Emboss 11/67/07

SHEET 3 OF 3

A.E. 7.08 REQUIREMENT

CORNER CODE N-1(1)