Paper weight-110# (minimum)

Black nonfading ink required

U.S. PUBLIC LAND SURVEY MONUMENT RECORD

Tuble Land Bulley Collects III.	WI ADMINISTRATIVE CODE A-E 7.00 REQUIREMENT		
T. $\angle N$. R. $1\overline{2}$ E. 4th P.M.	REV 10/23/2004 USMONREC.DWG		
CORNER CODE INDEX	BELOIT TWP		
A 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24	4 25 _A		
	B ROCK COUNTY WI		
	C IF AVAILABLE		
E	E ROCK COUNTY COORDINATES PERFERRED		
	F		
н	- G - н North Elev		
K B A A B	J K East		
M N O O O O O O O O O O O O O O O O O O	M Hor. Datum Vert. Datum		
P O O O O O O O O	O P Q LATITUDE ELLIPS. HT.		
U	$\stackrel{-}{\longrightarrow}$ V NAD83(91) NETWORK ADJ. YR		
x 3	X GPS (X) TRAVERSE (X)		
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24	Z BASED ON THE FOLLOWING CONTROL:		
PLACE MONUMENT SYMBOL AT PROPER LOCATION ON ABOVE INDEX			
(a) CORNER MONUMENT (WITNESS MONUMENT		

BEARINGS ARE BASED ON:________

		/	-7
FIELD BOOK PAGE #	SHEET	OF	_
SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT	AND SURROUN	DING	
PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPT	TH.		
PLANNING & ZONING COMMITTEE ADOPTED THIS EODM ON 12/2/1992			

CORNER CODE E-//(/)

be526 S1/4COR SEC 4

- (B) Describe any record evidence, monument evidence, occupational evidence ,testimonial evidence or any other material evidence you considered ,and whether the monument was found or placed.
- 1834 HARRISON EAST ON RAND. BETWEEN SEC 9 & 16

297 TO SUMMIT OF RIDGE E. SIDE OF DRAUGHT

2640 TEMPY 1/4 SEC. COR.

5259.54 INT. E. BDY 26.4 SOUTH OF POST

WEST COR. WEST

2629.77 QUARTER SEC COR. ON HIGH GROUND SET POST & MOUND

5259.54 SEC COR.

- 1844 TOWN ROAD RECORDS 2765.4 TO N 1/4 COR SEC 4.
- 1851 MCVEAN VOL 1 PG 1 2677.62 TO SW COR SEC 4, 2648.58 TO SE COR SEC 4, 2597.76 TO CENTER 4 (CENTER OF ROAD), & 5435.76 TO N 1/4 COR SEC 4.
- 1974 LEE MAP #209 SET CI MON. NO-17-45E 2653.52 TO CENTER SEC 4 & S89-58-32E 2650.37 TO SE COR SEC 4. 2633.44 TO CENTER OF SECTION 9 & 5277.74 TO S 1/4 COR SEC 9. ANGLE OF 89-43-43 FROM N 1/4 COR SEC 4 TO SE COR SEC 4 & 180-00-00 FROM SE TO SW CORNERS OF SEC 4.
- 1975 BICKEL CSM V5 PG 62 FOUND CI. SO-33-54£ TO CENTER OF SEC 9, N89-41-02£ 300 FROM CENTER TO PROPERTY COR., S89-41-02W 2726.03 FROM CEN TO PIPE IN MON. BOX @ W 1/4 COR SEC 9, & FROM W 1/4 COR SEC 9 TO NW COR SEC 9 IS NORTH.
- 1977 LEE CSM V6 PG 188 FOUND CI. 300.00 & ANGLE 90-14-56 @ PIPE @ CENTER OF SEC 9 FROM N 1/4 COR SEC 9 TO PROPERTY COR., ANGLE 89-45-00 FROM PIPE IN MON BOX @ W 1/4 COR SEC 9 @ PIPE IN CEN OF SEC 9 TO CI @ N 1/4 COR SEC 9.
- 1980 BARNES 2677.2 TO SW COR SEC 4, LEE 1970 2650.37 TO SW COR SEC 4, ANGLE 89-59-10 W 1/4 COR SEC 4 TO S 1/4 COR SEC 4 AT SW COR SEC 4, ANGLE 180-33-25 FROM S S1/4 COR SEC 5 TO 1/4 COR SEC 4 AT THE SW COR SEC 4.
- 1998 BARNES E-11 FOUND C.I. & CARSONITE. 2659.5 (REC 2597.76) TO CENTER OF NORTHERN ROAD. LEE'S 1974 RECORD DISTANCES INDICATES THAT THE CORNER WAS ESTABLISHED ON LINE WITH THE SE AND SW CORNERS OF SECTION 4. SINCE THEN THE RECORD SW CORNER OF SECTION 4 WAS FOUND WHICH DIFFERS GREATLY FROM THE CORNER LEE ESTABLISHED. ANGLE FROM N 1/4 COR SEC 4 TO SE COR SEC 4 IS 89-43-12 (REC 89-43-45) AND FROM SE TO SW CORNERS OF SEC 4 IS 180-50-13 (REC 180-00-00). FOUND C.I. MON. & CARSONITE. DID NOT AGREE WITH BATTERMAN'S 1974 PROCEDURE BUT DID NOT FIND ANY PHYSICAL EVIDENCE TO DISPUTE THE MONUMENT.
- 2007 LEUENBERGER #15803 FD CI.

World Darres 1/02/2009

2007 LEUENBERGER CSM 31-119 CI @ S 1/4 COR SEC 4, NO-19-09E 2654.09 TO CEN OF SEC 4, N89-57-02W 2636.59 FROM CEN SEC 4 TO PIPE IN MON BOX @ W 1/4 COR SEC 4, & S89-57-02E 2633.42 TO POSITION ESTABLISHED FROM TIES @ E 1/4 COR SEC 4.

COMBS REPORTED PROBLEMS WITH THE N/S POSITION OF EXISTING SURVEY MONUMENTS TO THE EAST. HE STATED THE COORDINATE POSITIONS THAT HE DETERMINED FOR THE MONUMENTS AT THE S 1/4 COR SEC 4 AND THE SE COR OF SEC 4 WERE IN HARMONY WITH MY COORDINATES. I MODIFIED THE TIE SHEET TO INCLUDE NEWER PLAT OF SURVEYS.

SHEET 1 OF 2

CORNER CODE E-11(1)

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED FD CI.

- D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.
- (E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.

I, **DONALD BARNES**, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Dende Kaines Just 2 /2009

SHEET 2 OF 2

CORNER CODE E-11(1)

A.E. 7.08 REQUIREMENT