

Paper weight-110# (minimum)

Black nonfading ink required

U.S. PUBLIC LAND SURVEY MONUMENT RECORD

For Public Land Survey Corners In:

WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT

T. 4 N. R. 11 E. 4th P.M.

REV 10/23/2004

USMONREC.DWG

CORNER CODE INDEX

PORTER TWP

ROCK COUNTY WI

IF AVAILABLE

ROCK COUNTY COORDINATES PREFERRED

A	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	A
B																										B
C																										C
D																										D
E																										E
F																										F
G																										G
H																										H
J																										J
K																										K
L																										L
M																										M
N																										N
O																										O
P																										P
Q																										Q
R																										R
S																										S
T																										T
U																										U
V																										V
W																										W
X																										X
Y																										Y
Z																										Z

North _____ Elev. _____

East _____

Hor. Datum _____ Vert. Datum _____

LATITUDE _____ ELLIPS. HT. _____

LONGITUDE _____

NAD83(91) _____ NETWORK ADJ. YR _____

GPS (X) _____ TRAVERSE (X) _____

BASED ON THE FOLLOWING CONTROL:

PLACE MONUMENT SYMBOL AT PROPER LOCATION ON ABOVE INDEX

CORNER MONUMENT

WITNESS MONUMENT

BEARINGS ARE BASED ON: _____

FIELD BOOK _____ PAGE # _____

SHEET 1 OF 3

SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.

PLANNING & ZONING COMMITTEE ADOPTED THIS FORM ON 12/2/1982

CORNER CODE N-19(z)

PO570

N1/4CORSEC23

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

- 1833 HARRISON (NOV 3RD) T4N R11E 4TH MER. EAST ON RAND.
BET. 14 & 23
 - 2640.0 TEMPY 1/4 SEC COR
 - 4620.0 LEFT PRAIRIE & ENTER TIMBER
 - 5324.88 INT. E BDY 7.92' SOUTH OF POST LAND 1ST
RATE ROLLING PRAIRIE GROWTH GRASS &
WEEDS
 - WEST COR WEST
 - 2662.44 QUARTER SEC COR {SET A POST AND
RAISED A MOUND
 - 5324.88 SEC COR
- 1885 RUGER VOL 2 PG 293 DROVE STAKE & SURROUNDED IT BY
4 HH STONES. 5448.96 FROM NE TO NW CORNERS OF SEC
23, DROVE STAKE & PUT LARGE HH STONE ON N & S SIDES
@ N 1/16TH COR OF NE 1/4 SEC 23, USED TO SUBDIVIDE
SEC 23
- 1975 BARNES VOL 5 PG 255 THE N 1/4 COR SEC 23 WAS SET
MIDWAY ON A LINE BETWEEN THE NE & THE NW COR. THIS
AGREED WITH THE PROJECTION OF THE CENTER AND THE S
1/4 COR OF SEC 23. THE CENTER OF SEC 23 WAS SET BY
PROJECTING THE S 1/16TH COR OF THE NE 1/4 AND THE E
1/4 AT THAT DISTANCE. THIS IS ALSO THE INTERSECTION
OF THE E/W AND N/S 1/4 LINES.
- 1977 BARNES VOL 5 PG 256 BARNES VOL 5 PG 255 I
TRAVERSED SEC 23. RESULTS INDICATE RUGER DIVIDED
THE SECTION BY INTERSECTING THE E/W 1/4 INE AND THE
N/S 1/4 LINE. BATTERMAN JR. AGREED THAT THE SW COR
OF THE NE 1/4 OF THE NE 1/4 AND THE NW COR OF THE NE
1/4 OF THE NE 1/4 WERE ERRONEOUSLY FOUND. THE
HIGHWAY RECORDS, THE S 1/16TH COR OF THE NE 1/4, THE
OCCUPATION LINE, ANT THE CORNER'S LOCATION TO THE N
1/4 COR AND THE NE COR INDICATE THE N 1/6 COR
SHOULD BE SET ON PG VOL 5 PG 254. THE NE COR WAS
SET BY PROJECTING THE E 1/4 COR AND THE FENCE
INTERSECTION AT THE E 1/16 COR OF THE NE 1/4 AT
RECORD DISTANCE. THIS POINT AGREED WITH THE RECORD
DISTANCE TO THE OCCUPATION TO THE NW CORNER. N89-
43-53W 2724.44 TO NW COR SEC 23, S89-43-53E 2724.51
TO NE COR SEC 23, S1-05-21W 2644.18 TO CENTER OF SEC
23, S1-05-21W 5308.69 TO S 1/4 COR SEC 23
- 1977 BARNES VOL 6 PG 398 S00-39-48W 2644.11 TO GEN SEC
23, 5308.73 TO S 1/4 COR SEC 23, N89-52-56E 2724.45
TO NE COR SEC 23, S89-52-56W 2724.45 TO NW COR SEC
23, ANGLE 89-13-07 @ N 1/4 COR SEC 23 FROM GEN 23 TO
NW COR SEC 23
- 1980 YOUNG GSM VOL 10 PG 148 FD ALUM.
- 1991 WOODMAN VOL 6 PG 418 N00-08-25W 2641.51 TO CENTER
OF SEC 14, N00-08-25W 5299.58 TO N 1/4 COR SEC 14.
- 1991 WOODMAN N-19 FD 4" ALUM. MON. TOP BROKE OFF-BASE
INTACT & 18" DEEP. REFERENCED SAME.
- 1991 WOODMAN #11921 FD 4" DIAMETER ALUM. MON. N00-08-
25E ALONG N/S CENTER OF SEC 14
- 1992 SCHROEDER GSM VOL 15 PG 395 STATES NOTHING ABOUT
MON.
- 2001 LATHROP #14107 & #7935 ALUM. N00-08-25W TO ALUM @
N 1/4 COR SEC 14

Donald Burns
10-28-2009

PO570 N1/4CORSEC23

2007 RIESOP GSM VOL 31 PG 12 FD ALUM. BASE. N00-04-26E
2645.70 TO CENTER OF SEC 14, N00-04-26E 5299.42 TO
ALUM @ N 1/4 COR SEC 14

2007 RIESOP N-19(1) FD BROKEN ALUM. 18" UNDER SURFACE,
N00-04-29E 2645.70 TO 3/4 ROD SET AT CENTER OF SEC
14, SET LONG TIES.

I SEARCHED & DID NOT FIND THE ALUM MON BASE. FOUND THE
1977 EASTERLY REFERENCE BUT DID NOT FIND THE WESTERLY
REFERENCE 31.71' PIPE. SEARCHED & DID NOT FIND WOODMAN'S
REFERENCE MONUMENTS. CORN WAS STANDING NEAR RIESOP'
PLACED REFERENCE MONUMENTS SO I WAS UNABLE TO USE THEM.
THE E/W FENCE IS GONE. AREA IS BEING FARMED. PLACED 3/4X3/4
REROD WITH PLASTIC CAP 2.0' DEEP. PLACED 2 MAGNETS ON NE
SIDE OF REROD. PLACED REROD IN HARMONY WITH FOUND RECORD
MONUMENTS.

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found
perpetuated location?

ACCEPTED OBLITERATED EVIDENCE LOCATION.

D) Describe any material discrepancy between the location of the corner as restored or reestablished
and the location of that corner as previously restored or reestablished by distance and direction. Show
the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as
previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4
of the witness monuments shown on the drawing in (a), above.

(E) Was the corner reestablished through lost corner proportionate methods? If so, show the method,
including the directions and distances to other public land survey corners used as evidence or used for
proportioning the corner location.

I, **Donald Barnes**, hereby certify that the corner location as identified by the corner code index
was determined by me under my direction and control and that this U.S. Public Land Survey
Monument Record is correct and complete to the best of my knowledge and belief.

Seal
Donald Barnes

SHEET 2 OF 3

10-28-2009

CORNER CODE

N-19(2)

A.E. 7.08 REQUIREMENT

N 1/4 COR
SEC 23
PORTER TWP
T4N R11E

Paul Barnes
EMBOSSED SEAL
6002-82-01

1977 BARNES S89-43-53E 5448.95
1885 RUGER 2-293 5448.96
2007 RIESOP N89-15-09E 2724.57
2007 RIESOP N89-15-40E 2724.64
1977 BARNES S89-43-53E 2724.44

1/2X24 REROD
1.5 DEEP/
2 MAGNETS ON
NORTH SIDE

1977 1-1/2X24 PIPE
SEARCHED &
FD NOTHING

1/2X24 REROD
1.5' DEEP
NS-02-47E 8.90
NS-02-47E 8.90
NS-02-47E 8.90
NS-02-47E 8.90

FIELD

1977 1-1/2X24 PIPE
FD PIPE 15' DEEP
PLACED MAGNET
DN NE SIDE

N88-52-16E 64.85
REC 65.15
0.48
FD BENT PIPE
REPLACED WITH
1/2X24 REROD
IN FIELD

ROAD

REC 208.00
NO-09-51E 207.84
FD PIPE

NE COR
SEC 23
PG 280
CSM VOL 6

1977 BARNES 1362.24
N89-16-39E 1362.38
1977 BARNES 2724.48
N89-15-26E 2724.44

SEARCHED & DID
NOT FIND ALUM.
SET 3/4X24 REROD/
PLASTIC CAP
20' DEEP
2 MAGNETS ON
NE SIDE

1991 WOODMAN N-19
1991 FD 4" ALUM MON.
TOP BROKE OFF. BASE
INTACT & 18" DEEP
IN PLOWED FIELD.
PLACED 3/4X12" SPIKE

S 1/4 COR
SEC 14

FIELD

1977 BARNES FB#1 PG47
2007 RIESOP N-19(1)
BROKEN ALU.
18" UNDER SURFACE

2007 N89-19-43E 904.80

2007 S89-39-39W 224.50

2007 S89-13-09W 680.30

1977 31.71

1977 29.09

1.29

0.48

0.04

0.04

2007 3/4 RRD
20' EAST OF
18" FENCE POST

2007
3/4" ROD
2' EAST OF
N/S FENCE
18" STUMP

2007 N00-03-48E 293.89

2007 S65-59-25W 745.03

1.0'