

Paper weight-110# (minimum)

Black nonfading ink required

U.S. PUBLIC LAND SURVEY MONUMENT RECORD

For Public Land Survey Corners In:

WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT

T. 4N. R. 11E. 4th P.M.

REV 10/23/2004

USMONREC.DWG

CORNER CODE INDEX

A	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	A
B																										B
C																										C
D																										D
E																										E
F																										F
G																										G
H																										H
J																										J
K																										K
L																										L
M																										M
N																										N
O																										O
P																										P
Q																										Q
R																										R
S																										S
T																										T
U																										U
V																										V
W																										W
X																										X
Y																										Y
Z																										Z

PORTER TWP

ROCK COUNTY WI

IF AVAILABLE
ROCK COUNTY COORDINATES PREFERRED

North _____ Elev. _____

East _____

Hor. Datum _____ Vert. Datum _____

LATITUDE _____ ELLIPS. HT. _____

LONGITUDE _____

NAD83(91) _____ NETWORK ADJ. YR _____

GPS (X) _____ TRAVERSE (X) _____

BASED ON THE FOLLOWING CONTROL:

PLACE MONUMENT SYMBOL AT PROPER LOCATION ON ABOVE INDEX

CORNER MONUMENT

WITNESS MONUMENT

(a)

BEARINGS ARE BASED ON: _____

FIELD BOOK _____ PAGE # _____

SHEET 1 OF 2

SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.

PLANNING & ZONING COMMITTEE ADOPTED THIS FORM ON 12/2/1982

CORNER CODE V-23(1)

PO612

S1/4CORSEC25

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

- 1833 (OCT 29) HARRISON EAST ON RAND BET SECS 25 & 36 T4N R11E
 - 379.5 TRAIL CRS NE
 - 2640 TEMPY 1/4 SEC COR
 - 5332.8 INT E BDY IN E EDGE OF PRAIRIE 26.4' SOUTH OF POST LAND GENTLY ROLLING 1ST RATE PRAIRIE GROWTH GRASS & WEEDS WEST BET SECS 25 & 36
 - 2666.4 QUARTER SEC. COR. {SET A POST AND RAISED A MOUND ON ROLLING GROUND
 - 5332.8 SEC COR
- 1854 PORTER TWP RD REC BK 1 PG 6 SURVEY OF A ROAD IN THE TOWN OF PORTER MADE ON 9TH DAY OF DEC 1854. BEGINNING 8.25' SOUTH OF THE SW COR OF SEC 25, T4NR11E; THENCE EAST PARALLEL TO THE SEC LINE, 1320'; THENCE N88 -1/2E 330' TO THE SEC LINE; THENCE EAST OF THE SOUTH LINE OF SEC 25, 3211.56' TO THE TOWN LINE RD THIS DAY LAID ON AND NEAR THE TOWN LINE BETWEEN THE TOWNS 4NR11 & 12 EAST. COURSES GIVEN ACCORDING TO THE TRUE MERIDIAN VARIATION OF NEEDLE 7-3/4.
- 1977 BARNES VOL 5 PG 267 2680.20 TO SW COR SEC 25, 2680.20 TO SE COR SEC 25
- 1977 BARNES VOL 5 PG 274 DUG & FD NOTHING SET AT SINGLE PROPORTIONATE DISTANCE ON LINE WITH SE AND SW CORNERS OF SEC 25. SET C.I. & REFERENCED SAME. 7' NORTH OF SOUTH PVMT EDGE & ON LINE WITH N/S FENCE ON NORTH SIDE OF RD. 2680.20 TO S 1/4 COR SEC 25 & 5360.40 TO SW COR SEC 35.
- 1977 SCHROEDER CSM VOL 6 PG 248 STATES NOTHING ABOUT MON. WEST ALONG SOUTH SEC LINE, NO-30E ALONG N/S 1/4 LINE. SET PIPE NO-30E 35.0X
- 2002 COMBS CSM VOL 25 PG 414 ALUM. 2679.95 TO PK @ NE COR SEC 36.
- 2007 RIESOP CSM VOL 31 PG 218 ALUM. S89-17-10W 2680.19 TO ALUM @ SW COR SEC 25
- 2007 RIESOP V-23 FD ALUM. MON SOUTH OF PVMT CENTER.

FD ALUM. MON. 0.2' DEEP & 2.2' SOUTH OF PVMT CENTER & THREE OF THE 1977 REFERENCE PIPES AND RIESOP'S REROD. TOP IS STARTING TO DISOLVE.

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED FD ALUM.

(E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.

YES - IN 1977

I, Donald Barnes, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Seal
Donald
Barnes

SHEET 1 OF 2

CORNER CODE V-23(1)

11/c 3/2009

A.E. 7.08 REQUIREMENT

