

U.S. PUBLIC LAND SURVEY MONUMENT RECORD

For Public Land Survey Corners In:

WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT

T. 4 N. R. 12 E. 4th P.M.

REV 10/23/2004

USMONREC.DWG

CORNER CODE INDEX

	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25
A																									
B																									
C	6																								
D																									
E																									
F																									
G	7																								
H																									
J																									
K	18																								
L																									
M																									
N																									
O																									
P	19																								
Q																									
R																									
S																									
T	30																								
U																									
V																									
W																									
X	31																								
Y																									
Z																									
	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25

FULTON TWP
ROCK COUNTY WI

IF AVAILABLE
ROCK COUNTY COORDINATES PREFERRED

North _____ Elev. _____

East _____

Hor. Datum _____ Vert. Datum _____

LATITUDE _____ ELLIPS. HT. _____

LONGITUDE _____

NAD83(91) _____ NETWORK ADJ. YR _____

GPS (X) _____ TRAVERSE (X) _____

BASED ON THE FOLLOWING CONTROL:

PLACE MONUMENT SYMBOL AT PROPER LOCATION ON ABOVE INDEX

CORNER MONUMENT

WITNESS MONUMENT

BEARINGS ARE BASED ON: _____

FIELD BOOK _____ PAGE # _____

SHEET 1 OF 5

SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.

PLANNING & ZONING COMMITTEE ADOPTED THIS FORM ON 12/2/1982

CORNER CODE A-17(4)

FU509 ^

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

- 1833 (SEP 21ST) MULLETT & BRINK EAST ON SOUTH SIDE SECTION 34 T5N R12E
- 1368.18 WHITE OAK 12 IN DIAMETER
2640 SET QUARTER SECTION POST WHITE OAK 14 N52W 25.08' WHITE OAK 16 N71E 21.12'
5280 SET POST CORNER SECTIONS 34 & 35 BUR OAK 14 N41W 26.4' BUR OAK 16 N25E 35.64' LAND ROLLING SECOND RATE TIMBER WHITE BLACK & BUR OAK
- 1833 (SEP 1ST) MULLETT & BRINK EAST ON SOUTH SIDE SECTION 35 T5N R12E
- 1668.48 WHITE OAK 12 IN DIAMETER
2640 SET QUARTER SECTION POST WHITE OAK 18 N72W 38.94' WHITE OAK 24 N68E 48.18'
2772 ENTER MARSH
3514.5 LEAVE MARSH
4097.28 WHITE OAK 14 IN DIAMETER
5280 SET POST CORNER SECTIONS 35 & 36 BUR OAK 14 N74W 41.58' BUR OAK 18 N62E 8.58' LAND ROLLING SECOND RATE WHITE BLACK AND BUR OAK
- 1833 (OCT/NOV) MILLER NORTH BET. SECTIONS 34 & 35 T5N R12E 4TH MER.
- 805.2 B. OAK 12 IN
2416.92 B. OAK 20 IN
2640 SET 1/4 SEC POST B. B. OAK 18" S77E 15.84', B.B. OAK 12" N68W 15.18'
3682.8 W. OAK 20 IN
5190.9 W. OAK 22 IN
5280 SET POST COR SEC 26,27,34,35 B{W.O. 22IN S40E 23.76', W.O. 16 IN N30W 67.32'
- 1834 (MAR/APR) HARRISON NORTH BET SECS 2 & 3
- 1174.80 WD 12 IN DIAM.
2447.28 W.O. 12 IN DIAM.
2640 QUARTER SEC COR. {W.O. 12 N88W 33' W.O. 12 S21E 67.98' W.O. 12 W.O. 12} MARKED
4116.42 W.O. 12 IN DIAM
5032.5 TRAIL & ROAD N.E.
5346 INT. N. BDG. 21.12' E OF POST {BURR O 12 S35W 40.92' BURR O 12 S19E 26.4' LAND ROLLING 2ND RATE TIMBER BURR & WHITE OAK. UNDERG. ? GRASS & WEEDS
- 1885 STEBBINS BK 1 PG 6 TWP RD BEGINNING AT A STAKE ON THE NORTH LINE OF SEC 3 T4NR12E 1365.54' WEST OF THE NE COR OF SAID SEC; THENCE S30W 2640 SET ANGLE POST, THENCE S25W 3478.2 SET ANGLE POST, BURR OAK, N45W 726'; THENCE S70W 2681.58' SET ANGLE POST BURR OAK 8; N50E 4620; THENCE S50-30W 2520.54 SET ANGLE POST W. OAK 20 S37E 86.46' BLACK OAK 24 S61E 103.62'; THENCE S. 2118.6' TO LINE BETWEEN 9 & 16 1320 E OF SW COR OF 9; THENCE WEST ON SEC LINE 11,880' TO THE SW COR OF SEC 7 & THE WHOLE LENGTH OF THE RD IS 25,318.92'. COURSE GIVEN ACCORDING TO THE TRUE MERIDIAN. VARIATION OF NEEDLE 7-30 [GTH F & STH 51]
- 1881 LEE VOL 2 PG 324 & #1001 THE COR FOR ROCK CO. IS 20.46' EAST OF COR FOR DANE CO. AT SE COR SEC 34 FD STUMPS OF BTS FOR DANE CO.
- 1884 RUGER BK 4 PG 26 BENTLEYS ADD. TO EDGERTON. STATES NOTHING ABOUT MON.
- 1884 RUGER VOL 2 PG 389 & 385 & #1000 & #1016 @ NE COR SEC 3 FD REMAINS OF OLD STAKE & STUMPS OF SE BT & WHERE SW BT HAD BEEN. DROVE NEW STAKE & SURROUNDED BY 4 HH STONES. EAST OF SE COR SEC 34. @ SE COR SEC 34 FD

Donald Baues

11/09/07

SHEET 1 OF 5
CORNER CODE A-17(4)

FU509

- STUMP OF NW BT & APPEARANCE OF OLD STAKE. DROVE NEW STAKE & SURROUNDED IT BY 4 H.H. STONES. VAR 6-17 2637.69 FROM SE COR SEC 34 TO E 1/4 COR SEC 34, 2645.94 FROM SE COR SEC 34 TO S 1/4 COR SEC 34.
- 1886 DOUGLAS VOL 6 PG 348 DANE COUNTY SURVEYOR STAKE AT SE COR SEC 34, 2640 FROM SE TO E 1/4 COR SEC 34, 2649.24 FROM SE COR SEC 34 TO S 1/4 COR SEC 34.
- 1911 HINTZE ALBION T5N R12E SET CORNER BETWEEN SEC 34 & 35, 21.1' WEST OF ROCK COUNTY CORNER. NB9-15E 2685.6 TO S 1/4 COR SEC 35, S89-29W 2648.6 TO S 1/4 COR SEC 34, & NO-32W 2642.8' TO W 1/4 COR SEC 35. SE COR HOUSE N52-45W 103.2', SOFT MAPLE 14" EAST 44.6, I.S. AT NW COR SEC 2. AT DANE COUNTY CORNERS, HINTZE INSTALLED CONCRETE MONUMENTS. THE DIFFERENCE IN BEARING OF LINES BETWEEN SECTION CORNERS GIVES THE TRUE DEVIATION FROM THE STRAIGHT LINE. SOME OF THE BEARINGS ARE MAGNETIC, CHECKED BY MEASUREMENTS, AND THE REST ARE TRANSIT LINES CHECKED BY OBSERVATIONS ON POLARIS. I HEREBY CERTIFY THAT THE DISTANCES AND BEARINGS ARE CORRECT ACCORDING TO SURVEY MADE UNDER THE PROVISIONS OF CHAPTER, 39 SECTION 825 OF THE REVISED STATUTES OF WISCONSIN AND IN ACCORDANCE WITH THE RULES ESTABLISHED BY THE UNITED STATES LAND OFFICE.
- 1951 DAHLAN #13897 FOUND I.S. 103.7 FROM SE COR OF HOUSE TO THE NW; FENCE IS 6' NORTH OF I.S. & ON LINE WITH N/S FENCE TO THE NORTH; THE N/S FENCE IS ALSO 17.5' WEST OF ANOTHER N/S FENCE; THE I.S. IS ALSO 21.1' WEST OF A N/S FENCE TO THE SOUTH;
- 1951 DAHLAN A-17 DAHLEN SHOWS AT THE SW COR. SEC 35 AN IRON STAKE ON LINE WITH THE N/S FENCE LINE AND 103.7' TO THE SE COR OF THE HOUSE.
- 1964 ? #1007 & 1008 DANE COUNTY TIE SHEET. @ SE COR SEC 34 1" I.S. 21.1 WEST OF NE COR SEC 3. STATES NOTHING ABOUT NE COR SEC 3
- 1965 WEIR #13896 FOUND IRON STAKE 0.65' SOUTH FENCE POST
- 1968 CPJ SUB #2113 DL 47 STATES NOTHING ABOUT MON.
- 1978 SANDSNES VOL 5 PG 447 PROVIDED FOLLOWING COORDINATES: 310,339.01; 2,254,004.69
- 1979 NORTHROP #13894 AT SE COR SEC 34 FD ALUM MON. OF REC
- 1978 SANDSNES #994 & 1013 EDGERTON PHOTO CONTROL
- 1984 BARNES VOL 6 PG 326 310,345.34; 2,254,009.46, 310,345.06; 2,253,988.33 AT SE COR SEC 34, NB9-17-51E 2647.87 TO N 1/4 COR SEC 2, S88-52-35W 2586.35 TO N 1/4 COR SEC 3, S1-42-32E 2727.06 TO E 1/4 COR SEC 3, NB9-05E 21.12 FROM SE COR SEC 34 TO NE COR SEC 3. SE COR SEC 34 TO CONC. MON @ E 1/4 COR SEC 34 N1-05-02W 2641.49 (REC 1912 HINTZE 2642.8, 1884 RUGER 2637.69)
- 1985 BARNES VOL 6 PG 342 & A17 FD CONCRET MON @ SW COR SEC 35, NB9-57-04E 2648.09 FROM NW COR SEC 2 TO N 1/4 COR SEC 2, S89-57-01W 21.1X TO SW COR SEC 35, NB9-56-01E 2648.09 FROM N 1/4 COR SEC 2 TO NE COR SEC 2., NB9-57-01E 2630.89 (REC 1912 HINTZE NB9-15E 2685.6) FROM SW COR SEC 35 TO S 1/4 COR SEC 35.
- 1985 BARNES A-17 N/S 310,345.34; 2,254,009.44 E/W FOR NE COR SEC 3, 310,345.08N/S; 2,253,988.34 FOR SW COR SEC 35, @ SW SEC 35 FD 18" ALUM. MON ON TOP OF CONCRETE MON., "@ NW COR SEC 2 SET POLY. MON., FD 3/4" PIPE S40-29-32W 8.55 OF SW COR SEC 35, FD BENT 3/4 PIPE S37-59W 7.98' OF NW COR SEC 2, REF SAME. POLY MON IS NORTH OF E/W FENCE. I DID NOT ACCEPT THE IRON PIPE BECAUSE THERE WAS NO DOCUMENTATION THAT SUPPORTED WHO OR HOW IT

Ronald Barnes
11/10/07

SHEET 2 OF 5
CORNER CODE A-17(4)

FU509

WAS ESTABLISHED. IN 1912 HINTZE STATED HE FOUND A DRAG TOOTH AT THE NW COR. OF SEC 2 & SET THE SW COR OF SEC 35 AT 21.1' WEST OF THE NW COR. HINTZE USED CONC. MON. FOR THE MONUMENTATION OF T5N R12E. THE FENCE LINES AS SHOWN WERE DRASTICALLY ALTERED AS A RESULT OF LITIGATION. MR CHESTER KRUCKERNBER STATED THIS WAS AGREED TO IN THE DANE COUNTY JUDGE'S CHAMBERS

1987 RADL A-17(1) FD ALUM @ NE COR SEC 3 & @ SE COR SEC 34 BROKEN OFF CONC. MON. 1.6' DOWN. SHOWS TIES. I FOUND THE ROCK COUNTY ALUM. MON. 21.10 EAST OF SE COR OF SEC 34. 310,345.44930 N/S; 254009.86474 E/W SOUTH ZONE

1987 RADL CSM VOL 13 PG 148 ALUM @ NE COR SEC 3 310,345.449; 254,009.86 STATE PLANE, 2727.32 TO E ¼ COR SEC 3

1988 WEIR CSM VOL 13 PG 309 SAME AS CSM VOL 13 PG 148

1996 COMBS CSM VOL 19 PG 152 S ¼ COR SEC 31 CONC. MON. NE COR SEC 3 ALUM. 2670.23 FROM S ¼ COR SEC 34 TO NE COR SEC 3.

1997 NORTHROP #8449

1997 NORTHROP #6682 POLY. MON. 21.05 N88-53-55E OF CONC MON AT SE COR SEC 34, 2727.72 TO E ¼ COR SEC 3, ANGLE OF 91-52-00 @ NE COR SEC 3 FROM E ¼ COR SEC 3 TO S ¼ COR SEC 34. FD CONC. MON TOP BROKEN OFF & 19" DEEP AT SE COR SEC 34

1997 WOLLEN 6-450 SE COR SEC 34 310,210.56'; 2,254,302.94' N89-10-56E 2661.98 FROM POINT 4101.

1998 NORTHROP A-17(2) ALUM. CAP POLY AT SEC COR S01-42-50E 2727.72 TO E ¼ COR SEC 3, S89-10-15W 21.12 TO SE COR SEC 34, @ SE COR SEC 34 CONC. MON. TOP BROKEN OFF, MON IS 20" DEEP 30345.03N/S; 2,253,988.32, N01-05-03W 2641.55 FROM SE TO E ¼ COR SEC 34, & S88-53-55W 2649.10 TO S ¼ COR SEC 34. REF COR. COORDINATES FOR NE COR SEC 3 310,345.34 N/S; 2,254,009.44 NAD27

1998 NOTBOHM CSM VOL 22 PG 33 ALUM. & CONC. AT S ¼ COR SEC 34. 2670.35 BETWEEN NE COR SEC 3 & S ¼ COR SEC 34.

2000 LATHROP #19785 SUB. FD ALUM. MON.

2001 RIESCP A-15 FD ALUM. MON.

2001 RIESCP A-17(3) FD ALUM. MON. S88-54-06W 21.12 TO ¾ ROD SET OVER CONCR. MON 2' UNDERGROUND @ SE COR SEC 34. CALLS FOR TIES. S88-54-06W 2586.65 TO N ¼ COR SEC 3. I FOUND THE BROKEN BASE OF THE INZ CONC. MON FOR ALBION TWP AND THE POLY MON. FOR THE ROCK COUNTY COR. THIS AREA AS BEEN DISTURBED BY STREET UTILITY CONSTRUCTION.

2001 RIESOP CSM 24 PG 333 ALUM 21.05 EAST OF SE COR SEC 34, CONC AT S ¼ COR SEC 34. 2586.65 FROM N ¼ COR TO NE COR SEC 3.

2004 COMBS "HEMPHILL STREET COMMONS" BK 32 PG 675-676 DOESN'T STATE TYPE OF MONUMENT. S89-54-06W 2586.67 TO N ¼ COR SEC 3

FD POLY MON AT NE COR SEC 3 & CONC. MON @ SE COR SEC 34. TOP OF CONC. MON. IS BROKEN.

Donald Barnes
1/09/09

SHEET 3 OF 5
CORNER CODE A-17(4)

FU509

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED FD MONUMENTS.

D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.

NO

(E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.

NO

I, **Donald Barnes**, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Donald Barnes
Seal

1/09/07
Emboss

SHEET 4 OF 5

CORNER CODE **A-17(4)**
A.E. 7.08 REQUIREMENT

