Paper weight-110# (minimum)

Black nonfading ink required

## U.S. PUBLIC LAND SURVEY MONUMENT RECORD

T. IN. R. JZE. 4th P.M.  CORNER CODE INDEX  A	WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT REV 10/23/2004 USMONREC.DWG  TWP ROCK COUNTY WI  IF AVAILABLE ROCK COUNTY COORDINATES PERFERRED F G H North L Elev. J
K L M N O P Q R S T U V W X Y Z 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 2 PLACE MONUMENT SYMBOL AT PROPER LOCATION ON ABOVE INDEX  CORNER MONUMENT	L M N Hor. Datum Vert. Datum O P LATITUDE ELLIPS. HOW S LONGITUDE V NAD83(91) NETWORK ADJ. YR W X GPS (X) TRAVERSE (X) Y BASED ON THE FOLLOWING CONTROL:
(a)	

FIELD BOOK \_\_\_\_ PAGE # \_\_\_\_ SHEET \_\_\_ OF \_\_\_ SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.
PLANNING & ZONING COMMITTEE ADOPTED THIS FORM ON 12/2/1982

BEARINGS ARE BASED ON:\_\_\_

CORNER CODE <u>G</u> -

## FU537^

(B)Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

1834 APR HARRISON ORIG. SURVEYOR.

NORTH BETWEEN SECS 9 & 10

377.52 RED OAK 12

2640 TO A HICKORY 10 INCHES IN DIAMETER IN WHICH ESTABLISHED QUARTER SEC COR.

3498 TRAIL CRS N.E.

3664.98 RED DAK 8

3994.98 TRAIL NE & ROAD

5016 TRAIL N.E.

5280 COR TO SECS 3, 4, 9,10

- 18?? RUGER VOL 5 VOL 431 HICKORY 10 CORNER.
- 1872 LEE VOL 2 PG 89 HICKORY TREE AT COR VAR 8-25 2669.70 TO SE COR SEC 9 5352.6 VAR 8 TO W 1/4 COR SEC 9
- 1885 TOWNE "LORD'S ADDITION TO THE CITY OF EDGERTON" BK 4 PG 38

  SW CORNER OF LOT 1 BLOCK 2; 140.25' SOUTH OF SOUTH R/W OF SOUTH ST. TREE AT CORNER.
- 1891 BLEEDORN VOL 2 PG 436 & 1092 HICKORY AT COR 2670.36 TO SE COR SEC 9.
- 1907 KERCH VOL 3 PG 40 SET  $\frac{1}{2}$ " IRON ROD 24.75' EAST OF  $\frac{1}{4}$  SEC COR. FD  $\frac{3}{4}$ " BOLT IN TOP OF HICKORY STUMP. PLACED LARGE RED HH ON WEST SIDE.
- 1931 SUNNY VOL 3 PG 197 AT W 1/4 COR SEC 10 FOUND IRON BOLT IN STUMP 2' BELOW SURFACE.
- 1939 SUNNY #1140 TIES CALLS FOR COR BUT STATES NOTHING ABOUT MON
- 1939 SUNNY VOL 3 PG 447 FD 1" BOLT IN HICKORY STUMP. SET 1"X24" IRON PIPE IN CONCR. ROAD FOR CORNER. REFERENCED SAME. SKETCH SHOWS 2.8' WEST OF CENTER OF PVMT. NOTE: RAISED TO TOP PVMT BY WI HWY COM. 1960.
- 1948 ELY DOROW'S ADDITION TO THE CITY OF EDGERTON" BK 14 PG 30 STATES NOTHING ABOUT MON. IN LORD'S ST. SW COR OF LOT 1 IS 52.83' EAST OF W 1/4 COR. ANGLE OF 90-35 @ W 1/4 COR SEC 10 FROM THE NORTH TO THE E/W 1/4 LINE.
- 1956 ELY QUIGLEY'S FIRST ADD" BK 18 PG 18 STATES NOTHING ABOUT MON.
- 1958 SUNNY "COMMUNITY SCHOOL ADDITION" BK 19 PG 10 IN ALBION ST. STATES NOTHING ABOUT. MON.
- 1959 BATTERMAN #1129 1 1/4 CAPPED PIPE
- 1976 WEIR #13576 CALLS FOR COR BUT STATES NOTHING ABOUT MON.
- 1978 SANDSNES VOL 5 PG 447 N/S 302,301.999; E/W 2,249,040.878 ELEV 878.58
- 1978 SANDSNES #1117, #1103, & #1120 GROUND CONTROL FOR CITY OF EDGERTON AIR PHOTO PROJECT.
- 1979 BARNES VOL 6 PG 3 FD BRASS PLUG. REPLACED WITH ALUM. MON.
- 1980 SANDSNES #1126&7159 N89-28-01E TO CEN SEC 10. BEARING IS NAD27
- 1981 SANDSNES #7158&1125 N89-28-01E 2611.24 TO CEN SEC 10, 5228.97 TO E  $^{1/4}$  COR SEC 10, ANGLE 91-01-34 @ CEN SEC 10 FROM S  $^{1/4}$  COR SEC 10 TO W  $^{1/4}$  COR SEC 10
- 1986 WEIR G-13 FOUND AN ALUMINUM MONUMENT REPRESENTING THE EAST ¼ CORNER OF SECTION 9. THE POSITION OF THE MONUMENT FITS THE LOCATION AS SHOWN ON PREVIOUS SURVEY RECORDS. I ACCEPTED THIS LOCATION AND ESTABLISHED FOUR NEW TIES AS SHOWN. 3.5 WEST OF N/S CENTER OF PVMT.
- 1986 WEIR CSM VOL 12 PG 389 ALUM. ANGLE 92-22-21 @ E  $\frac{1}{4}$  COR SEC 9 FROM CEN SEC 9 TO NE COR SEC 9
- 1988 BARNES VOL 6 PG 377 IN VOL 6 PG 3 THE E 1/4 COR SEC 10 SHOULD BE THE W 1/4 COR OF SEC 10.

PAGE 1 OF 2

CORNER CODE G-13(3)

Ruld Faires 1)/05/07 FU537

- 1993 KREBS #9829 FD ALUM. 2664.66 TO PIPE @ SE COR SEC 9, 2666.32 TO PIPE AT CEN SEC 9, ANGLE 89-53-20 @ E  $\frac{1}{4}$  COR SEC 9 FROM SE COR SEC 9 TO CEN SEC 9
- 1995 LATHROP CSM VOL 18 PG 494 FD ALUM. S89-48-15W 2666.42 TO FD PIPE AT CENTER OF SEC 9, NO1-03-45W 1465.58 TO FD PIPE
- 1997 ODD CSM VOL 20 PG 368 FD BERNTSEN MON. 302,301.999; 2,249.040.878, S89-12-55E 2611.23 TO IRON STAKE AT CENTER OF SEC 10. CENTER OF SEC 10 IS 302,326.292; 2,251,651.943
- 1997 COMBS CSM VOL 20 PG 320 ALUM. MON. 2611.49 TO IRON PIN AT ENTER OF SEC 10
- 1997 COMBS "WHISPERING PINES" BK 32 PG 383 FD 3" ROUND ALUM. MON. 2611.49 TO  $3\!\!/4$ " PIPE AT CENTER OF SEC 10
- 1999 BARNES G-13(1) FD ALUM., TIES, & REFERENCED SAME. MON IS 3.5 WEST OF CENTER PVMT.
- 1999 BARNES G-13(2) AFTER ROAD WAS PAVED I FOUND WIDOT DISK IN CONCRETE. ESTABLISHED LOCATION FROM REFERENCE MONUMENTS. DRILLED HOLE NEAR CENTER OF DISK.
- 200,2 COMBS CSM VOL 25 PG 359 ALUM. MON. 2611.49 TO FD IRON PIN AT CENTER OF SEC 10
- 2004 COMBS CSM VOL 28 PG 71 FD DOT DISK. 2664.48 TO IRON PIPE @ SW COR SEC 10
- 2004 COMBS #14904 FD WI DOT DISK 2664.48 TO FD PIPE @ SW COR SEC
- 2005 FAVORITE #??? FD ALUM. MON. S1-06-04 $\overline{\phi}$  2664.62 TO 2" PIPE @ SE COR SEC 9, & S88-47-16W 1333.16 TO 1/16 $^{\text{TH}}$  COR.
- 2005 J. SCHROEDER CSM VOL 29 PG 27 FD ALUM. 2664.48 TO 2" IRON PIPE @ SW COR SEC 10
- 2005 J. SCHROEDER BK32-684 FD ALUM. 2664.48 TO 2" IRON PIPE @ SW COR SEC 10

## FD DOT DISK WITH DRILL HOLE. ALSO FD REFERENCE MOMUMENTS.

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED FOUND PERPETUATED LOCATION.

- D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.
- I, **Donald Barnes**, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

seal emboss SHEET 2 OF 2

CORNER CODE G-13(3)

A-E 7.08 REQUIREMENT

Doll Laines 11/05/07