U.S.

PUBLIC LAND SURVEY MONUMENT RECORD

For Public Land Survey Corners In:

WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT

T. 4N. R. 13E.

CORNER CODE INDEX

6	6	Da .	3	2	
1	8	9	10		2
1,8	^	16	15	, A	13
19	20	₹	2	23	24
3,50	79	200	~~	26	25
3	32	33	30	25	36

11.67	TWP	
ROCK	COUNTY	WI

IF AVAILABLE
ROCK COUNTY COORDINATES PERFERRED

North	Elev.			
East				
Hor. Datum	Vert. Datum			
LATITUDE _	ELLIPS. HT			
LONGITUDE _				
GPS (X)	TRAVERSE (X)			
BASED ON THE	FOLLOWING CONTROL:			

♦ CORNER MONUMENT

○ WITNESS MONUMENT

BEARINGS ARE BASED ON:

(a)

FIELD BOOK _____ PAGE # ____ OF ____ OF ____ SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.
PLANNING & ZONING COMMITTEE ADOPTED THE ABOVE FORM ON 12/2/1982

MI610

- (B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.
- 1871 ? VOL 5 PG 116 COPIED FROM OLD NOTES. VAR 4-24 2653.53 TO SW COR SEC 26 & VAR 4-51 2665.24 TO SEC COR SEC 26
- 1871 RUGER REMON. NOTES. EAST ON NORTH LINE OF NW 1/4 OF SEC 35 ON A VAR 4-30
 - 2653.53 INTERSECTED ¼ LINE 4.62' NORTH OF ¼ COR. FOUND OLD STAKE AT COR. ALSO FOUND STUMP OF BEARING. COR VAR 4-24
 - EAST ON NORTH LINE OF NE 1/4 OF SEC 35 ON A VAR 5-00

 2665.58 INTERSECTED EAST BOUNDARY LINE 6.6' NORTH OF

 COR. FOUND LIMESTONE AT COR AND STUMPS OF

 NE & SW BEARING TREES COR VAR 4-51
- 1873 LEE VOL 2 PG 100 FD MON. 2650.56 TO NW COR SEC 35 19?? KERCH VOL 5 PG 494 SEE K6 PG 53-54 2652.66 TO SW COR SEC 26.
- 1927 ? VOL 3 PG 144 DUG & FD NOTHING
- 1928 BATTERMAN VOL 6 PG 298 ANGLE @ SE COR SEC 26 OF 87-24 FROM S $1/16^{\text{TH}}$ COR OF SE $\frac{1}{4}$ OF SEC 26 TO E $1/16^{\text{TH}}$ COR OF SE $\frac{1}{4}$ SEC 26. 1332.55 TO S $1/16^{\text{TH}}$ COR & 1326.88 TO E $1/16^{\text{TH}}$ COR.
- 1972 NORTHROP 2655.70 TO SE COR SEC 26, 2653.95 TO SW COR SEC 26, 2655.02 TO CENTER OF SEC 26, 5312.14 TO N $^{1}\!\!\!/$ COR SEC 26, FOLLOWING ANGLES:
 - **(a)** 85 FS 87-04-05 S 1/4 COR SEC 26 SW COR SEC 26 **CENTER 26** 92-49-36 5 ¼ COR SEC 26 CENTER 26 **SE SEC 26** 92-52-40 SW COR SEC 26 W 1/4 COR SEC 26 5¼ SEC 26 5 1/4 COR SEC 26 92-56-03 **CENTER 26** W 1/4 SEC 26 87-02-12 W 1/4 COR SEC 26 CENTER 26 SW SEC 26
- 1973 LEE VOL 5 PG 36 SET C.I. & TIES. DOES NOT STATE WHAT HE FOUND OR HOW HE SET MON.
- 1982 BARNES V-19 FD LEE'S NW & NE REF. PIPES, CAST IRON MON. & SET SW & SE REFERENCE MON.
- 1983 WIDOT STH59 R/W PLANS PROJECT #3143-00-21 SHEET 4.5 CAST IRON MON. 283,392.81; 2,288,396.65
- 1983 BARNES REMON. PROJECT 2654.06 TO SW COR SEC 26, 2665.89 TO SE COR SEC 26, 7 ANGLE 179-54-47 @ S 1 4 COR SEC 26 FROM SW TO SE COR SEC 26. FD CI
- 1984 WIDOT V-19(1) CALLS FOR CAST IRON MON AS STA 116 ± 72.37 & SET TIES.
- 1996 BARNES V-19(2) FD PK & WIDOT REF. MON. SET NW REF MON. PK AGREED WITH WIDOT TIES. TIE AGREES WITH DISTANCE TO NW COR. ELEVATION OF PVMT 882.3 AND THE RECORD ELEVATION OF THE CAST IRON IS 881.7. ACCEPTED FD PK FD TIES ON SOUTH SIDE OF RD. THE FOLLOWING ARE FROM THE MOST RECENT MILTWP ADJUSTMENT:

ANGLE	@	85	FS
87-03-35	5 ¼ COR SEC 26	SW COR SEC 26	CENTER 26
92-51-44	5 ¼ COR SEC 26	CENTER 26	SE SEC 26
92-52-59	SW COR SEC 26	W 1/4 COR SEC 26	5¼ SEC 26
92-56-03	CENTER 26	S ¼ COR SEC 26	W 1/4 SEC 26
87-07-23	W 1/4 COR SEC 26	CENTER 26	SW SEC 26
87-23-28	SE COR SEC 26	S 1/4 COR SEC 26	E ¼ SEC 26.

DISTANCES

2654.10 S 1/4 SEC 26 TO SW COR SEC 26

2665.71 S 1/4 SEC 26 TO SE COR SEC 26

2654.93 5 1/4 SEC 26 TO CENTER SEC 26

5312.11 S 1/4 SEC 26 TO N 1/4 COR SEC 26

FD WIDOT REFERENCE MONUMENTS. UNDERGROUND WATER AND SEWER WAS EXTENDED TO THIS AREA. IN FALL OF 2001 FD PK

SHEET 1 OF 3

V-19(3)

Darl Banes 5/06/02

MI610

AND TIES. PK WILL BE DESTROYED WITHIN A FEW MONTHS. IN APRIL OF 2002 FD TIES. SEARCHED FOR CI. BUT DID NOT FIND IT. PLACED ALUM. MON. FROM TIES. CI MONUMENT PROBABLY WAS DESTROYED BY SEWER PROJECT.

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED PERPETUATED LOGATION.

- D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.
- (E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.

I, Donald Barnes, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Daneld Barres Emboss 5/06/02

SHEET 2 OF 3

CORNER CODE V-19(3)

A.E. 7.08 REQUIREMENT

