

Paper weight-110# (minimum)

Black nonfading ink required

# U.S. PUBLIC LAND SURVEY MONUMENT RECORD

For Public Land Survey Corners In:  
T. 1N. R. 14E. 4th P.M.

WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT  
REV 10/23/2004 USMONREC.DWG

### CORNER CODE INDEX

	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25		
A																											A
B																											B
C																											C
D																											D
E																											E
F																											F
G																											G
H																											H
J																											J
K																											K
L																											L
M																											M
N																											N
O																											O
P																											P
Q																											Q
R																											R
S																											S
T																											T
U																											U
V																											V
W																											W
X																											X
Y																											Y
Z																											Z

1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25  
PLACE MONUMENT SYMBOL  AT PROPER  
LOCATION ON ABOVE INDEX

CLINTON TWP  
ROCK COUNTY WI

IF AVAILABLE  
ROCK COUNTY COORDINATES PREFERRED

North \_\_\_\_\_ Elev. \_\_\_\_\_

East \_\_\_\_\_

Hor. Datum \_\_\_\_\_ Vert. Datum \_\_\_\_\_

LATITUDE \_\_\_\_\_ ELLIPS. HT. \_\_\_\_\_

LONGITUDE \_\_\_\_\_

NAD83(91) \_\_\_\_\_ NETWORK ADJ. YR \_\_\_\_\_

GPS (X) \_\_\_\_\_ TRAVERSE (X) \_\_\_\_\_

BASED ON THE FOLLOWING CONTROL:  
\_\_\_\_\_

CORNER MONUMENT

WITNESS MONUMENT

BEARINGS ARE BASED ON: \_\_\_\_\_

FIELD BOOK \_\_\_\_\_ PAGE # \_\_\_\_\_

SHEET 1 OF 2

SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.

PLANNING & ZONING COMMITTEE ADOPTED THIS FORM ON 12/2/1982

CORNER CODE G-7

CL4535 GEN8

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

- 1877 RUGER VOL 2 PG 224 STATES NOTHING ABOUT MON.  
2653.20 TO N 1/4 COR SEC 8, 993.3 TO IRON PIN ON LINE  
TO N 1/4 COR SEC 8, 1294.42 TO CORNER ON LINE WITH N  
1/4 COR SEC 8.
- 1881 LEE VOL 6 PG 72 [SAME INFORMATION AS IN #876] THE  
PLAT OF SURVEY BY R. LEE IN 1881 IS FRAMED IN THE  
CLINTON CITY HALL.
- 1881 LEE VOL 2 PG 320 & VOL 6 PG 72 #00876 & STATES  
NOTHING ABOUT MON. N86-05E 1319.67 TO OAK STAKE ON  
LINE WITH E 1/4 COR SEC 8, N86-05E 2639.34 TO E 1/4  
COR SEC 8.
- 1881 LEE #876 FD RED HH AT CENTER. N5-05W 2641.58 TO FD  
STAKE & STONE BY RUGER @ N 1/4 COR SEC 8 & N86-05E  
2639.34 TO E 1/4 COR SEC 8.
- 1934 SUNNY "ASSESSOR'S PLAT VILLAGE OF CLINTON" #2009  
CALLS FOR CENTER OF SEC 8. MAP SHOWS SOUTH LINE OF  
DL 79 AS THE E/W 1/4 LINE, FROM CENTER EASTERLY  
223.75 TO OL CORNER; THENCE EASTERLY 73.32 TO OL  
CORNER.
- 1939 SUNNY VOL 3 PG 422 & #857 CALLS FOR BUT STATES  
NOTHING ABOUT MON. NORTHERLY 1330.5X ON N/S 1/4 LINE  
TO COR (NORTH LINE OF VILLAGE OF CLINTON). N2-30W  
2661.0X TO N 1/4 COR SEC 8 (FD PIPE MON. IN  
CONC.). #857 CALLS FOR MAGNETIC BEARING AS A  
REFERENCE.
- 1954 BATTERMAN #3656 & 13139 TIES TO SIGNAL BOX. SET PIN  
1/2 WAY BETWEEN S 1/4 COR SEC 8 & CENTER OF SEC 8  
(CROSS IN CONC.) 2654.46 FROM S 1/4 COR TO CENTER OF  
SEC 8.
- 1964 BATTERMAN #873 CALLS FOR CENTER OF SEC 8 BUT STATES  
NOTHING ABOUT MON. N5-05W 1330.32 TO PIPE.
- 1967 LEE #2020 & #6313 SET BRASS PLUG @ CENTER OF SEC 8.  
N0-03-15E 2660.62 TO N 1/4 COR SEC 8 & 2641.64 TO W  
1/4 COR SEC 8.
- 1969 BATTERMAN #00871 CALLS FOR CENTER BUT STATES  
NOTHING ABOUT MON. N5-05W 1330.32 TO PROPERTY COR.  
PIPE 33 TO THE EAST OF THE PROPERTY COR.
- 1969 BATTERMAN VOL 4 PG 414 CALLS FOR BRASS CAP & CALLS  
FOR 4 REFERENCE DISTANCE TO CORNERS OF HOMES.  
STATES MON IS 2.5' EAST OF CENTER OF PVMT.
- 1974 COMBS SUB #02020 ASSESSOR'S PLAT VILLAGE OF  
CLINTON, DL 62, 63&64 CSM 2 PG 190.  
FD BRASS PLUG. S4-32-30E TO FD PIN IN MON BOX @ S 1/4  
COR SEC 8. FROM S 1/4 COR SEC 8 TO PROPERTY COR ON  
SEC LINE IS S87-08-30W 328.0'.
- 1982 BARNES TWP PROJECT FD BRASS PLUG.
- 1988 LEE SUB #11538 ASSESSOR'S PLAT VILLAGE OF CLINTON  
SIZE 1, 1/10 DL 79 FD PK AT CENTER OF SEC 8. (EAST)  
32.92 TO FD PIPE BENT (REPLACED). EASTERLY 297.50 (REC  
297.07) FROM BENT PIPE TO FD PIPE. SOUTHERLY FROM  
BENT PIPE 73.88 (REC 74.25) TO FD PIPE. NORTHERLY  
FROM BENT PIPE 264.20 (REC 264.00) TO FD PIPE.
- 1994 GORDON CSM 18 PG 16 FD ALUM @ S 1/4 COR SEC 8,  
CENTER OF SEC 8, & N 1/4 COR SEC 8. S0-19-07E 2660.70  
TO S 1/4 COR SEC 8, N0-05-58E 2351.93
- 1996 GORDON "COUNTRY WALK" BK 32 PG 341 FD ALUM @ N 1/4  
COR SEC 5, N 1/4 COR SEC 8, & CENTER OF SEC 8. GRID  
BEARINGS REFERENCED TO WIS. SOUTH ZONE. N0-19-07W  
2660.70 TO N 1/4 COR SEC 8. N 1/4 COR SEC 8 TO N 1/4  
COR SEC 5 N00-05-58E 5650.11. COORDNATES OF  
208,470N/S ?? 2,305.787 E/W

*Donald Barnes*

OCT 2 2008

SHEET 1 OF 2  
CORNER CODE G-7

1997 GORDON GSM VOL 20 PG 112 FD ALUM @ CENTER & N 1/4  
COR SEC 8. NO-19-07W 2660.70 TO N 1/4 COR SEC 8.  
2005 LEUENBERGERGER #S14348 CENTER FROM TIES. S88-17-  
15E 240.41 TO PROPERTY COR.; THENCE S88-17-15E  
149.33 TO PROPERTY CORNER. AT FIRST PIPE - FD PIPE  
N2-36-49W 0.29'

I WAS NOTIFIED BY THE PROJECT ENGINEER AFTER THE PAVMENT  
WAS REMOVED AND THE BRASS PLUG WAS DESTROYED. SINCE  
THERE IS AN ISSUE WITH THE 2 MONUMENTS AT THE S 1/4 COR OF  
SEC 8, I DID NOT REPLACE THIS MONUMENT.

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found  
perpetuated location?

NO

D) Describe any material discrepancy between the location of the corner as restored or reestablished  
and the location of that corner as previously restored or reestablished by distance and direction. Show  
the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as  
previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4  
of the witness monuments shown on the drawing in (a), above.

(E) Was the corner reestablished through lost corner proportionate methods? If so, show the method,  
including the directions and distances to other public land survey corners used as evidence or used for  
proportioning the corner location.

NO

I, **Donald Barnes**, hereby certify that the corner location as identified by the corner code index  
was determined by me under my direction and control and that this U.S. Public Land Survey  
Monument Record is correct and complete to the best of my knowledge and belief.

*Donald Barnes*  
Seal  
Emboss

*OCT 2 2008*

SHEET 2 OF 2

CORNER CODE **G-7**  
A.E. 7.08 REQUIREMENT