

U.S. PUBLIC LAND SURVEY MONUMENT RECORD

For Public Land Survey Corners in:

WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT

T. 2 N., R. 11 E

CORNER CODE INDEX

A	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25
B																									
C	6																								
D																									
E																									
F																									
G	7																								
H																									
I																									
J																									
K	18																								
L																									
M																									
N																									
O																									
P	19																								
Q																									
R																									
S																									
T	30																								
U																									
V																									
W																									
X	31																								
Y																									
Z																									

PLYMOUTH TWP
ROCK COUNTY WI

IF AVAILABLE
ROCK COUNTY COORDINATES PREFERRED

North _____ Elev. _____

East _____

Hor. Datum _____ Vert. Datum _____

LATITUDE _____ ELLIPS. HT. _____

LONGITUDE _____

GPS (X) _____ TRAVERSE (X) _____

BASED ON THE FOLLOWING CONTROL:

PLACE MONUMENT SYMBOL  AT PROPER LOCATION ON ABOVE INDEX

 CORNER MONUMENT

 WITNESS MONUMENT

(a)

BEARINGS ARE BASED ON:

N¹/₄ COR
SEC 35
S89-58-02W
IP
IN MON
BOX
2674.27

ALUM W¹/₄ COR
SEC 35

N0-55-19W
2661.21

S89-08-57E
2644.06

IP IN
MON. BOX
N¹/₄ COR
SEC 36

N0-56-16W
2658.51

TIES W¹/₄ COR
SEC 36

OBSERVATION SHEETS
180, 329, 311, 611

FIELD BOOK _____ PAGE # _____

SHEET 1 OF 3

SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.

PLANNING & ZONING COMMITTEE ADOPTED THE ABOVE FORM ON 12/2/1982

CORNER CODE V-21

PL611

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

1833 HARRISON NORTH BETWEEN 35 & 36 VAR B-00E DEC 20TH
462 LEFT TIMBERING ENTER MARSH
990 LEAVE MARSH & ENTER TIMBER
2640 QUARTER SEC COR. BURR OAK 22 N87W 73.26'; BUR
OAK 8 S31E 30.36'; BURR OAK 22 & BURR O 8
MARKED.
3630 LEFT TIMBER & ENTER PRAIRIE
4854.96 LEFT PRAIRIE & ENTER TIMBER
4884 BLACK OAK 12
5214 BLACK OAK 12
COR TO SECS 26,25,35,36 RED OAK 24 N69E
25.08'; WHITE OAK 24 N 10W 38.94'; RED OAK 16
S9W 38.28'; RED OAK 14 S46E 75.9'; LAND
B? 2ND RATE. TIMBER BURR RED & WHITE OAK
DEC 20TH
EAST ON RANDOM BETWEEN SECS 25 & 36 (VAR B-00E)
2640 TEMPY 1/4 P
5273.4 INT. E BDY 62.04' NORTH OF POST. LAND BDB 1ST
RATE, TIMBER RED & W.O. ASPEN CHERRY ELM
WALNUT & ? OF HAZEL WEEDS
COR. WEST
392.04 W.O. 36
918.72 W.O. 18
2636.7 QUARTER SEC COR. WALNUT 15 N72E 6.60'; WALNUT
24 S33W 3.96'
WALNUT 15 WALNUT 24} MARKER
4224 ELM 12
4953.96 W.O. 12
5273.4 SEC COR.
NORTH BETWEEN 25 & 26 (VAR B-00E)
324.72 RED OAK 24 IN DIAM
657.36 ELM 12 IN DIAM
1151.04 ASH 36 IN DIAM
1617 CHERRY 24 IN DIA
2640 QUARTER SEC COR. {BUR OAK 14 S29E 129.36'
ASPEN 6 N66W 63.36'} BUR OAK 0 14 ASPEN 6}
MARKED
4290 LEFT TIMBER ENTER MARSH
5082 LEFT MARSH ENTER TIMBER
5280 COR TO SECS 23,24,25,26 {BUR O 8 S73E 36.96'
BUR O 9 N56E 53.46' BURR O 1 S56W 90.42' W O 36
N19W 164.34' LAND HIGH R?? 1ST RATE TIMBER RED,
W, & BURR O. ASPEN, ELM WALNUT.
EAST ON RAND. BET SECS 26 & 35
2640 TEMPY 1/4 POST
5308.38 INT. E BDY 32.34' S OF P. LAND ROLY 2ND RATE
TIMBER W.O., BURR O., HICK, ASH, ASPIN
COR WEST
2654.19 QUARTER SEC COR {W.O. 24 N74E 158.4' W.O. 16
S85E 187.44' W.O., 24 W.O 16} MARKED
4632.54 SEC COR ORIG GOV PLAT 5308.38
1849 MC VANE TOWN ROAD RECORDS BK 1 PG 26 "" THE WIDTH
OF 49.5' AND SAID COMMISSIONERS HAVE CAUSED A SURVEY
THERE OF TO BE MADE AS FOLLOWS; THE CENTER LINE OF
SAID HWY IS TO COMMENCE AT THE NW COR OF SEC 25;
THENCE RUNNING SOUTH ON THE SOUTH ON THE SECTION (2)6
TO THE SW COR OF SAID SEC 25; THENCE SOUTH ON THE SEC
LINE BETWEEN SEC 35 AND SEC 36 TERMINATING ON THE
SOUTH LINE OF SAID TOWN THE CENTER OF HWY TO BE ON THE
SEC LINE.
1852 McVEAN VOL 1 PG 14 2626.80 TO N 1/4 COR SEC 36
1856 CHURCH VOL 1 PG 62 2662.44 TO N 1/4 COR SEC 35
1865 LOCKE VOL 1 PG 248 2671.02 TO N 1/4 COR SEC 35; VAR 7-
35 2656.10 TO E 1/4 COR SEC 26.

Derald Barnes

SHEET 1 OF 3 CORNER CODE V-21

2/12/03

PL611

1868 LOOKE PG 5 WEST BETWEEN SECS 25 & 36 5-40
2659.14 INTERSECTED 1/4 LINE 10.56' SOUTH OF COR. FOUND
WHERE BTS WERE DUG OUT AND OLD STAKE. COR
20.46' SOUTH OF FENCE ON NORTH SIDE OF
HIGHWAY AND IN LINE WITH FENCE RUNNING NORTH
VAR CORRECTED 5-26
CONTINUED WEST FROM 1/4 COR WITH VAR 5-40
5304.42 INTERSECTED WEST BOUNDARY 48.18' SOUTH OF
COR. FOUND COR AS SET BY SELF (SEE COUNTY
SURVEYORS RECORD SEC 26) AND STUMP OF B.T. IN
SEC 26 VAR CORRECTED 4-38 COR IN CENTER OF
HIGHWAYS AUG 18 1868
PG 6 NORTH BETWEEN SECS 25 & 26 VAR 7-15
2666.07 INTERSECTED 1/4 LINE AT COR. FOUND COR AS SET BY
SELF (SEE COUNTY SURVEYORS RECORD SEC 26) &
BT IN SEC 25. CORNER IN CENTER OF HIGHWAY & IN
LINE WITH FENCE RUNNING WEST
CONTINUED NORTH FROM 1/4 COR WITH VAR 7
5330.49 INTERSECTED NORTH BOUNDARY 16.5' EAST OF COR
VAR CORRECTED 7-21 AUG 18 1868
PG 9 NORTH BETWEEN SEC 35 & 36 VAR 7-10
AUG 19TH 1868
2658.48 INTERSECTED 1/4 LINE AT COR. FOUND B.T. IN
SEC 35 (CUT DOWN BUT NOT REMOVED) AND
REMAINS OF STAKE. COR IN CENTER OF HIGHWAY
AND 1.98' SOUTH OF FENCE RUNNING WEST.
CONTINUED NORTH FROM 1/4 COR WITH VAR 7-15
5318.28 INTERSECTED NORTH BOUNDARY 6.6' WEST OF
COR. VAR CORRECTED 7-07
PG 10 WEST BETWEEN SEC 26 & 35 VAR 6-15 AUG 19 1868
2676.3 INTERSECTED 1/4 LINE AT COR. FOUND STUMPS OF BTS
AND STONE ON COR. COR IN CENTER OF HIGHWAY
CONTINUED WEST FROM 1/4 COR WITH VAR 6-12
5349.96 INTERSECTED WEST BOUNDARY 15.84' NORTH OF
COR. FOUND BT IN SEC 27 AND STUMPS OF BTS IN
26 AND 34 AND STONE SET ON COR. BT IN 26 IS
137.94' AND BT IN 27 IS 156.42. COR IN CENTER OF
HIGHWAY VAR CORRECTED 6-33 AUG 19 1868
1873 RUGER VOL 2 PG 115 STONE MON. VAR 6-20 TO W 1/4 COR
SEC 25 & VAR 4-51 2640 TO S 1/4 COR SEC 25.
1874 RUGER VOL 2 PG 127 STONE 2640 TO N 1/4 COR SEC 36
1882 LEE VOL 2 PG 367 MON VAR 6 2656.83 TO W 1/4 COR SEC 25.
1962 THOM MAP #4393 LIMESTONE. 2644.24 TO S 1/4 COR SEC 25.
1962 BATTERMAN VOL 4 PG 148 FD STONE MON. & REF SAME
1965 WIDOT MAP #07512 PROJECT S11-01(1) STATES NOTHING
ABOUT MON. BEARINGS SHOWN ON THIS PLAT ARE THE TRUE
BEARINGS OF EACH TANGENT TO THE NEAREST. WEST TO N 1/4
COR SEC 35 & S89-13E TO N 1/4 COR SEC 36
1966 BATTERMAN VOL 4 PG 260 STATES NOTHING ABOUT MON.
REF COR TO 2 P.P.
1966 BATTERMAN VOL 4 PG 284 LAND MARKS ARE CUT CROSS IN
8" CONG. MON {TIES FOR COR} WEST TO N 1/4 COR SEC 35, S89-
13E TO N 1/4 COR SEC 36.
1975 COMBS OSM VOL 4 PG 269 & 309 PIPE IN MON. BOX
1995 KREBS OSM VOL 18 PG 295 MONUMENT BOX
1998 HOULE MAP #08073 MONUMENT BOX
1999 LATHROP MAP #07258 PIPE IN MONUMENT BOX 2674.29 TO S 1/4
COR SEC 26

Ronald Barnes

2/12/03

FD 1" PIPE IN MON. BOX @ CENTER OF PVMT. INT.

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED 1" PIPE IN MON. BOX, WHICH PERPETUATES THE CUT L.S.

D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.

(E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.

I, Donald Barnes, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Seal

Donald
Barnes
Emboss

2-12-03

SHEET 3 OF 3

CORNER CODE V-21

A-E 7.08 REQUIREMENT