

U.S. PUBLIC LAND SURVEY MONUMENT RECORD

For Public Land Survey Corners in:

WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT

T. 4 N., R. 12 E

CORNER CODE INDEX

A	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25
B																									
C	6						5					4													1
D																									
E																									
F																									
G	7						8																		12
H																									
J																									
K																									
L	18						11					16													13
M																									
N																									
O																									
P	19						20					21													24
Q																									
R																									
S																									
T	30						29					28													25
U																									
V																									
W																									
X	31						32					33													38
Y																									
Z																									

FULTON TWP
ROCK COUNTY WI

IF AVAILABLE
ROCK COUNTY COORDINATES PREFERRED

North 307,904.70 Elev. _____

East 493,116.52

Hor. Datum _____ Vert. Datum _____

LATITUDE _____ ELLIPS. HT. _____

LONGITUDE _____

GPS (X) _____ TRAVERSE (X) _____

BASED ON THE FOLLOWING CONTROL:

PLACE MONUMENT SYMBOL AT PROPER LOCATION ON ABOVE INDEX

CORNER MONUMENT

WITNESS MONUMENT

(a)

BEARINGS ARE BASED ON:

OBSERVATION SHEET

FIELD BOOK _____ PAGE # _____

SHEET 1 OF 2

SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.

PLANNING & ZONING COMMITTEE ADOPTED THE ABOVE FORM ON 12/2/1982

CORNER CODE R-23(1)

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

- 1836 BURNHAM EAST RANDOM BETW SECS 24 & 25
5273.4 INT. RANGE LINE AT STAKE. WEST HALF BROKEN, EAST 1/4 FIRST RATE
BUR OAK OPENING GENTLY ROLLING
WEST MARKED LINE BETWE. 25 & 24
NO STATIONS
2636.7 SET 1/4 SEC POST BUR OAK 16 N52 1/2E 89.1' NO OTHER BEARING
5273.4 TO CORNER
- 1864 LOCKE VOL 1 PG 220 FD STUMPS OF B. TREE & OLD STAKE. SET PIECES OF
R.R. IRON (1 RAIL) 20" LONG. VAR 8-10 2641.32 TO NW COR SEC 25, VAR 8-18
2634.72' TO NE COR SEC 25, & VAR 7-15 2647.26 TO CENTER OF SEC 25, VAR 7-30
2647.26 FROM CENTER TO S 1/4 COR SEC 25.
- 1877 BROWN VOL 2 PG 501 T. RAIL 20" LONG VAR 8-18 TO SE COR SEC 24 & VAR 8-10
TO SW COR SEC 24. PG
- 1938 SUNNY VOL 3 PG 395 FD 4 1/2" RAIL AT COR. 24" LOW. SET 1 X20" PIPE ON TOP.
SET 12, 1940 SET 1 1/2" X24" CAPPED PIPE ON TOP FOR COR. REFERENCED
SAME. 1597 TO CENTER OF INTERSECTION OF SOUTH RAIL & CENTER OF
PVMT. 1319 TO N 1/16TH COR OF NE 1/4 SEC 25 (AT 1/16TH COR HE FD 2X7X18"
SANDSTONE). 322.3 FROM N 1/16TH OF NE 1/4 TO NE COR SEC 25 & 1325.3 FROM S
1/4 COR SEC 24 TO S 1/16TH COR OF SW 1/4 OF SEC 24.
- 1969 BECKER VOL 5 PG 513 INFORMATION FOUND IN COUNTY CLERK'S VAULT.
CORNER REFENCED BY GILBERT BECHER PROJECT ENGINEER ON DEC 8,
1969. PROJECT # S0453(6) ID 3656-1-70,71 1 1/2" CAPPED PIPE (ORIG COR)
DESTROYED. PVMT REMOVED. REFENCED WITH BRASS DISKS IN CONCRETE.
- 1970 BATTERMAN VOL 4 PG 333 1.5 CAPPED PIPE BY SUNNY AT N 1/4 COR SEC 25.
REFERENCED SAME
- 1988 BARNES R-23 CORNER WAS RESTORED THROUGH ACCEPTANCE OF FD
PERPETUATED LOCATION. 1 FD A 1" PIPE 0.5' DEEP & REFERENCE
MONUMENTS REPLACED WITH AN ALUM. MON. 4.1' NORTH OF NORTH EDGE
PVMT. IN HARMONY WITH RECORD DISTANCES TO REFERENCE BRASS DISKS.

FD T-BAR 0.7' NORTH OF NORTH PVMT EDGE TILAT WAS IN HARMONY WITH
REFERENE CONCRETE MONUMENTS. ESTABLISHED COUNTY COORDINATES FROM
WPL PS POINTS. N89-00-34E 2644.10 TO NE COR SEC 25.

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED FOUND PERPETUATED LOCATION.

D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.

(E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.

I, Donald Barnes, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

seal

Donald Barnes

emboss

11/04/99

Number of included sheets 1

CORNER CODE

R-23(1)

A-E 7.08 REQUIREMENT

