Paper weight-110# (minimum)

Black nonfading ink required

## U.S. **SURVEY PUBLIC** LAND MONUMENT RECORD

T. 4. N. R. 2E. 4th P.M.  CORNER CODE INDEX  A 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24  B C	B ROCK COUNTY WI
	D IF AVAILABLE  E ROCK COUNTY COORDINATES PERFERRED  F G H North Elev
	J K East L
N O P O O O O O O O O O O O O O O O O O	Hor. Datum Vert. Datum  O P LATITUDE ELLIPS. HT
T 30 39 38 31 30 32	s LONGITUDE T U V NAD83(91)NETWORK ADJ. YR
W X Y Z 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24	W X GPS (X) TRAVERSE (X)
PLACE MONUMENT SYMBOL  AT PROPER LOCATION ON ABOVE INDEX  CORNER MONUMENT  (a)	

BEARINGS ARE BASED ON:

FIELD BOOK. SHEET PAGE # SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH. PLANNING & ZONING COMMITTEE ADOPTED THIS FORM ON 12/2/1982 CORNER CODE R-25(1

## FU593^

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

1836 BRINK NORTH EAST SIDE SECTION 25

1417.02 BUR OAK 12 IN DIAMETER

2640 SET QUARTER SECTION POST WHITE DAK 16

S6W 77.88' WHITE DAK 18 N54W 14D.58'

5280 SET POST CORNER SECTIONS 24 & 25 BUR

OAK 12 N21W 20.46' BUR OAK 11 533 1/2W

21.12' LAND & SAME

1836 BRINK NORTH EAST SIDE SECTION 24 T4N R12E 4<sup>TH</sup>
MERIDIAN

2341.02 BUR OAK 12 IN DIAMETER

2640 SET QUARTER SECTION POST BUR OAK 20

N86W 28.38' BUR DAK 10 S27W 73.92'

4928.88 BUR DAK 12 IN DIAMETER

5280 SET POST CORNER SECTIONS 13 & 24 BUR

DAK 10 N8W 60.06' BLACK DAK 17 S33W 14.52' LAND ROLLING SECOND RATE BUR WHITE & BLACK DAK RED ROOT ROSIN WEED &

C

1836 (JULY6) BURNHAM WEST RANDOM BETWEEN SEC 19 & 30 T4N R13E

2970 ENTER DRY PRAIRIE

3630 LEAVE SAME

4956.60 INT. RANGE LINE 6.6' SOUTH BUR OAK 12

N6W 8.58' BUR OAK 10 S11E 39.6'? GOOD SECOND RATE BUR OAK OPENINGS & DRY

PRAIRIE

EAST CORRECTED BETW 30 & 19

2316.6 SET 1/4 SEC POST BUR OAK 12 S45E 16.5'

BUR OAK 12 N78E 9.24'

4956.6 TO CORNERS

WEDNESDAY JULY 6 1836

1836 (JULY10) BURNHAM EAST RANDOM BETWN SEC 24 & 25

5273.4 INT. RANGE LINE AT STAKE WEST HALF

BROKEN EAST 1/2 FIRST RATE BUR DAK

OPENINGS GENTLY ROLLING
WEST MARKED LINE BETWN 25 & 24

NO STATIONS

2636.7 SET 1/4 SEC POST BUR OAK 16 N52 1/2E 89.1'

NO OTHER BEARING

5273.4 TO CORNER

1842 STEBBINS TWP RD JV BK 1 PG 9 SURVEY OF A RD LEADING FROM STONES FERRY ON ROCK RIVER TO THE EAST LINE OF THE TOWN OF JANESVILLE, MADE JULY 18 & 29 1842.

BEGINNING AT A POINT ON THE EAST BANK OF ROCK RIVER 379.5' SOUTH OF THE NORTH LINE OF SEC 30 T4N R12E; THENCE N83E 5280; THENCE N65E 445.5'? TO SEC LINE; THENCE EAST 2706'; THENCE S77E 9240' TO A POINT WHICH BEARS SOUTH FROM A BURR OAK TREE 11.88'; THENCE N86-30E 4818'; THENCE S86E 1452'; THENCE N82-30E 2640; THENCE N10-30E 660'; THENCE N33-30E 594' TO A POINT ON THE NORTH LINE OF SEC 25, 1141.8' WEST OF THE QUARTER POST; THENCE EAST 3781.8' TO THE NORTHEAST COR OF SEC 25; AND THE WHOLE LENGTH OF THE ROAD IS 31,617.3'. COURSE GIVEN ACCORDING TO THE TRUE MERIDIAN VARIATION OF NEEDLE 7-30

1864 LOCKE VOL 1 PG 220 & #1341 FD S B TREE & (HOLE) OF N. B. T. AND OLD STAKE DISTANCE TO S. BT 27.72' IN STEAD OF 21.12'. SET 9 O. STAKE IN OLD HOLE WITH LIMESTONE 14X10X3 ON N

Dnd Baines

PAGE 1 OF 3 CORNER CODE R-25(1)

## FU593

- 1871 (AUG22) RUGER MILTON TWP REMON. SOUTH ON WEST LINE OF NW 1/4 OF SEC 30 ON A VAR 6-55 AT
  - 2657.16 INTERSECT 1/4 COR FOUND LIME STONE AT COR ALSO FOUND STUMPS OF SOUTH BARING TREES.

SOUTH ON WEST LINE OF SW 1/4 OF SEC 30 ON A VAR 6-55 AT

- 2655.18 INTERSECTED SOUTH BOUNDARY LINE 0.66' WEST OF COR. COR VAR 6-56
  WEST ON NORTH LINE OF NE 1/4 OF SEC 30 ON A VAR 3-54 AT
- 2653.20 INTERSECTED ¼ LINE 1.32' SOUTH OF ¼ COR. FOUND STAKE SURROUNDED BY STONES AT COR. ALSO FOUND SE BEARING TREE & WHERE STUMP OF N.E. BEARING HAD BEEN DUG UP COR VAR 3-52

WEST ON NORTH LINE OF NW 1/4 OF SEC 30 ON A VAR 3-22 AT

- 2321.88 INTERSECTED WET BOUNDARY LINE 7.92'
  SOUTH OF COR. FOUND STAKE AND STONE AT
  COR. ALSO FOUND S.W. BEARING TREE &
  WHERE STUMPS OF OTHER BEARING TREES
  HAD BEEN DUG UP. COR VAR 3-12
  NORTH ON WEST LINE OF SW 1/4 OF SEC 19 ON
  A VAR 6-05 AT
- 2670.36 INTERSECTED 1/4 LINE 3.3' WEST OF 1/4 COR.
  FOUND STAKE AT COR. ALSO FOUND STUMPS
  OF BEARING TREES COR VAR 6-01
  NORTH ON WEST LINE OF N.W. 1/4 OF SEC 19
  ON A VAR 6-00 AT
- 2675.64 INTERSECTED NORTH BOUNDARY LINE 4.62' EAST OF COR. FOUND OLD STAKE AT COR. ALSO FOUND STUMPS OF BEARING TREES. COR VAR 6-06

PLACED 6"X6" CUT LIMESTONE

- 1938 SUNNY VOL 3 PG 394 FD STONE MON 23" DEEP. 9-12-1940 SET A  $1\!\!/\!_2$ X18" CAPPED PIPE ON TOP FOR COR. REFERENCED SAME. 2322.1 TO N  $1\!\!/\!_4$  COR SEC 30
- 1961 BATTERMAN VOL 4 PG 84 SET SPIKE AT NW COR SEC 30 ACCORDING TO OLD REF TIES. REFERENCED SAME. 69.2 TO SE COR OF OAKDALE SCHOOL. NOTE: REF IN VOL 4 PG 413 2323.82 TO N 1/4 COR SEC 30
- 1969 BATTERMAN VOL 4 PG 413 REFERENCED SAME. 65.63 TO SE PIPE @ SE COR HOUSE.
- 1969 BECKER VOL 5 PG 515 THESE CORNER TIES WERE FD IN COUNTY CLERK'S VAULT. WORK DONE BY GIBERT BECKER, PROJECT EN. ON DEC 8 1969 PROJ #S0456-1-70,71. REFERENCE MON. ARE BRASS DISKS IN CONCR.
- 1969 DOT CTH M #11193 & 11194 STATES NOTHING ABOUT MON. 2.0' SOUTH OF TAN.
- 1976 COMBS CSM VOL 6 PG 15 MON. BOX
- 1983 BARNES MILTON TWP #6794 PROJECT S87-16-29E 2323.65
  TO N 1/4 COR SEC 3D, SD-11-44W 2658.16 TO W 1/4 COR SEC
  3D & ND-35-41E 2672.06 TO W 1/4 COR SEC 19, S87-16-29E
  2323.65 TO S 1/4 COR SEC 19 MILTON TWP
- 1998 COMBS CSM VOL 21 PG 283 FD ALUM. 2671.93 TO E  $\frac{1}{4}$  COR SEC 24

PAGE 2 OF 3 CORNER CODE R-25(1)

Corol/Baras 11/14/07 FU593

1999 BARNES R-25 FD PK AND S89-22-15E D.15 A PIPE IN MON. BDX D.6' DEEP. ALSO FD 2 DOT BRASS DISKS IN CONC & RECORD REFERENCE PIPE. S89-00-34W 2644.12 TO N 1/4 COR SEC 25. ESTABLISHED COUNTY COORDINATES FROM WPL GPS STATIONS. ACCEPTED FD PIPE THAT IS IN HARMONY WITH THE REFERENCE BRASS DISKS. THE DIFFERENCE OF 2.02' TO THE SW REFERENCE PIPE MAY BE A DRAFTING BLUNDER. 307,950.60; 495,760.24E/W

FD PK & REFERENCE MONUMENTS. HOUSE ON THE NW CORNER OF THE RD INTERSECTION IS GONE. IT IS BEING FARMED.

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED FD PERPETUATED LOCATION

- D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.
- (E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.

I, **Donald Barnes**, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

SHEET 3 OF 3

CORNER CODE R-25(1)

Dendo Diboss Fames CORNER C 11/14/07 A.E. 7.08 REQUIREMENT