

U.S. PUBLIC LAND SURVEY MONUMENT RECORD

For Public Land Survey Corners In:
T. 4 N. R. 12 E. 4th P.M.
CORNER CODE INDEX

WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT
REV 10/23/2004 USMONREC.DWG

A	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	A	
B																										B	
C	6						5								3											1	
D																											D
E																											E
F																											F
G	7						8								10											12	G
H																											H
J																											J
K	18						17								15											13	K
L																											L
M																											M
N																											N
O																											O
P	19						20								22											24	P
Q																											Q
R																											R
S																											S
T	30						29								27											25	T
U																											U
V																											V
W																											W
X	31						32								34											36	X
Y																											Y
Z																											Z

FULTON TWP

ROCK COUNTY WI

IF AVAILABLE
ROCK COUNTY COORDINATES PREFERRED

North _____ Elev. _____

East _____

Hor. Datum _____ Vert. Datum _____

LATITUDE _____ ELLIPS. HT. _____

LONGITUDE _____

NAD83(91) _____ NETWORK ADJ. YR _____

GPS (X) _____ TRAVERSE (X) _____

BASED ON THE FOLLOWING CONTROL:

PLACE MONUMENT SYMBOL AT PROPER LOCATION ON ABOVE INDEX

CORNER MONUMENT

WITNESS MONUMENT

BEARINGS ARE BASED ON: _____

FIELD BOOK _____ PAGE # _____

SHEET 1 OF 3

SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.

PLANNING & ZONING COMMITTEE ADOPTED THIS FORM ON 12/2/1982

CORNER CODE A-23(1)

FU512^

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

1833 (SEP21ST) MULLETT& BRINK EAST ON SOUTH SIDE SECTION 36

T5N R12E

487.08 WHITE OAK 36 IN DIAMETER
2640 SET QUARTER SECTION POST BUR OAK 10 N42E
12.54' BUR OAK 12 N45W 28.38'
4884 TRAIL @ SE
5016 ENTER WILLOW SWAMP
5280 SET POST CORNER TOWNSHIPS 4 & 5N RANGES 12
& 13 E BEARINGS {WILLOW 8 S26E 7.92' BLACK ASH
8 N60W 16.5' MARKED{ WILLOW 8 S72W SWAMP
OAK 12 N57E

1872 LONG VOL 6 PG 347 DANE COUNTY DEPUTY SURVEYOR
COURSES AT THE SOUTH QRT CORNER AND RUN TO NORTH
QRT CORNER TREES GONE BUT THE STUMP OF ONE TREE FD.
SET THE CORNER. 5303.76 FROM S 1/4 TO N 1/4 COR SEC 36.

1880 LEE VOL 2 PG 300 FD COR OF SEC 1 TO BE 2640
RESPECTIVELY FROM NW & NE CORNERS OF SEC 1. A SMALL
BL. O TREE 4" DIA. COMES AT COR OF 1/4 COR SEC 1.
2680.92 TO CEN SEC 1. 06 LKS [3.96' (.04'?)] EAST OF S 1/4
COR SEC 36. @ S 1/4 COR SEC 36 FD STUMPS OF BTS FOR
SEC 36. 2640 FROM S 1/4 COR SEC 36 TO SE COR SEC 36 &
2652.54 TO SW COR SEC 36.

1880 LEE VOL 2 PG 251 FD COR OF SEC 1 TO BE 2640
RESPECTIVELY FROM NW & NE CORNERS OF SEC 1. A SMALL
BL. O TREE 4" DIA. COMES AT COR OF 1/4 COR SEC 1.
2680.92 TO CEN SEC 1. .06 LKS .04' EAST OF S 1/4 COR SEC
36. @ S 1/4 COR SEC 36 FD STUMPS OF BTS FOR SEC 36.
2640 FROM S 1/4 COR SEC 36 TO SE COR SEC 36 & 2652.54
TO SW COR SEC 36. 0.04'

1911 HINTZE ALBION T5N R12E REMON. SOUTH LINE: SET SOUTH
OF SEC 36 ON STRAIGHT LINE AND ONE HALF BETWEEN
CORNERS. 2635.1 TO SW & SE CORNERS SEC 36. S89-35W
FROM SE TO SW CORNERS SEC 36; N 1/4 COR SEC 1 8.3' EAST
OF S 1/4 COR SEC 36 NO TREES AT S 1/4 COR SEC 36
AT DANE COUNTY CORNERS, HINTZE INSTALLED CONCRETE
MONUMENTS. THE DIFFERENCE IN BEARING OF LINES
BETWEEN SECTION CORNERS GIVES THE TRUE DEVIATION
FROM THE STRAIGHT LINE. SOME OF THE BEARINGS ARE
MAGNETIC, CHECKED BY MEASUREMENTS, AND THE REST ARE
TRANSIT LINES CHECKED BY OBSERVATIONS ON POLARIS. I
HEREBY CERTIFY THAT THE DISTANCES AND BEARINGS ARE
CORRECT ACCORDING TO SURVEY MADE UNDER THE
PROVISIONS OF CHAPTER, 39 SECTION 825 OF THE REVISED
STATUTES OF WISCONSIN AND IN ACCORDANCE WITH THE
RULES ESTABLISHED BY THE UNITED STATES LAND OFFICE.

1984 BARNES VOL 6 PG 326 310,432.18; 2,261,936.21 N88-39-
50E 2646.99 TO CUT LS @ NE COR SEC 1, S89-32-21W
2631.48 TO NW COR SEC 1, FD 3 LARGE HH AT N 1/4 COR SEC
1, FD SANDSTONE @ W 1/16TH COR OF NE 1/4 SEC 1
(309,063.2; 2,261,954.9), FD HH & SET POLY @ CEN SEC 1,
N88-39-50E (REC HINTZE N89-35E 2635.1') FROM S 1/4 COR
SEC 36 TO SE COR SEC 36, S89-32-22W 2647.98 (REC
HINTZE S89-35W 2635.1) FROM S 1/4 COR SEC 36 TO SW COR
SEC 36.

1985 BARNES A-23 FD 3/4X18 REROD & 3 LARGE HARD HEADS IN
TIGHT CLUSTER AT ABOUT 18' SOUTH OF THE REROD. THE
DANE COUNTY SURVEYOR, RON RIPP, DID NOT FIND ANY
DOCUMENTATION FOR THE REROD OR STONE. SET POLY.
MON. & CARSONSITE POST. SHOWS EXCAVATION AREA. I
ACCEPTED THE HARD HEAD STONES BECAUSE THEY WERE IN

Donald Barnes
1/09/07

SHEET 1 OF 3
CORNER CODE A-23(1)

FU512

HARMONY WITH LEE'S SURVEY AND THE MONUMENTS TO THE SOUTH AND THE FENCE INTERSECTION TO THE EAST.

310,42.18 N/S 2,261,936.21 E/W

1985 BARNES VOL 6 PG 341 NB9-19-23E 2647.28 TO NE COR SEC 1, NB9-48-27W 2631.68 TO NW COR SEC 1, SO-08-48E 1368.15 TO W 1/16TH COR OF NE 1/4 SEC 1, NB9-19-23E 2647.28 FROM S 1/4 COR SEC 36 TO SE COR SEC 36, NB9-48-27W 2648.18 FROM S 1/4 COR SEC 36 TO SW COR SEC 36.

1996 COMBS CSM VOL 19 PG 138 ALUM. MON 2631.74 TO NW COR SEC 1.

1998 SCHROEDER CSM VOL 21 PG 213 STATES NOTHING ABOUT MON. IT IS THE NW COR OF LOT 1 OF CSM. 586.16' WEST OF THE WEST R/W LINE OF HILLSIDE RD.

2004 LORD "WOODLANDS SUBDIVISION" BK32-673 FD ALUM.

2005 COMBS CSM VOL 29 PG 103 FD POLY MON. 2685.94 TO FD ALUM. @ CENTER OF SEC 1.

2005 LORD BK32-720 FD ALUM NB9-18-07E 2646.92 TO L.S. @ NE COR SEC 1 & ANGLE 89-09-02 @ NE COR SEC 1 FROM E 1/4 COR SEC 1 TO N 1/4 COR SEC 1.

FD ALUM. /CARSONITE & REFERENCE MONUMENTS. SINCE THERE WAS SO MUCH DISCREPANCY BETWEEN HINTZE'S DISTANCES AND THE FIELD DISTANCES, I DUG FOR RECORD CONC. MON. AT S 1/4 COR SEC 36 T5N R12E. I FD NOTHING.

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED FD ALUM.

D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.

HINTZES CALL DISTANCE OF EAST 8.3' TO THE N 1/4 COR SEC 1 IS NOT THE SAME AS LEE'S 1880 DISTANCE OF 0.04' (MAYBE 3.96').

(E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.

I, **Donald Barnes**, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Seal

Emboss
Donald Barnes
1/09/07

SHEET 2 OF 3

CORNER CODE
A.E. 7.08 REQUIREMENT

A-23(1)

