

Paper weight-110# (minimum)

Black nonfading ink required

# U.S. PUBLIC LAND SURVEY MONUMENT RECORD

For Public Land Survey Corners In:

WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT

T. ~~4~~ N. R. 12 E. 4th P.M.

REV 10/23/2004

USMONREC.DWG

### CORNER CODE INDEX

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	
A																									A
B																									B
C	6																								C
D						5																			D
E																									E
F																									F
G	7																								G
H						8																			H
J																									J
K																									K
L	18																								L
M																									M
N																									N
O																									O
P	19																								P
Q																									Q
R																									R
S																									S
T	30																								T
U																									U
V																									V
W																									W
X																									X
Y	31																								Y
Z																									Z

FULTON TWP  
ROCK COUNTY WI

IF AVAILABLE  
ROCK COUNTY COORDINATES PREFERRED

North \_\_\_\_\_ Elev. \_\_\_\_\_

East \_\_\_\_\_

Hor. Datum \_\_\_\_\_ Vert. Datum \_\_\_\_\_

LATITUDE \_\_\_\_\_ ELLIPS. HT. \_\_\_\_\_

LONGITUDE \_\_\_\_\_

NAD83(91) \_\_\_\_\_ NETWORK ADJ. YR \_\_\_\_\_

GPS (X) \_\_\_\_\_ TRAVERSE (X) \_\_\_\_\_

BASED ON THE FOLLOWING CONTROL:

PLACE MONUMENT SYMBOL  AT PROPER LOCATION ON ABOVE INDEX

CORNER MONUMENT

WITNESS MONUMENT

(a)

BEARINGS ARE BASED ON: \_\_\_\_\_

FIELD BOOK \_\_\_\_\_ PAGE # \_\_\_\_\_

SHEET 1 OF 3

SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.

PLANNING & ZONING COMMITTEE ADOPTED THIS FORM ON 12/2/1982

CORNER CODE X-21(2)

FU619^

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

- 1836 (JULY) BURNHAM NORTH BETWEEN SECTIONS 35 & 36  
1531.86 BUR OAK 12 IN DIA  
2640 SET 1/4 SEC POST BUR OAK 14 S88W 18.48' BUR OAK 12  
N75E 41.58'  
NO STATIONS  
5313 SET POST COR TO 25,26,35, & 36 BUR OAK 8 S14W 25.74'  
BUR OAK 12 N54E 42.9' FIRST RATE BUR OAK OPENINGS  
GENTLY ROLLING
- 1846 TWP RD BK 1 PG 8 BEGINNING 89.1' NORTH OF THE 1/4 POST  
BETWEEN SECTION 35 & 36 T4N R12E FROM THENCE NBW 1644.06'  
TO A POST STANDING IN THE CENTER OF THE HIGHWAY LEADING  
NORTHERLY TO GOODRICH'S FERRY. THIS RD IS LAID 66' WIDE BY  
ORDER OF THE COMMISSIONERS OF HIGHWAYS . " " " " THE SECTION  
LINE BEING THE CENTER OF THE SAME. " " " " "
- 1867 LOCKE VOL 1 PG 297 & #1482 FD STUMPS OF W. BT & WHERE E.  
B.T. WAS DUG OUT & OLD STAKE. RESET STAKE. USED TO  
SUBDIVIDE SEC 36.
- 1875 RUGER VOL 2 PG 188 & #6571 FD STAKE & STUMPS OF SW BT &  
WHERE STUMPS OF SE. BT HAD BEEN DUG UP. SET STAKE  
SURROUNDED BY 3 HH. VAR 5-48 2641.76 TO SE COR SEC 35, VAR  
6-46 2657.82 TO CENTER OF SEC 35, 5301.62 TO W 1/4 COR SEC  
35.
- 1875 RUGER VOL 2 PG 190 STAKE SURROUNDED BY 3 HH. SEE BK 2 PG  
143. VAR 5-48 2641.76 TO SE COR SEC 35
- 1939 SUNNY VOL 3 PG 446 SET 2"X4" C.I. ROUND MON. IN THE CONC.  
PVMT. 2663.9 TO FENCE INT. AT CENTER OF SEC 35; 2632.8 TO N/S  
FENCE AT CENTER OF SEC 36, & 2646.2 TO SE COR SEC 35.  
REFERENCED COR WITH TREES.
- 1947 SUNNY #1478 CALLS FOR COR BUT STATES NOTHING ABOUT MON.  
2646.2X TO SW COR SEC 36
- 1977 BARNES VOL 5 PG 374 FD C.I. & REFERENCED SAME.
- 1979 BARNES VOL 6 PG 3 FD BRASS PLUG & UNDER THAT FD IRON PIPE.  
REPLACED WITH ALUM MON.
- 1979 LEE "LOCKWOOD" BK 30 PG 28 PIPE/CAP EASTERLY 82.00 ALONG  
1/4 LINE TO 2" PIPE AT LOT COR. FD STONE AT GEN OF SEC 36 &  
REPLACED IT WITH A 2" PIPE. ANGLE @ E 1/4 COR SEC 35 FROM SE  
1/4 LINE TO CENTER OF SEC IS 89-42-50
- 1980 BARNES VOL 6 PG 17 RECORD DISTANCES.
- 1982 LEUENBERGER 6-365 2647.21 TO SE COR SEC 35, 1330.27 TO N  
1/16<sup>TH</sup> COR OF SE 1/4 OF SEC 35.,
- 1983 COMBS CSM VOL 11 PG 187 CI.
- 1982 COMBS CSM VOL 11 PG 241 C.I.
- 198? COMBS VOL 6 PG 365 2647.21 TO SE COR SEC 35, 1330.27 TO TO  
N 1/16<sup>TH</sup> COR OF SE 1/4 OF SEC 35, & ANGLE 89-24-04 @ E 1/4 COR  
SEC 35 FROM SE COR SEC 35 TO N1/16<sup>TH</sup> COR OF SE 1/4 OF SEC  
35
- 1984 COMBS CSM VOL 11 PG 622 CALLS FOR CI.
- 1985 COMBS "LOCKWOOD FIRST ADD." BK 32 PG 26 C.I.
- 1987 BARNES VOL 6 PG 365 RECORD DISTANCES
- 1990 COMBS #1999 CALLS FOR BUT STATES NOTHING ABOUT MON.
- 1990 COMBS #2264 & # 2054 STATES NOTHING ABOUT MON. WESTERLY  
1330.27 TO 1/16<sup>TH</sup> COR.
- 1990 COMBS #1919 STATES NOTHING ABOUT MON. 2660.54 TO 2" PIPE  
@ GEN. SEC 35. CALLS FOR A BEND @ THE N 1/16<sup>TH</sup> COR OF THE SE  
1/4 OF SEC 35.
- 1991 COMBS CSM VOL 15 PG 351 ALUM. WESTERLY 1330.27 TO 1/16<sup>TH</sup>  
COR
- 1993 COMBS CSM VOL 16 PG 395 PIPE. 2660.54 TO PIPE @ CENTER OF  
SEC 35

SHEET 1 OF 3

*Donald Barnes*

*Aug 20, 2007*

CORNER CODE X-21(2)

FU619

- 1994 COMBS CSM VOL 17 PG 331 C.I. 2914.99 TO SE COR SEC 35, 2660.54 TO CEN. SEC 35, & ANGLE 89-44-35 @ E 1/4 COR SEC 34 FROM SE TO CEN OF SEC 35
- 1999 LEUENBERGER #1475 & 2199 FD G-1 MON 2647.21 TO SE COR SEC 35, 1330.27 TO S 1/16<sup>TH</sup> COR OF NE 1/4 SEC 35, ANGLE 89-24-40 @ E 1/4 COR SEC 35 FROM SE COR SEC 35 TO S 1/16<sup>TH</sup> COR OF NE 1/4 SEC 35
- 1999 BARNES X-21 FD ALUM. MON. & REFERENCE MONUMENTS. MON IS 3.4 WEST OF EAST PVMT EDGE.
- 1999 BARNES X-21(1) AFTER ROAD WAS PAVED, I FOUND WIDOT DISK IN CONCRETE. I PLACED AN ALUM. SPIKE S43-41-23W 0.30' FROM THE CENTER OF THE WIDOT DISK BY RECORD DISTANCES FROM THE REFERENCE MONUMENTS.

FD WIDOT DISK & SURVEY SPIKE.

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED FD SURVEY SPIKE. PERPETUATED LOCATION BY FOUND REFERENCE MONUMENTS.

D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.

SEE SKETCH.

(E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.

I, **Donald Barnes**, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

seal



emboss

Aug 20, 2007

SHEET 2 OF 3

CORNER CODE **X-21(2)**

A-E 7.08 REQUIREMENT

