Paper weight-110# (minimum)

Black nonfading ink required

## U.S. PUBLIC LAND SURVEY MONUMENT RECORD

CORNER CODE INDEX A 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24	BELOIT TWP
B C D D D	B ROCK COUNTY WI C IF AVAILABLE E ROCK COUNTY COORDINATES PERFERRED
F G H J K	F G H North Elev
M N O O O O O O O O O O O O O O O O O O	L L L M N Hor. Datum Vert. Datum
P Q R S T Q Q Q Q Q Q Q Q Q Q Q Q Q Q Q Q Q Q	P LATITUDE ELLIPS. HT R S LONGITUDE
w x x x x x x x x x x x x x x x x x x x	U V NAD83(91)NETWORK ADJ. YR W X GPS (X) TRAVERSE (X)
Z 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 PLACE MONUMENT SYMBOL AT PROPER LOCATION ON ABOVE INDEX	Z BASED ON THE FOLLOWING CONTROL
(a) CORNER MONUMENT	WITNESS MONUMENT

BEARINGS ARE BASED ON:\_\_\_\_

FIELD BOOK PAGE # SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AN	SHEET	$\frac{1}{2}$ of $\frac{3}{2}$
PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.	BURROUN	
PLANNING & ZONING COMMITTEE ADOPTED THIS FORM ON 12/2/1982		
CORNER	CODE	1-5(1)

## BE595 E 1/4SEC30

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

1834 HARRISON NORTH BETWEEN SECS 29 & 30

1261.92

BROOK & CRS S.W.

2640

QUARTER SEC COR.

BURR DAK 12 N31W B1.18' BURR DAK 12 S6BW 29.7' BURR DAK 12" MARKED BURR DAK 12" MARKED

2454.54

BURR OAK 8 & ENTER SEATY? TIMBER

5280

COR TO SEC 19-20-29-30

TIMBER ADJACENT TOO SMALL WHEREON REESTABLISHED COR. I THEREFORE SET POST

& RAISED MOUND.

1963 THOM #???? RHB FILE SET PIPE ON LINE & MIDWAY BETWEEN THE NW & SW CORNERS OF SEC 29.

1975 WPL #6039 CALLS FOR N1-12-50W 5300.95 FROM SE TO NE COR SEC 30 & N89-24-58W 2641.51 FROM SE COR SEC 30 TO S 1/4 COR SEC 30

1983 LEE MAP #14004 CALLS FOR THE CORNER. 2650.95 TO SE COR SEC 30 & AN ANGLE OF 88-10-00 FROM S 1/4 COR SEC 30 TO E 1/4 COR SEC 30 AT THE SE COR SEC 30.

1996 KREBS CSM 20-256 FD PIPE WHICH IS 11 WEST OF THE CENTER OF PVMT. NORTH 2650.45 TO FD PIPE IN MON. BOX @ NW COR SEC 29 & S88-22-57E 1338.78 TO PIPE.

1998 COMBS CSM 21-206. FD PIPE SO-27E 2651.39 TO ALUM @ SW COR SEC 29. FROM SW COR SEC 29 TO FD ALUM @ S 1/4 COR SEC 29 IS 588-10-20E 2648.68.

1998 BARNES T-5 DID NOT FIND A MONUMENT OR OLD RD. EXCAVATION PATCH. POSITION IS ACCORDING TO LEE'S SURVEY. DID NOT ACCEPT NOR REJECT LOCATION. CORNER NEEDS TO BE DUG FOR.

1999 COMBS CSM 23-63 FD PIPE SBB-18-25E 133B.74 TO PIPE & SOUTH 2651.39 TO FD ALUM @ SW COR SEC 29

ON AUG 13, 2009 JIM PREHN CALLED & SAID HE FD A PIPE. THE GPS COORDINATES WERE 209,253.43; 469,666.01 WHICH DID NOT FIT THE COMPUTED POSITION COORDINATES. THE COMPUTED COORDINATES ARE S71-22E 2.0X OF THE PIPE. THE INVERSE DISTANCE FROM HIS GPS COORDINATES TO THE NE & SE CORNERS OF SEC 30 ARE MORE IN HARMONY WITH MORE RECENT DISTANCES.

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

I DID NOT ACCEPT NOR REJECT THE PIPE, WHICH APPEARS TO BE 1.9X WEST OF THE LINE BETWEEN THE SE & NE CORNERS OF SEC 30. THE PIPE IS ALSO 0.7X NORTH OF THE MIDWAY POSITION. THE CORNER NEEDS TO BE EXCAVATED FOR.

CORNER CODE T-5(1)

Devel Bains 8/19/2009

## BE595 E 1/4SEC30

- D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.
- (E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.

IN 1963 RICHARD THOM ESTABLISHED THE CORNER BY THE LOST PROPORTIONATE METHOD.

I, **DONALD BARNES**, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Emboss

SHEET 2 OF 3

CORNER CODE T-5(1)

A.E. 7.08 REQUIREMENT

8/19/2009

