Paper weight-110# (minimum)

Black nonfading ink required

U.S.

PUBLIC LAND SURVEY MONUMENT RECORD

For Public Land Survey Corners In:	WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT
$T. \stackrel{\mathcal{L}}{=} N. R. / \stackrel{\mathcal{L}}{=} E. 4th P.M.$	REV 19/23/2004 USMONREC.DWG
CORNER CODE INDEX	$\rho_{\alpha} \circ + - \rho$
A 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22	PORTER TWP
B C 6 5 10 10 10 10 10 10 10 10 10 10 10 10 10	ROCK COUNTY WI
D	C IF AVAILABLE
E	E ROCK COUNTY COORDINATES PERFERRED
H J	H North Elev.
K S A S	K East
M N N N N N N N N N N N N N N N N N N N	M Hor. Datum Vert. Datum
	Q LATITUDE ELLIPS. HT
S NO NO NO NO NO	S LONGITUDE
V. T.	v NAD83(91)NETWORK ADJ. YR
x of of of of	x GPS (X) TRAVERSE (X)
1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 : PLACE MONUMENT SYMBOL AT PROPER LOCATION ON ABOVE INDEX	T DACED ON THE BOX - COLUMN
(a) CORNER MONUMENT	O WITNESS MONUMENT

BEARINGS ARE BASED ON:

′ of 3 FIELD BOOK PAGE # SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH. PLANNING & ZONING COMMITTEE ADOPTED THIS FORM ON 12/2/1982

```
PD529
           SECORSEC3
```

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

T4N R11E 4TH MER. NORTH HARRISON (OCT 29TH) BET. 10 & 11

> **LEAVE PRAIRIE & ENTER TIMBER** 396.0

2089.56 CAT-FISH CRK CRS S.E. SET MEANDER POST BURR OAK 10 S24W 30.36'; WHITE OAK 24 89E 97.68'

2367.42 LEAVE CAT-FISH SET MEANDER POST RED DAK 12 886E 52.80'

2640.0 QUARTER SEC COR. RED OAK 10 N71E 19.14'; WHITE OAK 10 N75W 27.06'

3828.0 CAT-FISH CRS S.W. SET MEANDER POST

4191.0 LEAVE CAT-FISH SET MEANDER POST

4806.78 A WESTERN BEND OF CAT-FISH SET MEANDER POST

4950.0 LEFT SAME SET MEANDER POST

5280.00 INT. CAT-FISH SET COR TO SECS 2,3,10,11 & MEANDER POST BURR OAK 18 N61W 285.12'; RED OAK 12 S40W 415.80' LAND ROLLING 2^{ND} RATE AS BEFORE

HARRISON (OCT 31st) T4N R11E 4TH MER. EAST BET. SECS. 2 & 11

> 274.56 LEAVE CAT-FISH SET MEANDER POST

2640.00 TEMPY 1/4 POST

3828.0 ENTER PRAIRIE

4264.92 TRAIL CRS N.W.

5207.40 TRAIL NW

5339.40 INT. E BDY 19.8' SOUTH OF POST LAND 1 ST 1/2 MILE SAME AS BEFORE LAST 1/2 MILE LEVEL 1 ST RATE PRAIRIE

WEST COR. WEST

2669.70 QUARTER SEC. COR. (BURR DAK 12 N70W 91.08'; BURR OAK 12 547E 137.28' {BURR OAK 12; BURR OAK 12} MARKED

5339.40 SEC COR.

HARRISON (NOV 1 ST)T4N R11E NORTH BETWEEN SECS 2 & 3 1833

LEAVE RIVER SET MEANDER POST 924.0

1416.36 BURR DAK 12

2640.0 QUARTER SEC CORNER {WHITE DAK 10 846E 19.8'; WHITE DAK 12 N27W 10.56'

CAT-FISH SET MEANDER POST 3498.0

3646.50 LEAVE CAT-FISH S.W. SET MEANDER POST

4009.50 CAT-FISH SE SET MEANDER POST

LEAVE SAME SET MEANDER POST 4158.0

4438.50 CAT-FISH SW SET MEANDER POST

4818.0 LEAVE CAT-FISH SET MEANDER POST

5307.72 INT. NORTH BDY 16.50' EAST OF POST WHITE OAK 20 862W 103.62'; RED OAK 820E 55.44

LAND SAME AS BEFORE NOV 18T

T4N R11E 4TH MER. EAST BET. SECS. 1833 HARRISON (NOV 2ND)

3 & 10

CREEK 19.8' CRS S.E. 495.0

2640.0 TEMPY 1/4 SEC COR

4290.0 **CREEK 13.2' CRS N.E.**

5247.0 INT. E BDY 33' NORTH OF POST LAND ROLLING 2ND RATE TIMBER ??? RED OAK,

GRUBS, ?? OF WEEDS

WEST COR. WEST BET. 3 & 10

2623.5 QUARTER BEC. COR. {RED OAK 10 N?5? 65.34'; RED OAK 10 87E 46.86' {RED OAK 10; RED DAK10}

5247.00 SEC COR

SHEET 1 OF 3

CORNER CODE E-17

Pares Apr 28,200

PO529 SECORSEC3

- 1885 RUGER VOL 2 PG 292 & #6837 FD SW BT STUMP WITH FOOT MARK & WHERE N.W. BT STUMP HAD DECAYED IN GROUND & TRACES OF OLD STAKE. DROVE NEW STAKE IN PLACE OF OLD & SURROUNDED BY 5 SMALL HH STONES. 2626.47 TO N 1/4 COR SEC 10. 2654.52 TO E 1/4 COR SEC
- 1945 WIDOT 8TH 59 #3902 SHOWS CORNER BUT DID NOT USE IT OR STATE ANYTHING ABOUT THE MON.
- 1950 FEDERAL PHOTO XA-3G-58 DATED 10/21/1950 8HOWS ORIGINAL LOCATION OF BADFISH CREEK. SINCE THEN THE CREEK WAS DRASTICALLY ALTERED. THE CREEK IS AT THIS LOCATION IS NOW A E/W CHANNEL ON THE ALONG THE SECTION LINE.

ESTABLISHED THE CORNER BUT I DID NOT PLACE A MONUMENT. THE CORNER IS IN THE CREEK.

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

BY COMPARING THE 1950 AIRPHOTO AND THE COUNTY'S 2000 DIGITAL ORTHOPHOTOS IT IS APPARENT THAT THE ORIGINAL CREEK WAS STRAIGHTENED OUT NEAR THE S 1/16TH COR OF THE SE 1/4 OF SEC 3 AND RAN STRAIGHT TO BADFISH CREEK. IT ALSO APPEARS THEY MAY HAVE USED THE E/W FENCE LINE WHICH WAS ON OR NEAR THE SECTION LINE AS THE CENTER OF THE NEWLY DREDGED CREEK. THE NEARNESS OF THE NEW LOCATION OF THE CHANNEL IS SUCH THAT RUGER'S MONUMENTS AT THE SE COR SEC 3 AND THE S 1/16TH COR OF THE SE 1/4 OF SEC 3 WERE DESTROYED. I USED THE PRORATION OF RUGER'S AND LEE'S DISTANCES IN SECTION 3 TO DETERMINE THE POSITION. THIS POSITION IS IN HARMONY WITH RECORD DISTANCES EXCEPT THE ORIGINAL GOVERNMENT SURVEY NORTH/SOUTH DISTANCES. THIS MAY BE THE RESULT OF THE 10 WATER CROSSINGS ALONG THE EAST LINE OF SEC 10 & THE EAST LINE OF SEC 3. I DUG A 5.5' LONG BY 5 WIDE HOLE 1.5 DEEP @ THE CENTER OF THE SE 1/4 OF SEC 3 AND ONLY FD 1 SMALL STONE. THE METAL FENCE BRACE ON THE NORTH SIDE OF THE HOLE MAY HAVE BEEN FOR A FENCE OPENING. I ALSO CHECKED WITH THE METAL LOCATION IN THE FIELD ON THE EAST AND WEST SIDE OF THE N/S FENCE FOR ANY INDICATION OF REMAINANTS OF AN E/W FENCE.

THE S 1/4 COR OF SEC 2 IS ONLY 6.8 NORTH OF A LINE BETWEEN THE SW & SE CORNERS OF SEC 2. PRORATION OF THE ORIGINAL GOVERNMENT DISTANCES WOULD PLACE THE POSITION 56.99 SOUTH OF MY POSITION & 9.22 WEST OF MY POSITION. THE 1950 PHOTOS SHOWS AN E/W FENCE LINE NEAR THE S 1/16TH COR & CONTINUEING EAST TO THE RIVER. ALSO IT SHOWS THE CREEK DID NOT GO E/W BUT INSTEAD WENT NORTHEASTERLY TO THE RIVER.

D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.

NONE

(E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.

NC

I, **Donald Barnes**, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

SHEET 2 OF 3

CORNER CODE E-17

A.E. 7.08 REQUIREMENT

MR 28, 2010

