

Paper weight-110# (minimum)

Black nonfading ink required

U.S. PUBLIC LAND SURVEY MONUMENT RECORD

For Public Land Survey Corners In:
T. 4N. R. 12E. 4th P.M.

WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT
REV 10/23/2004 USMONREC.DWG

CORNER CODE INDEX

	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25
A																									
B																									
C																									
D																									
E																									
F																									
G																									
H																									
J																									
K																									
L																									
M																									
N																									
O																									
P																									
Q																									
R																									
S																									
T																									
U																									
V																									
W																									
X																									
Y																									
Z																									

FULTON TWP
ROCK COUNTY WI

IF AVAILABLE
ROCK COUNTY COORDINATES PREFERRED

North _____ Elev. _____

East _____

Hor. Datum _____ Vert. Datum _____

LATITUDE _____ ELLIPS. HT. _____

LONGITUDE _____

NAD83(91) _____ NETWORK ADJ. YR _____

GPS (X) _____ TRAVERSE (X) _____

BASED ON THE FOLLOWING CONTROL:

PLACE MONUMENT SYMBOL AT PROPER LOCATION ON ABOVE INDEX

CORNER MONUMENT

WITNESS MONUMENT

BEARINGS ARE BASED ON: _____

FIELD BOOK _____ PAGE # _____

SHEET 1 OF 2

SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.

PLANNING & ZONING COMMITTEE ADOPTED THIS FORM ON 12/2/1982

CORNER CODE 0-21(1)

FU519

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

- 1834 (MAR/APR) HARRISON NORTH BET SECS 1 & 2
445.5 W.O. 12 IN DIAM.
766.92 BURR O. 12 IN DIAM
2260.5 RED O 20 IN DIAM
2640 QUARTER SEC. COR. BEARINGS {W.O. 18 N59W 16.5'
W.O. 20 N52E 25.08' W.O. 18 W.O 20} MARKED
3400.32 TRAIL N.E.
5165.16 BURR O 14
5385.6 INT. N. BDY. 16.5' E OF P. {BURR O 14 S12W 9.9'
BURR O 12 S18E 91.74' LAND ROLLING 2ND RATE
WITH BURR & W.O. TIMBER AS BEFORE
- 1880 LEE VOL 2 PG 300 SET DRY OAK STAKE S. OF RAIL FENCE FD
B.T.S & STUMP OF B.T.s & STUMP OF BT. USED TO SUBDIVIDE
SEC 1.
- 1961 SHIMEALL #13796 FD STONE AT W 1/4 SEC 1 DISTURBED
RESET SAME. 2618.21 TO SW COR SEC 1
- 1970 COMBS #1570 & 988 SHOWS THE COR BUT DOES NOT STATE
WHAT HE FOUND OR SET. 2618.44 TO SE COR SEC 2.
- 1977 SCHROEDER CSM VOL 6 PG 353 STATES NOTHING ABOUT
MON.
- 1984 BARNES C-21 SET POLY MON WITH CARSONITE 0.8' NORTH OF
NEW E/W FENCE & ON LINE WITH OLD N/S FENCE. 1229.29'
NO-21-33E OF FD 1" IRON PIPE ON NORTH SIDE STH 59. SET
POLY MON. USING HAROLD COMBS' INFORMATION
- 1984 BARNES VOL 6 PG 326 FD ALUM. MON 307,675.59;
2,259,331.98 NO-34-09W 2735.56 TO NE COR SEC 2.
- 1985 BARNES VOL 6 PG 341 STATES NOTHING ABOUT TYPE OF
MON. 2735.80 TO NE COR SEC SEC 2, 2646.91 TO CEN SEC
1, 5276.9X TO E 1/4 COR SEC 1, ANGLE 89-01-39 @ W 1/4 COR
SEC 1 FROM NW COR SEC 1 TO CEN SEC 1
- 1985 BRANDT #13733 FD ALUM
- 1985 BARNES VOL 6 PG 342 NB9-06-42E 2646.91 TO CEN SEC 1,
NO-05-03E 2735.80 TO NW COR SEC 1, 5276.86 TO E 1/4 COR
SEC 1. ASSUMED NORTH.
- 1985 SCHROEDER #13602 DOES NOT STATE THE TYPE OF
MONUMENT
- 1986 BRANDT #13511 FD ALUM 2648.55 TO CEN SEC 1.
- 1989 SCHROEDER CSM VOL 14 PG 200 STATES NOTHING ABOUT
TYPE OF MON.
- 1994 SCHROEDER CSM VOL 17 PG 316 STATES NOTHING ABOUT
TYPE OF MON. ANGLE 89-34-25 @ E 1/4 COR SEC 2 FROM SE
COR SEC 2 TO W 1/4 COR SEC 2
- 1994 SCHROEDER #9947 CALLS FOR BUT STATES NOTHING ABOUT
MON.
- 1995 NORTHROP #9281 ALUM MON FND. NO-07-15E 2735.75 TO
NW COR SEC 1 TRUE NORTH REFERENCED TO I-90 REF LINE
BEARING
- 1997 KEACH #8654 & 8431 FD COUNTY MON. 2618.23 SO-21-37W
TO SE COR SEC 2, GRID NORTH [NAD83(91)] IS 0-39-51.3
WEST OF TRUE NORTH.
- 1997 NORTHROP #8449&8446 ALUM. 2619.85 TO CEN SEC 2,
2735.73 TO NE COR SEC 2, ANGLE 90-02-57 @ E 1/4 COR SEC
2 FROM W 1/4 COR SEC 2 TO NE COR SEC 2.
- 1997 NORTRHOP #8447 & 8450 STATES NOTHING ABOUT MON.
S89-23-10W 2619.85 TO CEN SEC 2, NO-33-53W 2735.73 TO
NE COR SEC 2.
- 2000 COMBS CSM VOL 26 PG 43 FD ALUM. 2617.97 TO SE COR SEC
2, 911.13 TO NORTH LINE OF HEMENWAY LANE R/W LANE.

SHEET 1 OF 2
CORNER CODE C-21(1)

David Barnes
11/01/07

FU519

FD ALUM. MON/ CARSONITES POST & REFERENCE MONUMENTS.

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED FD ALUM. MON. IN HARMONY WITH REC. DISTANCES. IN HARMONY WITH SHIMEALL'S 1961 SURVEY. HE FOUND THE STONE

D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.

NONE

(E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.

NO

I, **Donald Barnes**, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Donald Barnes
Seal

Emboss
11/01/07

SHEET 2 OF 2

CORNER CODE
A.E. 7.08 REQUIREMENT

C-21(1)