U.S.

PUBLIC LAND SURVEY MONUMENT RECORD

| For Public Land Survey Corners In: T. N. R. 12E. 4th P.M. | WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT REV 10/23/2004 USMONREC,DWG |
|--|---|
| CORNER CODE INDEX A 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 2 | TWP |
| B C S S S S S S S S S S S S S S S S S S | ROCK COUNTY WI |
| D E F | C D IF AVAILABLE E ROCK COUNTY COORDINATES PERFERRED F |
| G H J | G H North Elev |
| K & A A B | K East |
| M N O O O O O O O O O O O O O O O O O O | M N Hor. Datum Vert. Datum |
| P Q Q Q Q Q Q Q Q Q Q Q Q Q Q Q Q Q Q Q | Q LATITUDE ELLIPS. HT |
| S T 30 79 78 7 70 75 | R S LONGITUDE |
| v | U V NAD83(91)NETWORK ADJ. YR |
| x y y y | Y (11) |
| 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 PLACE MONUMENT SYMBOL AT PROPER LOCATION ON ABOVE INDEX | BASED ON THE FOLLOWING CONTROL: |
| ♦ CORNER MONUMENT (a) | WITNESS MONUMENT |
| | |
| | |

BEARINGS ARE BASED ON:____

| FIELD BOOK PAGE # SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT ANI | HEET RROUNI | DING | OF | 2 |
|---|----------------|------|-----|--------|
| PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH. | | | | |
| PLANNING & ZONING COMMITTEE ADOPTED THIS FORM ON 12/2/1982 | | | | |
| | | _ | 1 - | \sim |

```
FU569^
(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or
any other material evidence you considered, and whether the monument was found or placed.
1834 (MAR/APR) HARRISON
                           NORTH BETWEEN 14 & 15
        2226.84
                   LEAVE ROCK RIVER & ESTABLISHED MEANDER
                   POST ON RIGHT BANK BEARINGS (BURR O B
                   585E 87.12' W.O. 8 N51E 71.94' MARKED
        2392.5
                   TRAIL CRS E
        2640
                    QUARTER SEC COR BEARINGS (BUR O 8 S85E
                    87.12' W.O. 8 N51E 71.94' BURR D 8 W.D.
                    89 MARKED
        5280
                    COR TO SECS 10 11 14 15 (WO 24 N76W
                    161.04' HICHY 12 563W 36.3' W.O. 18 N35E
                    69.3' W.O. 18 S88E 151.8' LAND ROLLING
                    2<sup>ND</sup> RATE AND SAME AS BEFORE.
1836 (AUG) BURNHAM
                        NORTH BETWEEN SECTIONS 14 & 15
                         T4N R12E
        1419
                   TRAIL @ NE & SW
        1815
                   TO LEFT BANK ROCK RIVER
        2272.38
                   INT RIGHT BANK 268.62' WEST OF M.P. GOOD
                    \mathbf{Z}^{\text{ND}} RATE ? & VELION? DAK OPENINGS BROKEN
                        SOUTH CORRECTED TO THE?
                        SECS 14 & 15
                    SET MP ON LEFT B. W OAK 12 N61 1/2E 15.18'
        457.38
                   W. DAK 16 S21W 49.5' WHITE DAK 18 IN DIA
1836 (AUG) BURNHAM
                        RANDOM BETWN SECS 15 & 22
                   ENTER DRY PRAIRIE
        122
        2640
                   LEAVE SAME
        5237.1
                   INT. EAST BOUNDY 42.9' SOUTH WEST 1/2
                   FIRST RATE DRY PRAIRIE EAST 1/2 W., Y. & BUR
                    DAK. DAK OPENINGS BROKEN
                        CORRECTED BETWE SECS 15 & 22
        2618.22
                   SET 1/4 SEC POST BUR DAK 12 N59 1/2E 41.58'
                   BUR OAK 12 S30W 80.52'
                   TO CORNERS
        5237.1
1836 (JULY11) BURNHAM NORTH BETWEEN SECTIONS 22 & 23
        676.5
                   BUR OAK 12 IN DI
        2640
                   SET 1/4 SEC POST YELLOW OAK 16 S79W
                    11.22' BUR OAK 12 S25 1/2E 37.62'
        4170.54
                   BUR DAK B IN DI
        5280
                   SET POST COR TO 14,15,22,23
                   YELLOW OAK 24 N53W 37.62' W. OAK 12 S20E
                    11.22' FIRST RATE W. & BUR DAK OPENINGS
                   BUT RATHER BROKEN
1836 (JULY) BURNHAM
                        EAST RANDOM BETWEEN SECS 14 & 23
        2376
                   ENTER WILD MEADOW
        2739
```

STREAM 13.2' S.W. & NW

3379.2

LEAVE WILD MEADOW

5240.4

INT EAST BOUNDY 9.9' N GODD SECOND RATE

BUR DAK DPENINGS & WILD MEADOWS WEST CORRECTED BETWEEN 14 & 23

NO STATION

2620.2

SET 1/4 SEC POST WILLOW 6 542 1/2W 69.3' NO OTHER BEARING

5240.4

TO CORNERS

1960 RYAN #6181 STATES NOTHING ABOUT MON. 1611.2 TO MP ON LEFT BANK OF ROCK RIVER

1962 ELY #1230 STATES NOTHING ABOUT TYPE OF MON.

1978 BARNES VOL 5 PG 472 FD HH WITH DRILL HOLE. REPLACED WITH ALUM. MON.

1990 BARNES VOL 6 PG 406 FD ALUM. MON. 2619.93 TO N 1/4 COR SEC 23, ANGLE 90-00-13 @ N 1/4 COR SEC 23 FROM S 1/4 COR SEC 23 TO NW COR SEC 23, ANGLE 179-43-43 @ N 1/4 COR SEC 23 FROM NE COR TO NW CORNERS SEC 23.

PAGE 1 OF 2

CORNER CODE N-17(1)

Pould Barnes 11/12/07

FU569

- 1990 BARNES N-17 FD ALUM. MON. PLACED CARSONITE 1' NW. REF SAME. SE OF FENCE INT.
- 1994 COMBS #9540 CALLS FOR BUT STATES NOTHING ABOUT MON. 2629.49 TO N 1/4 COR SEC 22, ANGLE OF 89-12-45 @ NE COR SEC 22 FROM E 1/4 COR SEC 22 TO N 1/4 COR SEC 22, 2657.20 TO E $\frac{1}{4}$ COR SEC 22
- 1999 LATHROP CSM VOL 22 PG 208 ALUM. MON. 2629.78 TO N 1/4 COR SEC 22, ANGLE 91-05-00 @ N 1/4 COR SEC 22 FROM NE COR SEC 22 TO N/S 1/4 LINE SEC 22.
- 2001 KASTEN CSM VOL 24 PG 149 STATES NOTHING ABOUT MON. 2629.62 TO N 1/4 COR SEC 22
- CHAPUT #14799 STATES NOTHING ABOUT MON. SO1-06-35E 1328.44 TO FD 3/4 ROD & AT FD ROD S88-21-27W 1318.21 TO FD RDD

USED MY 1990 OBSERVATIONS. FD ALUM. MON./CARSONITE & REFERENCE MONUMENTS.

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED FD ALUM. MON.

- D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.
- (E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.

I, Donald Barnes, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

SHEET 2 OF 2

Botherson COR A.E. 7.08 REQUIREMENT CORNER CODE N-17(1)