

U.S. PUBLIC LAND SURVEY MONUMENT RECORD

For Public Land Survey Corners In:
T. 4N. R. 12E. 4th P.M.

WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT
REV 10/23/2004 USMONREC.DWG

CORNER CODE INDEX

	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25		
A																											A
B																											B
C																											C
D																											D
E																											E
F																											F
G																											G
H																											H
J																											J
K																											K
L																											L
M																											M
N																											N
O																											O
P																											P
Q																											Q
R																											R
S																											S
T																											T
U																											U
V																											V
W																											W
X																											X
Y																											Y
Z																											Z

FULTON TWP
ROCK COUNTY WI

IF AVAILABLE
ROCK COUNTY COORDINATES PREFERRED

North _____ Elev. _____

East _____

Hor. Datum _____ Vert. Datum _____

LATITUDE _____ ELLIPS. HT. _____

LONGITUDE _____

NAD83(91) _____ NETWORK ADJ. YR _____

GPS (X) _____ TRAVERSE (X) _____

BASED ON THE FOLLOWING CONTROL:

PLACE MONUMENT SYMBOL AT PROPER LOCATION ON ABOVE INDEX

CORNER MONUMENT

WITNESS MONUMENT

(a)

BEARINGS ARE BASED ON: _____

FIELD BOOK _____ PAGE # _____

SHEET 1 OF 3

SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.

PLANNING & ZONING COMMITTEE ADOPTED THIS FORM ON 12/2/1982

CORNER CODE E-19(1)

FU530 ^

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

- 1834 (MAR/APR) HARRISON EAST ON RANDOM BET SECS 2 & 11
2640 TEMPY 1/4 SEC COR.
5240.4 INT. E BDY 19.8' N OF POST LAND FOR THE 1ST 1/2
SAME AS BEFORE LATTER 1/2 RATHER BROKEN 2ND
RATE TIMBER W.O.
COR WEST
2620.2 QUARTER SEC CORNER {W.O. 18 S50W 18.48' W.O.
16 N2W 6.6' WO 18, WO.O. 16} MARKED
5240.4 INT. SEC. COR.
- 1876 TWP RD BK 1 PG 53 COMMENCING 49.5' SOUTH OF SOUTH
QUARTER STAKE OF SEC 2 OF THE TOWN OF FULTON, & 24.75'
WEST OF SAID QUARTER LINE; THENCE NORTH ON LAND OF
JAMES WELCH, JOHN SHERMAN AND PATRICK QUIGLEY 5478'
TO HIGHWAY AND 24.75' WEST OF PARALLEL WITH SAID
QUARTER LINE, SAID LINE BEING THE CENTER OF SAID
HIGHWAY WHICH IS LAID OUT 49.5' WIDE AND \$60.00
DAMAGES IS AWARDED TO PATRICK QUIGLEY.
- 1977 BARNES VOL 5 PG 245 FD C.I. MON. & REF. SAME. 10' WEST
OF WEST EDGE OF N/S PVMT. & ON LINE WITH SOUTH PVMT
EDGE PROJECTED FROM EAST.
- 1978 SANDSNES VOL 5 PG 447 PROVIDED THE FOLLOWING:
305,021.97; 2,256,764.96
- 1978 SANDSNES #997 & 1159 GROUND CONTROL FOR AIR PHOTO
MAPPING
- 1979 WEIR BK 30 PG 23 SUN VALLEY EAST; ALUM
- 1984 COMBS CSM VOL 11 PG 510 CI
- 1984 BARNES VOL 6 PG 326 305,021.97; 2,256,764.97 S89-14-
41W 2585.10 TO SW COR SEC 2
- 1985 SCHROEDER #13604 DOESN'T CALL FOR TYPE OF MON.
2625.8 TO CENTER OF SEC 2
- 1986 SCHROEDER #13374 DOESN'T CALL FOR TYPE OF MON.
2625.8 TO CENTER OF SEC 2
- 1989 NORTHROP CSM VOL 13 PG 498 FD C.I. N89-55-25E 2584.0
TO SE COR SEC 2
- 1990 NORTHROP #11906, 11905, 2480, & 2481 CI, 2584.94 TO NE
COR SEC 10, S3-03-41E 1295.43 TO NE COR OF PLAT, SE COR
OF N 1/4 OF NW 1/4, ANGLE 92-59-30 @ N 1/4 COR SEC 11 FROM
NE COR OF PLAT TO NE COR SEC 10, & ANGLE @ S 1/4 COR
SEC 2 FROM SW COR SEC 2 TO CENTER SEC 2 IS 90-03-32.
- 1990 NORTHROP E-19 FD CI MON. NEAR NORTH EDGE OF GRAVEL
DR. 305,021.97N/S; 2,256,764.97 E/W THIS COR IS AN
EXISTING FD MON COR OF RECORD. A HARRISON CAST IRON
MON WAS FOUND AT THIS COR IN THE POSITION SHOWN ON
THE EXISTING TIE SHEET IN THE COUNTY SURVEYOR RECORDS
BY DONALD BARNES, DATE 1977
- 1991 COMBS #11925 STATES NOTHING ABOUT MON. 2584.79 TO
NE COR SEC 11, & ANGLE 87-00 @ N 1/4 COR SEC 11 FROM NE
COR SEC 11 TO MP ON NORTH BANK OF ROCK RIVER, 1145.43
TO MP
- 1991 NORTHROP #11909 & #11910 EXIST. C.I. FD AT 1/4 COR
- 1991 NORTHROP #11979 & 11978 FD C.I.
- 1991 COMBS CSM VOL 15 PG 263 CI
- 1992 COMBS BK 32 PG 157 FOX MEADOWS SHORES CI 2584.79 TO
NE COR SEC 11
- 1993 COMBS "FOX MEADOW SHORES FIRST ADD." BK 32 PG 161
C.I. PIPE 2.96 TO THE EAST. 2587.75 TO NE COR SEC 11
- 1994 COMBS CSM VOL 17 PG 258 C.I. 2584.79 TO NE COR SEC 11
- 1995 COMBS CSM VOL 19 PG 170 C.I. 2584.79 TO NE COR SEC 11
- 1997 NORTHROP #8449 & 8446 CI 2626.0X TO CEN SEC 2 &
5357.05 TO N 1/4 COR SEC 2
- 1997 NORTHROP #8447 & 8450 CI. 2626.0 TO CEN SEC 2 &
5357.05' N 1/4 COR SEC 2.

SHEET 1 OF 3

CORNER CODE E-19(1)

Donald Barnes
10/19/2006

FU530

1997 SCHROEDER CSM VOL 20 PG 74 STATES NOTHING ABOUT
MON. ANGLE 90-34-50 @ S 1/4 COR SEC 2 FROM N/S 1/4 LINE
SEC 2 TO SE COR SEC 2. FROM SEC COR HE SET A PROPERTY
PIPE EASTERLY 10.25.

1998 COMBS "FOX MEADOW SHORES SECOND ADD." BK 32 PG 523
C.I. 2584.79 TO NE COR SEC 11.

2002 COMBS CSM VOL 25 PG 282 & 437 CI 2584.79 TO NE COR
SEC 11

DUG 0.3 DEEP & FD TOP 4" OF C.I. MON LAYING HORIZONTALLY
WITH NAIL IN DIRT. 1.1 DEEP FOUND CI MON IN EXCELLENT
CONDITION.

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

I WAS UNABLE TO FIND ANY RECORD STATING WHO OR HOW THE
CAST IRON MONUMENT WAS SET. SINCE THIS LOCATION DOES NOT
APPEAR TO BE IN A MAJOR CONFLICT WITH ANYTHING, I ACCEPTED
THE CI MON.

D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.

THE FD CI AND NAIL DOES NOT AGREE WITH FD REFERENCE PIPES.

(E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.

I, **Donald Barnes**, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Seal

Donald Barnes

Emboss

10/19/2006

SHEET 2 OF 3

CORNER CODE
A.E. 7.08 REQUIREMENT

E-19(1)

