

# U.S. PUBLIC LAND SURVEY MONUMENT RECORD

For Public Land Survey Corners In:

WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT

T. 4 N. R. 12 E. 4th P.M.

REV 10/23/2004

USMONREC.DWG

### CORNER CODE INDEX

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	
A																									A
B	6					5								4											B
C																									C
D																									D
E																									E
F																									F
G	7					8								9											G
H																									H
J																									J
K																									K
L	18					17								16											L
M																									M
N																									N
O																									O
P	19					20								21											P
Q																									Q
R																									R
S																									S
T	30					29								28											T
U																									U
V																									V
W																									W
X	31					32								33											X
Y																									Y
Z																									Z

FULTON TWP  
ROCK COUNTY WI

IF AVAILABLE  
ROCK COUNTY COORDINATES PREFERRED

North \_\_\_\_\_ Elev. \_\_\_\_\_

East \_\_\_\_\_

Hor. Datum \_\_\_\_\_ Vert. Datum \_\_\_\_\_

LATITUDE \_\_\_\_\_ ELLIPS. HT. \_\_\_\_\_

LONGITUDE \_\_\_\_\_

NAD83(91) \_\_\_\_\_ NETWORK ADJ. YR \_\_\_\_\_

GPS (X) \_\_\_\_\_ TRAVERSE (X) \_\_\_\_\_

BASED ON THE FOLLOWING CONTROL:  
\_\_\_\_\_

PLACE MONUMENT SYMBOL  AT PROPER LOCATION ON ABOVE INDEX

CORNER MONUMENT       WITNESS MONUMENT

BEARINGS ARE BASED ON: \_\_\_\_\_

FIELD BOOK \_\_\_\_\_ PAGE # \_\_\_\_\_ SHEET 1 OF 4

SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.

PLANNING & ZONING COMMITTEE ADOPTED THIS FORM ON 12/2/1982

CORNER CODE A-15(1)

FU508 ^

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

1833 (SEP 21ST) MULLETT & BRINK EAST ON SOUTH SIDE SECTION  
34 T5N R12E

1368.18 WHITE OAK 12 IN DIAMETER  
2640 SET QUARTER SECTION POST WHITE OAK 14 N52W  
25.08' WHITE OAK 16 N71E 21.12'  
5280 SET POST CORNER SECTIONS 34 & 35 BUR OAK 14  
N41W 26.4' BUR OAK 16 N25E 35.64' LAND  
ROLLING SECOND RATE TIMBER WHITE BLACK & BUR  
OAK

1881 LEE VOL 2 PG 324 MADE NO COR. 2584.89 TO NW COR SEC  
3, 2584.89' TO NE COR SEC 3, VAR 8-10 TO CEN SEC 3

1884 RUGER VOL 2 PG 385 SET HH STONE 17X9X7 SURROUNDED  
BY 4 HH. EAST OF S 1/4 COR SEC 34. @ S 1/4 COR SEC 34 FD  
REMAINS OF BOTH BT STUMPS & REMAINS OF OLD STAKE.  
DROVE NEW STAKE & SURROUNDED BY A LOT OF FLINTY H.H.  
STONES

1884 RUGER VOL 2 PG 389 & #1000 @ S 1/4 COR SEC 34 FD BT  
STUMPS & REMAINS OF OLD STAKE DROVE NEW STAKE  
SURROUNDED BY HH STONES. 2651.22 FROM S 1/4 COR SEC  
34 TO SW COR SEC 34, 2645.94 FROM S 1/4 COR SEC 34 TO  
SE COR SEC 34, & 2642.64 FROM S 1/4 COR TO CENTER SEC  
34.

1885 RUGER BK 4 PG 33 "PLAT OF TOYNTON & OTHERS SUB" HH  
17X9X7 SURROUNDED BY HH. @ N 1/4 COR SEC 3

1886 DOUGLAS VOL 6 PG 348 DANE COUNTY SURVEYOR. 2649.24  
FROM S 1/4 COR 34 TO SE COR SEC 34, VAR 6-30 2642.64?  
FROM S 1/4 COR SEC 34 TO CEN SEC 34, VAR 6-30 5285.28?  
FROM S 1/4 COR SEC 34 TO N 1/4 COR SEC 34.

1892 BLEEDORN VOL 2 PG 469 & #1002 HH SET BY RUGER P 310  
SET HH 192.72' SOUTH OF 1/4 COR ON N/S 1/4 LINE. 1185.36'  
WEST OF CENTER OF RD.

1911 HINTZE ALBION T5N R12E N89-29E 2648.6 TO SE COR  
SEC 34. S89-30W 2650.6 TO SW COR SEC 34. NO TREES.  
83.2' WEST OF STONE AT N 1/4 COR SEC 3. SET SOUTH 1/4 COR  
OF SEC 34, 83.2' WEST OF STONE AT ROCK COUNTY CORNER.  
AT DANE COUNTY CORNERS, HINTZE INSTALLED CONCRETE  
MONUMENTS. THE DIFFERENCE IN BEARING OF LINES  
BETWEEN SECTION CORNERS GIVES THE TRUE DEVIATION  
FROM THE STRAIGHT LINE. SOME OF THE BEARINGS ARE  
MAGNETIC, CHECKED BY MEASUREMENTS, AND THE REST ARE  
TRANSIT LINES CHECKED BY OBSERVATIONS ON POLARIS. I  
HEREBY CERTIFY THAT THE DISTANCES AND BEARINGS ARE  
CORRECT ACCORDING TO SURVEY MADE UNDER THE  
PROVISIONS OF CHAPTER, 39 SECTION 825 OF THE REVISED  
STATUTES OF WISCONSIN AND IN ACCORDANCE WITH THE  
RULES ESTABLISHED BY THE UNITED STATES LAND OFFICE.

1956 ELY BK 18 PG 31 LADD'S SECOND ADD. STATES NOTHING  
ABOUT MON.

1958 ELY BK 19 PG 9 SUNSET COURT. STATES NOTHING ABOUT  
MON.

1960 ELY #2117 OL 42 STATES NOTHING ABOUT MON.

1960 ELY #13418 OL 44 STATES NOTHING ABOUT MON.

1961 ELY #7220 PLOT OF TOYNTON & OTHERS SUB BK 4 PG 33 LOT  
6,9-11,13-14, 16-19 CHISELED CROSS ON ROCK; NE COR OF  
OL 16 & NW COR OF OL 42. N89-33E 600.74 FROM NE COR  
LOT 8 SUNSET ADD & NO-57W 1279.81 FROM NORTH LINE LOT  
7 BLOCK C.

1963 ELY #13407 SUB OL 47 CALLS FOR N 1/4 COR SEC 3 BUT  
PAPER IS CUT OFF & CAN NOT READ DESCRIPTION

1963 ELY BK22 PG 2 ST. JOSEPH'S ADD. NE CORNER OF LOT 20.  
122.57 NORTH OF NORTH R/W LINE OF HEMPHILL. 2X30"  
STEEL PIPE.

PAGE 1 OF 4

CORNER CODE A-15(1)

Donald Barnes

1/09/07

FU508

- 1963 TREFZ #2094 SUB. STATES NOTHING ABOUT MON.  
1964 ? #1007 & 1008 DANE COUNTY TIE BRASS CAP IN CONCRETE  
MON. @ S 1/4 COR SEC 34. I FOUND THE S 1/4 COR SEC 34 T5N  
R12E  
1965 WEIR #13896 DOESN'T DESCRIBE MON.  
1972 WEIR #2087 SUB IRON STAKE FD.  
1973 TREFZ #2061 SUB CSM VOL 3 PG 228 STATES NOTHING  
ABOUT MON. S5-40-10E 518.85 ALONG 1/4 LINE, EAST LINE  
OF ST. JOSHOPE'S ADD. BK 22 PG 1-2, & WEST LINE OF  
LADD'S SECOND ADDITION BK 18 PG 31 TO SOUTH LINE OF  
LADD LANE.  
1978 SANDSNES #01013 CONTROL FOR MAPPING PROJECT.  
1978 SANDSNES VOL 5 PG 447 PROVIDED FOLLOWING  
COORDINATES: 310,294.62; 2,251,423.61  
1979 MORTHROP #13894 FD CONC. MON OF RECORDS AT S 1/4 COR  
SEC 34 STATE PLANE COORD. SOUTH ZONE; 310,294.16;  
2,251,339.92 EAST  
1984 BARNES VOL 6 PG 326 COORDINATES BY SANDSNES  
310,294.62; 2,251,423.61 S89-41W 83.69 TO S 1/4 COR SEC  
34, S88-57-56W 2587.28 TO NW COR SEC 3, N88-52-35E  
2586.35 TO NE COR SEC 3, S1-41-28E 2674.56 TO CEN SEC  
3, 5333.65 TO S 1/4 COR SEC 3. COORDINATES @ S 1/4 COR  
SEC 34 310,294.16; 2,251,339.92 BY NORTROP,  
1997 NORTHROP#6682 2649.10 TO SE COR SEC 34.  
2001 RIESCP CSM VOL 24 PG 333 CONC. AT S 1/4 COR SEC 34. N 1/4  
COR SEC 3 IS 83.68 WEST OF S 1/4 COR SEC 34. N 1/4 COR SEC  
3 TO NE COR SEC 3 IS 2586.65  
2001 RIESCP A-15 3/4 REBAR SET N88-54-06E 83.68' OF S 1/4 COR  
SEC 34. REFERENCED MON. @ S 1/4 COR SEC 34 FD  
CONCRETE MON. THE CORNER WAS RESET ON COUNTY LINE  
BETWEEN SE COR SEC 34 T5N R12E AND S 1/4 COR SEC 34  
T5N R12E, TOH CONCRETE MONUMENTS FROM HINZ  
RESURVEY OF ALBION TWP. E/W POSITION WAS DETERMINED  
BY THAT SHOWN BY D. BARNES PLAT & RECORD VOL 6 PG 34  
83.69 E OF DANE COUNTY CORNER. [DISCREPANCY: THE  
CORNER IS ON COUNTY LINE AND IS 1.2' NORTH OF THAT AS  
SHOWN ON PLAT OF ST. JOSEPH'S ADDITION.]  
2001 RIESOP A-17(3) 3/4" REBAR SET N88-54-06E 2586.65 FROM N  
1/4 COR SEC 3 TO NE COR SEC 3.  
2004 COMBS "HEMPHILL STREET COMMONS" BK 32 PG 675-676 FD  
3/4" ROUND IRON PIN. N89-54-06E 2586.67 TO NE COR SEC  
3, S1-38-31E 320.64 TO BLOCK COR.

FD 3/4" REBAR AT THE N 1/4 COR SEC 3 WHICH IS IN HARMONY WITH  
RIESOP'S TIES. AT S 1/4 COR SEC 34 T5N R12E FD CONC. MON. WITH  
PIN IN TOP NEXT TO A FENCE POST.

LEE'S 1881 AND RUGER'S 1884 DISTANCES INDICATE THEIR INTENT  
WAS TO PLACE THE N 1/4 COR MIDWAY BETWEEN THE NE & NW  
CORNERS OF SEC 3. FD RIESOP'S REBAR WHICH IS ON LINE  
BETWEEN THE S 1/4 COR SEC 34 AND THE SE COR OF SEC 33.

*Donald Barnes*

*11/09/07*

SHEET 2 OF 4  
CORNER CODE **A-15(1)**

FU508

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED FD MONUMENTS.

D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.

IN 2001 RIESGP (A-15) SET A 3/4 REBAR AND CALLED FOR A DISCREPANCY. CALLS FOR THE CORNER BEING ON THE COUNTY LINE AND IT IS 1.2' NORTH OF THAT AS SHOWN ON PLAT OF ST. JOSEPH'S ADDITION.

IN ELY'S 1963 PLAT ST. JOSEPH'S ADD (BK22 PG 2) HE DOES NOT STATE THE MONUMENT THAT HE HAD.

(E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.

NO

I, **Donald Barnes**, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Donald  
Barnes

Emboss

1/09/07

SHEET 3 OF 4

CORNER CODE **A-15(1)**  
A.E. 7.08 REQUIREMENT

