

# U.S. PUBLIC LAND SURVEY MONUMENT RECORD

For Public Land Survey Corners in:

WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT

T. 1N., R. 11E


### CORNER CODE INDEX

NEWARK TWP

ROCK COUNTY WI

IF AVAILABLE  
ROCK COUNTY COORDINATES PREFERRED

A	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25
B																								
C	6													3										1
D																								
E														4										
F																								
G	7													10										12
H																								
I																								
J																								
K																								
L	18													15										13
M																								
N																								
O																								
P	19													22										24
Q																								
R																								
S																								
T	30													27										25
U																								
V																								
W																								
X	31													34										36
Y																								
Z																								

PLACE MONUMENT SYMBOL  AT PROPER LOCATION ON ABOVE INDEX

North \_\_\_\_\_ Elev. \_\_\_\_\_

East \_\_\_\_\_

Hor. Datum \_\_\_\_\_ Vert. Datum \_\_\_\_\_

LATITUDE \_\_\_\_\_ ELLIPS. HT. \_\_\_\_\_

LONGITUDE \_\_\_\_\_

GPS (X) \_\_\_\_\_ TRAVERSE (X) \_\_\_\_\_

BASED ON THE FOLLOWING CONTROL:

 CORNER MONUMENT

 WITNESS MONUMENT

(a)

BEARINGS ARE BASED ON: \_\_\_\_\_

FIELD BOOK \_\_\_\_\_ PAGE # \_\_\_\_\_

SHEET 1 OF 2

SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.

PLANNING & ZONING COMMITTEE ADOPTED THE ABOVE FORM ON 12/2/1982

CORNER CODE E-15

NE528s1/4cor3

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

1834 MILLER PG 24 EAST RANDOM BETWEEN SECS 3 & 10  
2719.2 TRAIL N.W.  
5275.38 INTERSECTED SEC LINE 4.62' NORTH POST. LAND DRY ROLLING  
PRAIRIE 2ND RATE.

WEST CORRECTION

2637.36 SET 1/4 SEC POST IN MOUND OF EARTH AND SOD  
5275.38 SEC COR. MARCH 10, 1834

1871 COLLINS REMONUMENTATION

PG 171 EAST BETWEEN 3 & 10 VARIATION 2-05

2685.54 SET 1/4 STONE IN OLD MOUND AS SHOWN BY MR. POWERS.  
CONTINUED EAST SAME VARIATION

5320.92 SECTION CORNER.

REMON. MAP. 2685.54' VAR 2-05 TO SW 3 & 2635.38' VAR 2-05 TO SE  
COR SEC 3.

1873 RUGER VOL 2 PG 117 STONE MON. 2678.28 TO SW COR SEC 3, 2630.60 TO SE COR  
SEC 3, 2662.94 TO CENTER OF SEC 3, & 5316.80 TO N 1/4 COR SEC 3.

1974 COMBS CSM 4 PG 48 1328.4 TO NORTH 1/16TH COR  
OF NW 1/4 OF SEC 10 & ANGLE OF 93-29 @ N 1/4 COR SEC 10 FROM N/S CENTER  
LINE OF SEC 10 TO ALONG THE NORTH LINE OF THE NW 1/4 LINE OF SEC 10.

1977 BARNES VOL 5 PG 332 FD ALUM. MON. 3.1' SOUTH OF NORTH PVMT EDGE.  
REFERENCED SAME.

FD ALUM. MON. COLLIN'S REMONUMENTATION DISTANCES WAS IN HARMONY  
WITH THE N/S FENCE. I DUG AND FOUND CUT LIMESTONE 24.14 EAST OF THE ALUM.  
MON. THE CRUZ AIR BROKE THE L.S. LENGTHWISE. IT IS ABOUT 10" DEEP & 1'  
NORTH OF CENTER OF PVMT & ON LINE WITH N/S FENCE AND TREE ROWS ON THE  
NORTH & SOUTH SIDES OF THE ROAD. PLACED MAGNETS 14" DEEP ON EAST SIDE  
OF L.S.

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found  
perpetuated location?

ACCEPTED PERPETUATED LOCATION AS MONUMENT BY L.S..

D) Describe any material discrepancy between the location of the corner as restored or reestablished and the  
location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy  
on the plan view drawing under (a), above. Show the distances between the corner as previously restored or  
reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments  
shown on the drawing in (a), above.

FD ALUM. MON. IS ON LINE WITH THE SE & SW CORNERS BUT NOT AT  
PROPORTIONATE DISTANCES WITH COLLIN NOR ORIG. GOV. MEASUREMENTS. FD  
CUT LIMESTONE IS IN HARMONY WITH COLLIN'S REMONUMENTATION DISTANCES  
AND RUGER'S PRORATION DISTANCES IN SEC 3. RECORDS INDICATES THE ALUM.  
MON. WAS PROBABLE SET BY THE FORMER COUNTY SURVEYOR.

(E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including  
the directions and distances to other public land survey corners used as evidence or used for proportioning the  
corner location.

I, Donald Barnes, hereby certify that the corner location as identified by the corner code index was  
determined by me under my direction and control and that this U.S. Public Land Survey Monument Record  
is correct and complete to the best of my knowledge and belief.

seal  
Donald Barnes  
emboss  
6-28-01

Number of included sheets 1

CORNER CODE E-15

