

# U.S. PUBLIC LAND SURVEY MONUMENT RECORD

For Public Land Survey Corners in:

WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT

T. 1N., R. 2E 4th P.M.

### CORNER CODE INDEX

A	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25
B																									
C	6																								
D																									
E																									
F																									
G	7																								
H																									
I																									
J																									
K	18																								
L																									
M																									
N																									
O	19																								
P																									
Q																									
R		20																							
S																									
T																									
U	30																								
V																									
W																									
X																									
Y																									
Z																									

BELOIT TWP  
ROCK COUNTY, WI

IF AVAILABLE  
ROCK COUNTY COORDINATES PREFERRED

North 227,717.41 Elev. \_\_\_\_\_

East 477,785.87

Hor. Datum \_\_\_\_\_ Vert. Datum \_\_\_\_\_


LATITUDE \_\_\_\_\_ ELLIPS. HT. \_\_\_\_\_

LONGITUDE \_\_\_\_\_

ELLIPS. DATUM  
NAD83(91) \_\_\_\_\_ COUNTY \_\_\_\_\_ LIST \_\_\_\_\_

GPS (X) \_\_\_\_\_ TRAVERSE (X) \_\_\_\_\_

BASED ON THE FOLLOWING CONTROL:

PLACE MONUMENT SYMBOL  AT PROPER LOCATION ON ABOVE INDEX

 CORNER MONUMENT

WITNESS MONUMENT

(a)  
BEARINGS ARE BASED ON:

FIELD BOOK \_\_\_\_\_ PAGE # \_\_\_\_\_

SHEET 1 OF 2

SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.

PLANNING & ZONING COMMITTEE ADOPTED THE ABOVE FORM ON 12/2/1982

CORNER CODE E-11

be526

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

- 1834 HARRISON EAST ON RAND. BETWEEN SEC 9 & 16
  - 297 TO SUMMIT OF RIDGE E. SIDE OF DRAUGHT
  - 2640 TEMPY 1/4 SEC. COR.
  - 5259.54 INT. E. BDY 26.4' SOUTH OF POST WEST COR. WEST
  - 2629.77 QUARTER SEC COR. ON HIGH GROUND SET POST & MOUND
  - 5259.54 SEC COR.
- 1844 TOWN ROAD RECORDS 2765.4 TO N 1/4 COR SEC 4.
- 1851 McVEAN VOL 1 PG 1 2677.62 TO SW COR SEC 4, 2648.58 TO SE COR SEC 4, 2597.76 TO CENTER 4 (CENTER OF ROAD), & 5435.76 TO N 1/4 COR SEC 4.
- 1974 LEE MAP #209 SET CI MON. N0-17-45E 2653.52 TO CENTER SEC 4 & S89-58-32E 2650.37 TO SE COR SEC 4. 2633.44 TO CENTER OF SECTION 9 & 5277.74 TO S 1/4 COR SEC 9. ANGLE OF 89-43-43 FROM N 1/4 COR SEC 4 TO SE COR SEC 4 & 180-00-00 FROM SE TO SW CORNERS OF SEC 4.
- 1975 BICKEL CSM V5 PG 62 FOUND CI
- 1977 LEE CMS V6 PG 188 FOUND CI
- 1980 BARNES 2677.2 TO SW COR SEC 4, LEE 1970 2650.37 TO SW COR SEC 4, ANGLE 89-59-10 W 1/4 COR SEC 4 TO S 1/4 COR SEC 4 AT SW COR SEC 4, ANGLE 180-33-25 FROM S S1/4 COR SEC 5 TO 1/4 COR SEC 4 AT THE SW COR SEC 4.

FOUND C.I. & CARSONITE. 2659.5 (REC 2597.76) TO CENTER OF NORTHERN ROAD. LEE'S 1974 RECORD DISTANCES INDICATES THAT THE CORNER WAS ESTABLISHED ON LINE WITH THE SE AND SW CORNERS OF SECTION 4. SINCE THEN THE RECORD SW CORNER OF SECTION 4 WAS FOUND WHICH DIFFERS GREATLY FROM THE CORNER LEE ESTABLISHED. ANGLE FROM N 1/4 COR SEC 4 TO SE COR SEC 4 IS 89-43-12 (REC 89-43-43) AND FROM SE TO SW CORNERS OF SEC 4 IS 180-50-13 (REC 180-00-00).

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location? FOUND C.I. MON. & CARSONITE. DID NOT AGREE WITH BATTERMAN'S 1974 PROCEDURE BUT DID NOT FIND ANY PHYSICAL EVIDENCE TO DISPUTE THE MONUMENT.

D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.

(E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.

I, Donald Barnes, hereby certify that the corner points as identified by the corner code index were, in a field survey on, MAY 1998, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with the regulations and rules as required in the current manual of survey instructions of the United States Department of Interior, Bureau of Land Management.

COUNTY SURVEYOR FILING DATA

Date of computer entry \_\_\_\_\_

Number of included sheets 1  
CORNER CODE

EMBOSS LAND SURVEYOR SEAL

A-E 7.08 REQUIREMENT

E-11

seal  
*Donald Barnes*  
6/18/98

W 1/4 CDR  
SEC 4

N1-23-30E 2616.05

S63-14-16E 5903.54

S44-37-26E 3732.30

FIELD

S 1/4 CDR  
SEC 4

XXXXXX

S89-07-21E 2685.72

S82-05-06E 2350.42

SW CDR  
SEC 4

SE CDR  
SEC 4

S89-57-33E 2649.42

FD C.I. /  
CARBONITE POST  
NO E/W FENCE

S3-30-27E 2673.61

S12-8-58E 2442.28

XXXXXX

N51-40-19E  
4551.57

FD WPL 1  
BAR IN  
E/W FENCE

FIELD

N42-59-23E 3645.66

XXX SHORT SECTION OF FENCE

U.S. HORIZONTAL  
DISK IN CONCRETE  
"CENTRAL AZM."

OBSERVATION SHEET

EMBOSSED SEAL

*Donald Baines*

June 18, 1998

E-11

