Paper weight-110# (minimum)

Black nonfading ink required

Black nonfa LAND **PUBLIC** U.S. **SURVEY**

MONUMENT RECORD			
T. N. R. L. E. 4th P.M. CORNER CODE INDEX A 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 ABC DEFFICIAL STATES OF THE STATES OF	ROCK COUNTY WI IF AVAILABLE ROCK COUNTY COORDINATES PERFERRED North Elev. East Hor. Datum Vert. Datum LATITUDE ELLIPS. HT LONGITUDE NAD83(91) NETWORK ADJ. YR GPS (X) TRAVERSE (X)		
BEARINGS ARE BASED ON:			

		,	7
FIELD BOOK PAGE #	SHEET	OF	_
SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND S	URROUN		
PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.		2110	

PLANNING & ZONING COMMITTEE ADOPTED THIS FORM ON 12/2/1982

PD546

S1/4CORSEC9

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

1833 HARRISON (NOV 3RD) T4N R11E 4TH MER. EAST ON RAND. BET. 9 & 16

1386.00 BROOK 3.3' CRS N

2640.0 TEMPY 1/4 SEC COR.

5235.12 INT. E BDY 9.24' NORTH OF POST LAND 1ST RATE ROLLING PRAIRIE GROWTH GRASS & WEEDS

WEST COR. WEST BET 9 & 16

2617.56 QUARTER SEC COR. {SET A POST AND RAISED A MOUND OF EARTH & SOD

5235.12 SEC COR.

- PORTER TWP RD REC BK 1 PG 12 BEGINNING AT A POINT ON 1858 THE SECTION LINE BETWEEN SECTIONS 21 & 22 1438.80 SOUTH OF THE NE COR OF SEC 21 AT THE TERMINATION OF A ROAD CONTINUING SOUTH AND AT THE INTERSECTION OF A ROAD RUNNING NORTH WESTERLY THROUGH SECTIONS 21 & 22, THENCE NORTH ON THE SEC LINE BETWEEN SECTIONS 21 & 22, 15 & 16, 9 & 10, 11,998.8 TO THE NE COR OF SEC 9. ALSO BEGINNING AT THE NE COR OF THE WEST 1/2 OF THE NW 1/4 OF SEC 15; THENCE WEST ON THE SEC LINE BETWEEN SECTIONS 10 & 15, 9 & 16, 6,600' TO THE SW COR OF SEC 9 AND THE LINES ABOVE DESCRIBED ARE THE CENTER OF HIGHWAYS 66' WIDE AND WE THE SAID SUPERVISORS DO HEREBY DISCONTINUE THE PUBLIC HIGHWAY DISCRIBED AS FOLLOWS: BEGINNING AT THE SE COR OF THE W 1/4 OF SEC 22 AND RUNNING NORTH ON THE LINE OF EIGHTIES THROUGH SAID QUARTER SECTION AND THROUGH SEC 15 AND A PORTION OF SEC 10, UNTIL IT INTERSECTS THE ROAD RUNNING WEST FROM VAN TATTENS BRIDGE THROUGH SEC 10,
- 1964 BATTERMAN VOL 4 PG 2 DUG LARGE HOLE 10X6X3 FD NOTHING AT N 1/4 COR SEC 16
- 1970 COMBS CSM 1-289 STATES NOTHING ABOUT MON. ANGLE 89-53-05 @ SW COR SEC 9 FROM W 1/4 SEC 9 TO S 1/4 COR SEC 9

MY ANGLE 89-52-41 @ SW COR SEC 9 FROM W 1/4 SEC 9 TO S 1/4 COR SEC 9 IS IN HARMONY WITH COMBS ANGLE.

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

NO

D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.

NONE

(E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.

YES. SET SURVEY SPIKE ON LINE & MIDWAY BETWEEN THE SW & SE CORNERS OF SEC 9. THIS IS IN HAMONY WITH N/S FENCE & CENTER OF PVMT.

I, **Donald Barnes**, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Meaument Record is correct and complete to the best of my knowledge and belief.

SHEET 1 OF 2

CORNER CODE J-11

A.E. 7.08 REQUIREMENT

Emboss Nov 5,2009

