

Paper weight-110# (minimum)

Black nonfading ink required

U.S. PUBLIC LAND SURVEY MONUMENT RECORD

For Public Land Survey Corners In:

WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT

T. 4N. R. 12E. 4th P.M.

REV 10/23/2004

USMONREC.DWG

CORNER CODE INDEX

A	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	A
B																										B
C																										C
D																										D
E																										E
F																										F
G																										G
H																										H
J																										J
K																										K
L																										L
M																										M
N																										N
O																										O
P																										P
Q																										Q
R																										R
S																										S
T																										T
U																										U
V																										V
W																										W
X																										X
Y																										Y
Z																										Z

FULTON TWP
ROCK COUNTY WI

IF AVAILABLE
ROCK COUNTY COORDINATES PREFERRED

North _____ Elev. _____

East _____

Hor. Datum _____ Vert. Datum _____

LATITUDE _____ ELLIPS. HT. _____

LONGITUDE _____

NAD83(91) _____ NETWORK ADJ. YR _____

GPS (X) _____ TRAVERSE (X) _____

BASED ON THE FOLLOWING CONTROL:

PLACE MONUMENT SYMBOL AT PROPER LOCATION ON ABOVE INDEX

CORNER MONUMENT

WITNESS MONUMENT

(a)

BEARINGS ARE BASED ON: _____

FIELD BOOK _____ PAGE # _____

SHEET 1 OF 2

SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.

PLANNING & ZONING COMMITTEE ADOPTED THIS FORM ON 12/2/1982

CORNER CODE C-25

FU520 ^

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

1833 (OCT 17) BRINK & MULLETT VAR 8-15 SOUTH ON EAST SIDE
SECTION 1 T4N R12E

297 LEAVE SWAMP
330 TRAIL @ SE
2640 SET QUARTER SECTION POST WHITE OAK 14 S64W
29.7' WHITE OAK 36 N46W 44.22'
3939.54 WHITE OAK 16 IN DIAMETER
5280 SET POST CORNER SECTIONS 1 & 12 WHITE OAK 26
S10W 41.58' WHITE OAK 14 N72W 34.32' LAND
ROLLING SECOND RATE AND THINLY TIMBERED WITH
WHITE BLACK & BUR OAK HICKORY ?

1871 (SEP 11) RUGER MILTON REMON. NORTH ON WEST LINE OF SW
¼ OF SEC 6 ON A VAR 7-15 OFFSET EAST 6.60' AT
2655.84 INTERSECTED ¼ LINE 5.28' EAST OF ¼ COR. FOUND
LARGE STONE AT COR. ALSO FOUND STUMPS OF
BOTH BEARING TREES COR VAR 7-13

NORTH ON WEST LINE OF NW ¼ OF SEC 6 ON A
VAR 7-15 OFFSET EAST 16.50' AT

2658.48 INTERSECTED NORTH BOUNDARY LINE 40.92' EAST
OF COR. FOUND STUMPS OF BOTH BEARING TREES
& ESTABLISHED COR. FROM THEM. COR VAR 7-47
PLACED 6"X6" CUT LIMESTONE

1880 LEE VOL 2 PG 300 FD MON. VAR 4-18 2651.88 TO NE COR
SEC 1, 2628.12 TO CEN SEC 1

1899 BROWN VOL 2 PG 513 MON. STATES NOTHING ELSE

1958 BATTERMAN VOL 3 PG 572 DUG & FD STONE 2' DEEP 16"
LONG 6"X7". 3' E EAST OF N/S FENCE LINE. REF. SAME.

1961 SHIMEALL #13796 FD 6"X6" STONE AT E ¼ COR

1973 SCHROEDER CSM VOL 3 PG 166 STATES NOTHING. 1500.23
EAST OF CENTER OF LAKE ROAD.

1977 BARNES VOL 5 PG 375 FD CONG. NAIL 0.3' DEEP. DID NOT
DIG OR SET MON. BECAUSE OF HAZARDOUS DRIVING
CONDITIONS. SET 3.00 PK TO NORTH & EAST. REFERENCED
SAME. IN MAPLE BEACH RD.

1981 BARNES VOL 6 PG 210 FD PK NAIL & 24" DEEP FD CUT LS.
SET ALUM MON ON TOP OF CUT L.S. IN BEACH RD. 3.00
NORTH TO PK & 3.00 EAST TO PK.

1981 BUCKETT VOL 6 PG 299 2666.50 TO SE COR SEC 1.

1983 BARNES VOL 6 PG 299 SHOWS REC DISTANCES

1983 BARNES REMON. #6794 NO-09-00E 2655.76 TO NE COR SEC
1, SO-09-05E 2666.55 TO SE COR SEC 1

1984 BARNES VOL 6 PG 326 FD ALUM 307,837.86; 2,264,605.92;
SO-49-12E 2666.40 TO SE COR SEC 1, NO-31-10W 2655.62
TO NE COR SEC 1,

1985 BARNES VOL 6 PG 341 STATES NOTHING ABOUT TYPE OF
MON. 2655.77 TO NE COR SEC 1, 2629.95 TO CEN SEC 1,
ANGLE 90-29-19 @ E ¼ COR SEC 1 FROM CEN SEC 1 TO NE
COR SEC 1.

1993 JOHNS #10226 MOUND SITE. CALLS FOR MON BUT STATES
NOTHING ABOUT IT. 2666.41 TO SE COR SEC 1 & ANGLE 90-
38-31 @ SE COR SEC 1 FROM S ¼ COR SEC 1 TO E ¼ COR
SEC 1

2004 LORD "WOODLANDS SUBDIVISION" BK32-673 FD ALUM. NO-
09-05E 2655.80 TO NE COR SEC 1.

2005 LORD BK32-720 FD ALUM. ANGLE 89-09-02 @ NE COR SEC 1
FROM E ¼ COR SEC 1 TO N ¼ COR SEC 1 & 2655.80 TO L.S
@ NE COR SEC 1.

SHEET 1 OF 2

CORNER CODE C-25

Donald James
11/03/2007

FU520

FD ALUM. MON. & REFERENCE MONUMENTS

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED FD ALUM. MON. OVER CUT LIMESTONE.

D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.

NONE

(E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.

NO

I, **Donald Barnes**, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Donald Barnes
Seal

Barnes
Emboss

11/03/2007

SHEET 2 OF 2

CORNER CODE

C-25

A.E. 7.08 REQUIREMENT