

Paper weight-110# (minimum)

Black nonfading ink required

U.S. PUBLIC LAND SURVEY MONUMENT RECORD

For Public Land Survey Corners In:

WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT

T. 4 N. R. 12 E. 4th P.M.

REV 10/23/2004

USMONREC.DWG

CORNER CODE INDEX

	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25
A																									
B																									
C																									
D																									
E																									
F																									
G																									
H																									
J																									
K																									
L																									
M																									
N																									
O																									
P																									
Q																									
R																									
S																									
T																									
U																									
V																									
W																									
X																									
Y																									
Z																									

FULTON TWP

ROCK COUNTY WI

IF AVAILABLE
ROCK COUNTY COORDINATES PREFERRED

North _____ Elev. _____

East _____

Hor. Datum _____ Vert. Datum _____

LATITUDE _____ ELLIPS. HT. _____

LONGITUDE _____

NAD83(91) _____ NETWORK ADJ. YR _____

GPS (X) _____ TRAVERSE (X) _____

BASED ON THE FOLLOWING CONTROL:

PLACE MONUMENT SYMBOL AT PROPER LOCATION ON ABOVE INDEX

CORNER MONUMENT

WITNESS MONUMENT

BEARINGS ARE BASED ON: _____

FIELD BOOK _____ PAGE # _____

SHEET 1 OF 4

SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.

PLANNING & ZONING COMMITTEE ADOPTED THIS FORM ON 12/2/1982

CORNER CODE 2-25

FU633 ^

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

1835 (NOV29) MULLETT NORTH ON EAST SIDE SECTION 1 T3N R12E

2640 SET QUARTER SECTION POST BURR OAK 8
S55W 67.98' W. OAK 12 N49W 66'

5280 SET TEMPY SIX MILE POST
LAND ROLLING SECOND RATE
SCATTERING 2 B & BURR OAKS

1835 MULLETT WEST ON SOUTH SIDE SEC 31 T4N R13E

1067.22 BUR OAK 12

2640 SET 1/4 SECTION POST BUR OAK 14 N84E
58.08' BUR OAK 12 N49W 32.34'

3210.24 BUR OAK 16

5148 INTERSECTED WEST BOUNDARY 374.88' NORTH
OF TEMP POST SET POST AT INTERSECTION COR
BTs 3 & 4N R812 & 13E BUR OAK 12 N74W
16.5' BUR OAK 16 N15 1/2E 36.96' LAND
ROLLING 2ND RATE BUR OAK OPENINGS

1835 (JAN 7) MULLETT & BRINK WEST ON SOUTH SIDE SECTION 36
T4N R12 VAR 8 20 EAST

1828.86 BUR OAK 10

2640 SET 1/4 SECTION POST W. OAK 22 N37W 112.2'
BUR OAK 10 N35E 19.14'?

4486.02 BUR OAK 10

5280 SET POST COR SECTIONS 35 & 36 B. OAK 10
N49W 135.3' B. OAK 12 N86E 9.24' LAND
GENTLY ROLLING 2ND RATE W. B. & BUR OAK

1836 BRINK NORTH EAST SIDE SEC 36 T4N R12E VAR
FOUND BY OBSERVATION 7-45'E

969.54 BLACK OAK 12 IN DIAMETER

2640 SET QUARTER SECTION POST BUR OAK 12 N13
1/2W 29.04' BUR OAK 20 S28 1/2W 82.5'

4180.44 BUR OAK 12 IN DIAMETER

5280 SET POST CORNER SECTIONS 25 & 36 BUR
OAK 16 S14W 14.52' BUR OAK N20W 40.92'
LAND ROLLING SECOND RATE BUR WHITE AND
BLACK OAK RED ROOT & C

1845 JANESVILLE TWP RD REC BK 1 PG 37 ESTABLISH A PUBLIC
HIGHWAY IN SAID TOWN OF THE WIDTH OF 66'. BEGINNING AT
THE NORTHEAST COR OF SEC 1 IN T3N R12E AND RUNNING
THENCE SOUTH 12,507' ON THE LINE BETWEEN RANGES 12 &
13 EAST AND TO THE INTERSECTIONS OF THE ROAD LEADING
FROM HUMES BRIDGE TO MT. ZION; " " " " " "

1845 STORY JANESVILLE TWP RD REC BK 1 PG 36 BEGINNING AT
THE SOUTHEAST COR OF THE TOWN OF FULTON AND AT THE
NORTHEAST COR OF SEC 1 T3 R12 FROM THENCE ALONG THE
EAST BOUNDS OF R12 SOUTHERLY AND SECS 12 & 13 TO
THE NORTHEAST COR OF SEC 24; " " " " " " " " " " " " THIS ROAD IS LAID
33' FROM RIGHT TO THE LEFT CENTER .

1848 PIERCE JANESVILLE TWP RD RECORDS BK 1 PG 93 BEGINNING
AT A POINT ON THE LINE BETWEEN THE AFORESAID TOWNS
WHERE THE OLD ROAD LEAVES THE SAID LINE BETWEEN SEC
3 AND 34, , WEST OF J. WATTERMAN/S HOUSE. NOW FROM
SAID POINT AS PLACE OF BEGINNING RUNNING S84-45W
6,583.56' ON THE TOWN LINE TO WHERE THE OLD TOWN LINE
ROAD INTERSECTS TOWN LINE AGAIN. MAKING ONE MILE 29
RODS. ALSO ON SAME INSTANT FOR THE SAME COMMISSION.
A ROAD RUNNING FROM WHERE THE NORTH AND SOUTH
ROAD CROSSES THE TOWN LINE BETWEEN SEC 4 & 33 ,
PLACE OF BEGINNING. RUN ON THE ABOVE DESCRIBED TOWN
LINE S45-84W 7161' TO A POST, THENCE N81-W 3630';
THENCE S75W 448.8' TO A POST ON TOWN LINE, THENCE
S84-45W 2933.7' ON TOWN LINE TO THE SW COR OF THE
TOWN OF MILTON. THE ABOVE DESCRIBE LINES IS THE
CENTER OF THE ROADS, WHICH IS 66' WIDE.

Donald Barnes

Dec 13 2007

SHEET 1 OF 4
CORNER CODE Z-25

FU633

- 1849 TOWN RD REC BK 1-14 BEGINNING AT THE SOUTH WEST CORNER OF SEC 31 IN THE TOWN OF MILTON AND RUNNING NORTH ALONG SECTIONS 31,30,19 AND 18 AND ON SEC 7 2970' AND ALSO ON THE EAST LINE OF SECTIONS 31,25,24, AND 13 TO A POST THENCE NORTHERLY ALONG SECTION 12 2970' IN THE TOWN OF FULTON TO THE CENTER OF HIGHWAY LEADING FROM WHITEWATER TO MINIERAL POINT SAID HIGHWAY IS LAID 66' WIDE ON THE LINE OF THE TWO TOWNSHIPS, 33' ON EACH SIDE OF THE TOWN LINE AND WE DO FURTHER ORDER THE SAID HIGHWAY""""
- 1860 RUGER VOL 1 PG 133 SET HARD HEAD 24X7X6 2528.46 TO N ¼ COR SEC 6 HARMONY TWP.
- 1866 JANESVILLE TWP RD REC. BK 1 PG 408 COMMENCING AT THE NORTHEAST CORNER OF SECTION IN SAID TOWN OF JANESVILLE AND IN THE CENTER OF THE HIGHWAY RUNNING BETWEEN THE TOWNS OF JANESVILLE AND HARMONY RUNNING THENCE WEST ON THE NORTH LINE OF SAID SECTION 1 5280' TO THE CENTER OF THE HIGHWAY RUNNING BETWEEN SECTIONS 1 AND 2 IN SAID TOWN OF JANESVILLE. THE LINE OF THE SAID SURVEY TO THE CENTER OF THE HIGHWAY WHICH LINE IS THE TOWN LINE OF SAID TOWNS OF JANESVILLE AND FULTON; AND THE SAME IS ESTABLISHED 66' IN WIDTH, 33' ON EACH SIDE OF SAID LINE.
- 1866 JANESVILLE TWP RD REC BK 2 PG 32 COMMENCING AT THE NORTHEAST COR OF SEC 1 IN SAID TOWN OF JANESVILLE & IN THE CENTER OF THE HIGHWAY RUNNING BETWEEN THE TOWNS OF JANESVILLE AND HARMONY, RUNNING THENCE WEST ON NORTH LINE OF SAID SECTION 1 AND 2 IN SAID TOWN OF JANESVILLE.
- 1866 FULTON TWP RD REC BK 1 PG 44 COMMENCING AT THE NORTH EAST CORNER OF SECTION ONE OF THE TOWN OF JANESVILLE AND IN THE CENTER OF THE HIGHWAY RUNNING BETWEEN THE TOWNS OF JANESVILLE & HARMONY RUNNING THENCE WEST ON THE NORTH LINE OF SAID SECTION 1 ONE MILE TO THE CENTER OF THE HIGHWAY RUNNING BETWEEN SECTIONS 1 & 2 IN SAID TOWN OF JANESVILLE. THE LINE OF SAID SURVEY TO BE THE CENTER OF SAID HIGHWAY WHICH LINE IS THE TOWN LINE BETWEEN THE TOWNS OF FULTON & JANESVILLE AND THE SAME IS ESTABLISHED 66' IN WIDTH; 33' ON EACH SIDE OF SAID LINE.
- 1870 RUGER HARMONY REMON. FIELD NOTES. *EAST ON NORTH LINE OF NW ¼ SEC 6 ON A VAR 5-12'*
INTERSECTED QUARTER LINE OF SEC 31 T4 R13
3.96' NORTH OF QUARTER COR
CORR VAR 5-07 CONTINUED EAST ON TOWN LINE FROM SOUTH QUARTER POST OF SEC 31 T4 R13 ON A VAR 4-18'; AT
5165.16' INTERSECTED EAST BOUNDARY LINE 3.3' SOUTH OF NE COR SEC 6 FOUND IRON PIN PLANTED BY SELF AND STUMP OF S.W. BEARING TREE, AND STUMP OF BEARING TREE FOR SE COR OF SEC 31 T4R 13. ESTABLISHED NORTH QUARTER COR OF SEC 6 HARMONY ON THE TOWN LINE AND 2532.92' FROM THE NW COR AND 2632.24' FROM THE NE COR OF SAID SECTION COR VAR 4-22
NORTH ON WEST LINE OF NW ¼ SEC 6 ON A VAR 7-35, AT 3030.72' INTERSECTED NORTH BOUNDARY LINE AT 5.94' EAST OF COR. FOUND REMAINS OF STUMP OF NW BEARING TREE. COR VAR 7-42
PLACED 6"X6" CUT LIMESTONE

Donald Barnes
Dec 13 2007

SHEET 2 OF 4
CORNER CODE Z-25

FU633

- 1871 (AUG16) RUGER MILTON TWP REMON. WEST ON SOUTH LINE OF SE ¼ SEC 31 ON A VAR 4-22 AT
2632.24 INTERSECTED ¼ LINE AT ¼ COR FOUND STUMP OF NW BEARING TREE & WHERE STUMP OF N E BEARING TREE HAD BEEN DUG UP. ESTABLISHED COR. FROM THEM. THE SOUTH ¼ COR OF SEC 31 MILTON IS 32.34' WEST OF THE NORTH ¼ COR OF SEC 6 HARMONY
WEST ON SOUTH LINE OF SW ¼ OF SEC 31 ON A VAR 5-07 AT
- 2500.74 INTERSECTED WEST BOUNDARY LINE AT COR. STONE AT COR. ERECTED IN SURVEY OF THE TOWN OF HARMONY.
NORTH ON WEST LINE OF SW ¼ OF SEC 31 ON A VAR 6-20 AT
- 2656.83 INTERSECTED ¼ LINE AT ¼ COR. FOUND STAKE SURROUNDED BY HARD HEAD STONES AT COR. ALSO FOUND REMAINS OF STUMPS OF BOTH BEARING TREES.
NORTH ON WEST LINE OF N.W. ¼ OF SEC 31 ON A VAR 6-20 AT
- 2662.66 INTERSECTED NORTH BOUNDARY LINE AT COR. FOUND HARD HEAD STONE ON COR. ALSO FOUND WHERE THE STUMPS OF THE 4 BEARING TREES HAD BEEN DUG OUT
- 1872 LEE VOL 2 PG 93 FD MON VAR 6-50 2623.5 TO N ¼ COR SEC 1 JANESVILLE TWP
- 1895 BROWN VOL 2 PG 491 CALLS FOR BUT DOES STATE TYPE OF MON. 2504.21 TO S ¼ COR SEC 31
- 1947 SUNNY #1478 CALLS FOR COR BUT STATES NOTHING ABOUT MON. 2632.X TO S ¼ COR SEC 36, 2651.6 TO E ¼ COR SEC 36
- 1960 BATTERMAN VOL 4 PG 79 FD CUT STONE MON NOTE: RE-REFERNCED IN VOL 4 PG 472.
- 1960 BATTERMAN VOL 4 PG 82 FD CUT STONE MON. SEE VOL 4 PG 79
- 1965 LEE CSM VOL 1 PG 120 STATES NOTHING ABOUT NOTHING ABOUT MON.
- 1965 LEE #2171 STATES NOTHING ABOUT MON.
- 1968 LEE CSM VOL 1 PG 181 STATES NOTHING ABOUT MON.
- 1970 BATTERMAN VOL 4 PG 472 SET R/R SPIKE OVER NW COR SEC 6 3-13. REFER. MON. NOTE: THIS IS A RE-REFERENCE OF COR. ON VOL 4 PG 79
- 1970 COMBS CSM VOL 1 PG 310 STATES NOTHING ABOUT MON
- 197? HURD MAPPING FOR CITY OF JANESVILLE #6269, #6270, #6271, #6272, & #6268 STATES NOTHING ABOUT MON. 278,637.408; 2,264,923.788 NAD27
- 1974 COMBS CSM VOL 4 PG 104 STATES NOTHING ABOUT MON.
- 1977 BARNES VOL 5 PG 317 FD PK & TIES.
- 1978 HURD MAPPING VOL 5 PG 517 278,637.408; 2,264,923.788
- 1981 LEE #2181 C.I. MON
- 1983 BARNES Z-1 FD PK. 0.1' DEEP. & R/R SPIKE 1' DEEP. REPLACED WITH POLY. REF. SAME.
- 1983 BARNES REMON #6794 S87-59-03E 2509.74 TO S ¼ COR SEC 31 MILTON TWP, S87-59-02E 2541.89 TO N ¼ COR SEC 6 T3N R13E

SHEET 3 OF 4
CORNER CODE Z-25

Donald Barnes
12/13/07

FU633

1988 COMBS VOL 13 PG 273 STATES NOTHING ABOUT MON
1989 SCHROEDER VOL 13 PG 495 STATES NOTHING ABOUT MON
1991 COMBS #11761 ALUM. 2619.46 TO N 1/4 COR SEC 1
JANESVILLE TWP
1992 COMBS CSM VOL 15 PG 361 POLY MON 2619.46 TO N 1/4 COR
SEC 1 JANESVILLE TWP
1992 SCHROEDER CSM VOL 15 PG 504 STATES NOTHING ABOUT
MON
1995 COMBS VOL 18 PG 450 ALUM MON 2541.92 TO S 1/4 COR SEC
31 MILTON TWP
2000 LATHROP CSM VOL 23 PG 310 ALUM MON N89-46-50W TO
ALUM AT N 1/4 COR SEC 1 & SOUTH ALONG EAST LINE OF NE
1/4 OF SEC 1 JANESVILLE TWP
2002 COMBS CSM VOL 25 PG 276 ALUM. MON. 2619.36 TO N 1/4
COR SEC 1 JANESVILLE TWP.

FD ALUM. MON & REFERENCE MONUMENTS.


C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED FD MONUMENTS.

D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.

(E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.

I, **Donald Barnes**, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Seal


Emboss
Barnes

12/13/07

SHEET 4 OF 4

CORNER CODE **Z-25**

A.E. 7.08 REQUIREMENT SHEET 1 OF