Paper weight-110# (minimum)

Black nonfading ink required

U.S. LAND **SURVEY PUBLIC** MONUMENT RECORD

| For Public Land Survey Corners In: T. £N. R. £E. 4th P.M. | WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT REV 10/23/2004 USMONREC.DWG |
|--|---|
| CORNER CODE INDEX A 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 2 B C D D D D D D D D D D D D D D D D D D | B ROCK COUNTY WI C IF AVAILABLE ROCK COUNTY COORDINATES PERFERRED F G H North Elev K East L M N Hor. Datum Vert. Datum |
| R S T U V X Y Z 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 2- PLACE MONUMENT SYMBOL AT PROPER LOCATION ON ABOVE INDEX | R S LONGITUDE V V NAD83(91) V V S S S S S S S S S S S S S S S S S |
| (a) CORNER MONUMENT | WITNESS MONUMENT |

SHEET FIELD BOOK . PAGE # SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH. PLANNING & ZONING COMMITTEE ADOPTED THIS FORM ON 12/2/1982

BEARINGS ARE BASED ON:___

CORNER CODE <u>E</u> - 25

FU533^

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

1833 (OCT 17) BRINK & MULLETT VAR 8-15 SOUTH ON EAST SIDE SECTION 1 T4N R12E

297 LEAVE SWAMP

330 TRAIL @ SE

2640 SET QUARTER SECTION POST WHITE OAK 14 S64W 29.7' WHITE OAK 36 N46W 44.22'

3939.54 WHITE DAK 16 IN DIAMETER

5280 SET POST CORNER SECTIONS 1 & 12 WHITE DAK 26 S1DW 41.58' WHITE DAK 14 N72W 34.32' LAND ROLLING SECOND RATE AND THINLY TIMBERED WITH WHITE BLACK & BUR DAK HICKORY?

1833 (OCT 17) BRINK & MULLETT SOUTH ON EAST SIDE SECTION 12
4N R12

627 ROCK RIVER 396' @ SW SET POST ON RIGHT BANK WHITE OAK 10 N18 1/2W 102.3' BLACK OAK 10 N56E 129.36' LAND & SAME AS LAST MILE

1834 (MAR) HARRISON EAST ON RANDOM BET SECS 1 & 12

2640 TEMPY 1/4 SEC. COR.

5280 INT. E BDY AT POST. LAND ROLLING 2ND RATE THE SAID BEING THE HIGHLANDS ADJACENT THE RIVER & COVERED BURR TIMBER

WEST COR WEST

2640 SET POST FOR QUARTER SEC COR. BEARINGS {W.O. 18 S18W 54.12' W.O. 20 N48W 62.7' W.O. 18 W.O. 20}MARKED

5280 SEC COR.

1834 (MAR 31) HARRISON EAST BETWEEN SECS 6 & 7 VAR 8-40E T4N R13E 14TH MER.

538.56 TRAIL N.W.

940.5 RED 0 20 IN DIAM.

990 TO A RANGE OF APPARENTLY ARTIFICIAL MOUND BEARING N.E.

1435.5 RED 0 12

2178 TRAIL N & ENTER BOTTOM

2310 INT. RIGHT BANK OF ROCK RIVER SET MEANDER POST {BUR O 12 S69W 162.36' BURR O 8 N4W 161.7' LAND ROLLING 2ND RATE TIMBER BURR RED & W.O. UNDERGROWTH SCRUBS GRASS & WEEDS

1836 (JULY) BRINK NORTH EAST SIDE SECTION 12 4N 12E

1358.28 BLACK OAK 18 IN DIAMETER

2640 SET QUARTER SECTION POST BUR OAK 30 S22W 87.78' WHITE OAK 7 N37W 60.06'

3102 ARMY TRAIL @ NE

3747.48 INTERSECT LEFT BANK OF ROCK RIVER SET POST BUR OAK 16 S3W 505.56' BUR OAK 18 S17E 600.6' LAND & C SAME RIVER 907.5' WIDE RUNNING SOUTH WEST

1854 TWP RD BK 1 PG 30 BEGINNING ON THE EAST LINE OF THE TOWN OF FULTON ON THE CORNER OF SECTIONS #1 & #12 IN SAID TOWN AND RUNNING THENCE; WEST ALONG AND ON THE LINE BETWEEN SAID SECTIONS #1 & #12 2013', INTERSECTING A PUBLIC ROAD. THE SAID COURSE AND DISTANCE BEING THE CENTER LINE OF SAID ROAD. """"" ROAD TO BE A PUBLIC HIGHWAY 66' WIDE """"".

1871 (SEP11) RUGER MILTON REMON. NORTH ON WEST LINE OF SW
1/4 OF SEC 6 ON A VAR 7-15 OFFSET EAST 6.60' AT

2655.84 INTERSECTED 1/4 LINE 5.28' EAST OF 1/4 COR. FOUND LARGE STONE AT COR. ALSO FOUND STUMPS OF BOTH BEARING TREES COR VAR 7-13

NORTH ON WEST LINE OF NW 1/4 OF SEC 6 ON A VAR 7-15 OFFSET EAST 16.50' AT

PAGE 1 OF 3

CORNER CODE E-25

Penled Brenes 11/06/07 FU533

2658.48

- INTERSECTED NORTH BOUNDARY LINE 40.92' EAST OF COR. FOUND STUMPS OF BOTH BEARING TREES & ESTABLISHED COR. FROM THEM. COR VAR 7-47
- 1871 (SEP11) RUGER MILTON TWP REMON. NORTH ON WEST LINE

 OF NW 1/4 OF SEC 7 ON A VAR 6-05 AT
 - 1104.84 INTERSECTED MEANDER LINE 9.90' EAST OF COR. FOUND STUMPS OF BOTH BEARING TREES & ESTABLISHED MEANDER COR. FROM THEM. COR VAR 6-35

AT MEANDER COR. ON NORTH BANK OF ROCK RIVER. WEST LINE OF SEC 7 FOUND OLD STAKE AT COR. ALSO FOUND NW BEARING TREE & STUMP OF NE BEARING TREE. NORTH ON WEST LINE OF NW 1/4 OF SEC 7 ON A VAR 6-30 OFFSET EAST 10.56' AT

- 630.96 INTERSECTED NORTH BOUNDARY LINE 11.88' EAST OF COR. FOUND OLD STAKE AT COR. ALSO FOUND STUMP OF N.W. BEARING TREE & WHERE STUMP OF S.E. BEARING TREE HAD BEEN DUG UP. COR VAR 6-37
- 1871 (SEP11) RUGER MILTON TWP REMON. EAST ON SOUTH LINE OF SW 1/4 OF SEC 6 ON A VAR 7-10 AT
 - 2276.34 INTERSECTED MEANDER LINE 104.94' SOUTH OF MEANDER COR. FOUND OLD STAKE AT COR. ALSO FOUND STUMP OF S.W. BEARING TREE & WHERE STUMP OF N.W. BEARING TREE HAD BEEN DUG UP COR VAR 9-48

PLACED 6"X6" CUT LIMESTONE

- 1899 BROWN VOL 2 PG 513 MON. STATES NOTHING ELSE
- 1908 MABBETT "KOSHONONG RETREAT SUB" BK 7 PG 26 SQUARE STONE ON LINE WITH EAST EDGE OF SUB. 20.00' NORTH OF NE COR OF LOT 12. LOT 12 IS 100' DEEP AND FACES N/S RD. SOUTH 633.5 TO SQUARE STONE AT MP.
- 1940 SUNNY VOL 3 PG 440 FD 6X6 CUT STONE MON 6" ABOVE GROUND. 9' NORTH OF CENTER LINE OF E/W GRAVEL RD, 1.5' NORTH OF NORTH EDGE OF RD. REF. SAME. 50.11 SW TO NE COR OF SHADOW HILL COTTAGE.
- 1958 BATTERMAN VOL 3 PG 572 6"X6" EXISTING STONE MON. 13' SOUTH OF NORTH R/W LINE TO THE EAST, 35' SOUTH OF NORTH R/W LINE TO THE WEST, 13 SOUTH OF 1" EXISTING PIPE. 20' NORTH OF CENTER LINE PVMT, SHOWS DISTANCES TO EXISTING MONUMENTS.
- 1961 SHIMEALL #13796 FD STONE AT SE COR
- 1961 BATTERMAN SEP 12TH #1191 FD CUT STONE MONUMENT AT NE COR SEC 12 2647.69 TO N ¼ COR SEC 12. ANGLE 89-47-10 @ N ¼ COR SEC 12 FROM N/S CENTER LINE OF SEC 12 TO NE COR SEC 12. N ¼ COR SEC 12 ON LINE WITH NW & NE CORNERS OF SEC 12, ANGLE 89-27-20 @ NE COR SEC 12 FROM EAST LIST SEC 12 TO NW COR SEC 12
- 1961 BATTERMAN DEC 4^{TH} #1165 FD STONE MON 2644.0 TO N $\frac{1}{4}$ COR SEC 12, N $\frac{1}{4}$ COR SEC 12 IS NOT ON LINE BETWEEN NW & NE COR SEC 12. ANGLE @ N $\frac{1}{4}$ COR SEC 12 FROM NE TO NW CORNERS SEC 12 IS 180-28-00, ANGLE NE COR SEC 12 FROM EAST LINE SEC 12 TO N $\frac{1}{4}$ COR SEC 12 IS 89-13-20
- 1961 BATTERMAN VOL 4 PG 113 FD CUT STONE. S89-13-20W 2644.00 TO N $\frac{1}{4}$ COR SEC 12, EAST LINE OF SEC 12 IS BEARING SOUTH.
- 1961 LEE CSM VOL 1 PG 141 STATES NOTHING ABOUT MON. 2644.0 TO N $^{1\!\!/_{\!\!4}}$ COR SEC 12 & ANGLE OF 180-28-00 @ N $^{1\!\!/_{\!\!4}}$ COR SEC 12 FROM NE TO NW CORNERS OF SEC 12.
- 1977 BARNES VOL 5 PG 376 SET ALUM. & REF. SAME. 3' SOUTH OF NORTH PVMT EDGE OF MALLWOOD DR.
- 1980 NORTHROP #1193 BERNTSEN ALUM. MON. OF REC. 2645.11 TO N $\frac{1}{4}$ COR SEC 12
- 1981 BARNES VOL 6 PG 204 FD ALUM. MON.

 11/06/07

PAGE 2 OF 3

E7.5

FU533

- 1983 BARNES VOL 6 PG 299 STATES NOTHING ABOUT MON. SHOWS TRAVERSE LINE TO MEANDER CORNER TO THE EAST. 2666.40 TO E 1/4 COR SEC 1, S88-31-14W 2645.01 (RUGER REMON. 2276.34) TO S 1/4 COR SEC 1
- 1983 BARNES REMON. #6794 NO-09-05W 2666.55 TO E 1/4 COR SEC 1, S89-49-40E 2285.46 TO S $\frac{1}{4}$ COR SEC 6 MILTON TWP
- 1984 BARNES VOL 6 PG 326 305,171.73; 2,264,644.10 NO-49-12W
- 1984 WEIR #6396 ALUM. MON. 305,171.73; 2,264,644.10 2644.97 TO S ¼ COR SEC 1.
- 1987 LEE #12799 FD ALUM. MON.
- 1988 SCHROEDER CSM VOL 13 PG 180 STATES NOTHING ABOUT MON.
- 1988 DOT #15031 & 11167 STH 59 ALUM. MON. 305,169.80; E/W 2,264,641.41 588-32-40W 2645.09 TO S $\frac{1}{4}$ COR SEC 1
- 1993 HALVERSON CSM VOL 17 PG 51 FD ALUM. 2645.03 TO S 1/4 COR SEC 1.
- 1993 JOHNS #10198 FD ALUM. 2645.20 TO N 1/4 COR SEC 12, SO-17-02W 593.30 TO 2" SQUARE BRASS MON, & ANGLE 89-17-29 @ NE COR SEC 12 FROM 2" SQUARE BRASS MON TO N $\frac{1}{4}$ COR SEC 12
- 1993 JOHNS #10226 NO-12-24E 2666.41 TO E 1/4 COR SEC 1, S89-33-53W 2644.99 TO N ¼ COR SEC 12, & ANGLE 90-30-31 @ NE COR SEC 12 FROM N 1/4 COR SEC 12 TO E 1/4 COR SEC 1
- 2000 HALVERSON #7831 HARRISON/BERNTSEN 2645.03 TO S 1/4 COR SEC 1
- 2000 LEUENBERGER #7696 FD ALUM.
- 2005 WILLIAMSON CSM VOL 28 PG 257 FD ALUM 2644.96 TO FD SURVEY SPIKE @ S 1/4 COR SEC 1

FD ALUM. MON. & REFERENCE MONUMENTS.

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED FD MON.

- D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.
- (E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.

I, **Donald Barnes**, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

SHEET 3 OF 3

CORNER CODE E-25

A.E. 7.08 REQUIREMENT