Paper weight-110# (minimum)

Black nonfading ink required

## U.S. PUBLIC LAND SURVEY MONUMENT RECORD

. 1_	2 3 4 5			ODE IN		1 22 23 24 25 <sub>A</sub>	TWP
B C	6	5	<b>X</b>	3	7	A B	ROCK COUNTY WI
D E F						E F	IF AVAILABLE ROCK COUNTY COORDINATES PERFERRED
G H J		\$			**	H	North Elev
K L	8	1	76	15		A I	East
M N						N	Hor. Datum Vert. Datum
P Q	10	120		27	3		LATITUDE ELLIPS. HT
R S T	30	29	28	2	76	S	LONGITUDE
v						V V	NAD83(91)NETWORK ADJ. YR
X X	3	7	2	30	3	30 X	GPS (X) TRAVERSE (X)
z L	PLACE M	IONUMEN' N ON AB	r symbol ove inde	X AT P	ROPER	1 22 23 24 25	BASED ON THE FOLLOWING CONTROL:
(a	)	<b>♦</b> C	CORNER	MONUN	MENT	0	WITNESS MONUMENT

BEARINGS ARE BASED ON:\_\_\_\_\_

,	
	1
FIELD BOOK PAGE #	SHEET OF
SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUME	NT AND SURROUNDING
PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DE	EPTH.

## FU565^

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

1834 APR HARRISON NORTH BETWEEN SECS 20 & 21 PG 20

4884 LEAVE ROCK RIVER & SET MEANDER POST ON RIGHT BANK OF SAME {W OAK 12 N7E 63.36' WHITE OAK 18 N33W 49.5'

5280 SET COR TO SECS 16,17,20,&21 RED OAK 18 S41E 7.92' RED OAK 12 S29W 14.52' WHITE OAK 20 N58W 47.52' WHITE OAK 12 N37E 33' LAND ROLLING  $2^{ND}$  RATE TIMBER MOSTLY WHITE OAK. GRASS & WEEDS.

1834 APR HARRISON EAST BET. SECS 16 & 21 PG 20

346.5 INT. RIGHT BANK OF ROCK RIVER BEARING TO MEANDER POST {RED OAK 12 N13W 89.1' RED OAK 10 S73W 94.38' LAND SAME

1834 APR HARRISON NORTH BETWEEN SECS 16 & 17 PG 21

1386 TRAIL N.E.

2640 QUARTER SEC. COR. {RED 0. 10 S69E 16.5' RED 0 12 N74W 68.64'

3851.76 WO 20 IN DIAM

4720.98 RED 0 12 IN DIAM

5280 COR TO SECS 8,9,16,17 {BURR O 24 S30W 93.26'
RED OAK 12 N80E 64.02' BURR O 12 N24W
144.54' & BURR O 10 S10E 81.84' LAND LEVEL 2<sup>ND</sup>
RATE TIMBER RED BURR & WHITE GRASS & WEEDS

1834 APR HARRISON EAST ON RANDOM BET. 17 & 20 PG 24 369.6 TRAIL N.E.

2640 TEMPY 1/4 SEC COR.

5291.88 INT. E. BOUNDARY 13.2' N.  $\square$  POST LAND ROLLING  $2^{\text{ND}}$  RATE TIMBER RED BURR & WHITE  $\square$ AK. GRASS & WEEDS

WEST COR. WEST BET. 17 & 20

2645.94 QUARTER SEC. COIR. {RED OAK 12 N35W 11.88' RED OAK 18 S70E 15.18'} {RED OAK 12 RED OAK 1} MARKED

5291.88 SEC COR

1836 JULY BURNHAM NORTH BETWEEN SECS 20 & 21 PG 47

1716 LEFT PRAIRIE

4290 TRAIL CROSS NE & SW

4342.8 TO LEFT BANK R. RIVER

4934.16 INT. RIGHT BK 27.06' EAST OF MP FIRST RATE DRY PRAIRIE AND BUR & W.O. OPENINGS

SOUTH CORRECTED BETW. SEC 20 &21

600.6 SET MP ON LEFT BANK R. RIVER YELLOW OAK 8 S54 ½E 9.9' WHITE OAK 16 S19 ½W 35.64' NO STATIONS

2294.16 SET 1/4 SEC POST W. OAK 24 S57W 30.36 BUR OAK 16 N71E 21.12' BUR OAK 10 IN DIA.

1836 JULY BURNHAM WEST RANDOM BETW SEC 16 & 21 PG 44

4158 TRAIL @ NE & SW

4237.2 LEFT BANK ROCK RIVER

4765.2 INT RIGHT BANK @ M. POST, FIRST RATE W & BUR OAK OPENINGS

EAST CORRECTED BETW SECS 16 & 21

528 SET M.P. ON LEFT BANK W. DAK 8 N11E 15.84' BUR DAK 8 S21W 58.74' NO STATIONS

2125.2 SET 1/4 SEC POST BUR DAK 10 N1DE 7.92' BUR DAK 12 S49E 16.5'

4765.2 TO CORNER

184? TOWNSHIP RD RECORDS VOL 6 PG 333. 194.04' SOUTH OF E/W RD, 2640 TO W  $\frac{1}{4}$  COR SEC 16.

SHEET 1 OF 4

CORNER CODE N-9(1)

Dorald Barrey 1/08/07

- 1844 STEBBINS TWP RD REC BK1 PG 4 SURVEY OF A RD IN THE TOWN OF FULTON LEADING FROM THE NORTH LINE OF ROCK COUNTY TO THE INDIAN FORD ON ROCK RIVER MADE APRIL 19<sup>TH</sup> 1844. BEGINNING AT THE TERMINATION OF A RD LAID IN THE COUNTY OF DANE AT THE ¼ POST ON THE SOUTH LINE OF SOUTH 32 T5N R12E, THENCE S 2 ½E 5280' TO ¼ POST SOUTH LINE OF S. 5 T4N R12E; THENCE SOUTH 1 EAST 3036' TO STAKE SET, POST OF BURR OAK, SOUTH 27W 6468', THENCE S32E 4966.5' TO A PT ON THE EAST LINE OF S 17, 662.64' NORTH OF THE ¼ POST, THENCE S½E 3302.64' TO THE SE COR OF S 17 AND THE WHOLE LENGTH OF THE ROAD IS 16, 585.14'. COURSES GIVEN ACCORDING TO THE TRUE MERIDIAN. VARIATION OF NEEDLE 7- 30 HARRISON STEBBINS CO. SURVEYOR.
- 1845 STEBBINS TWP RD BK 1 PG 6 BEGINNING AT THE NE COR OF SEC 17 T4N R12E; THENCE SOUTH ON THE SECTION LINE 1977.36' TO A POINT ON SAID LINE 662.64' NORTH OF THE 1/4 POST. THE LENGTH OF SAID ROAD IS 1977.36'. COURSE GIVEN ACCORDING TO THE TRUE MERIDIAN.
- 1848 DEPARTMENT OF LANDS "STATE SCHOOL KRAFT" #8591 STATES NOTHING ABOUT MON. 5148 FROM SW TO SE CORNERS SEC 16
- 1858 TWP RD BK 1 PG 38 BEGINNING AT THE SW COR OF SEC 16, IN THE TOWN OF FULTON, AND RUNNING; THENCE NORTH 660' ALONG THE SECTION LINE TO AN AVENUE; THENCE RUNNING EAST ALONG SAID AVENUE 330' TO A STAKE IN THE CENTER OF ANOTHER AVENUE; THENCE RUNNING NORTH 47 ½ EAST 1798.5' ALONG SAID AVENUE; THENCE RUNNING SIX (6) WEST 577.5'; THENCE RUNNING NORTH 3 ½ WEST 2656.5' TO THE N.E. COR OF NW ¼ NW ¼ OF SEC 16 IN SAID TOWN OF FULTON. THE SAID COURSE AND DISTANCE BEING THE CENTER LINE OF SAID ROAD """ THE ABOVE DESCRIBED ROAD TO BE A PUBLIC HIGHWAY 66' WIDE""
- 1875 RUGER VOL 2 PG 197 FD L.S. SET COR. ALSO FD WHERE B.T. STUMPS HAD BEEN DUG OUT. EAST 346.5' TO MP. FD WHERE BT STUMPS HAD BEEN DUG UP. DROVE IRON PIN. LONG ONE. SURROUNDED BY 3 HH. SOUTH 396' TO MP. FD STUMPS OF STUMPS OF NW BT HAD BEEN DUG UP. DROVE STAKE SURROUNDED BY 3 HH.
- 1875 RUGER VOL 2 PG 199 2654.19 TO W 1/4 COR SEC 16.
- 1888 ? ROAD RECORDS VOL 6 PG 333 FROM A BOOK IN COUNTY CLERK'S VAULT SHOWS THE FOLLOWING: STARTING FROM A POINT ON THE WEST LINE OF SW 1/4 OF SEC 16 WHICH IS 194.06' FROM THE SW COR SEC 16 & 2445.96 FROM THE W 1/4 COR SEC 16 THENCE N34W 1716', THENCE N55 1/2 W 2024.22 TO THE N 1/4 COR SEC 17, THENCE NORTH 10,560' TO THE N 1/4 COR SEC 5.
- 1886 RUGER VOL 2 PG 275 FD WHERE BOTH BT STUMPS HAD DECAYED IN GROUND. SET IN PLACE OF SW BT STUMP A FLAT SPLIT WHITE HH STONE 21X8X5. ALSO SET IN PLACE OF SE BT STUMP A FLIT SPLIT HH STONE (TRIANGLE) 20X16X4. ALSO FD LIMESTONE SET ON END AT COR SURROUNDED BY HH STONES. VAR 6-07 2650.10 TO N 1/4 COR SEC 20, VAR 6 414.15' TO MP
- 1927 ELY "SUNNYVIEW PARK" BK 10 PG 44 33' NORTH OF P!PE IN FRONT LINE OF LOT 3. STATES NOTHING ABOUT MON.
- 1933 SUNNY VOL 3 PG 231 FD STONE MON. SURROUNDED BY 4 STONES SET BY RUGER. SET 1 1/4" IRON PIPE ON TOP OF SAME.
- 1940 SUNNY VOL 3 PG 460 FD LIMESTONE MON. SURROUNDED BY 4 HH 20" LONG. SET 1 1/4" CAPPED IRON PIPE ON TOP. REFERENCED SAME TO TREES. SOUTH 30.7' TO IRON PIPE.

SHEET 2 OF 4 CORNER CODE N-9(1)

Durls Bares 11/08/67 FU565

- 1940 SUNNY "TEUBERT & O'CONNORS" BK 12 PG 29 NORTH LINE OF SEC 20 IS IN MIDDLE OF CTH M, TIE TO MANY LOT CORNERS.
- 1960 BATTERMAN VOL 4 PG 13 5287.08' TO NW COR SEC 20.
- 1961 BATTERMAN VOL 4 PG 93 29.84' TO IRON PIPE TO SOUTH. 2 PIPES SOUTH ABOUT 1.63' APART. SOUTH 395.25 TO MP. FD DECAYED STAKE SURROUNDED BY 3 HH DESCRIBED IN SURVEY BY RUGER IN VOL 2 PG 197. RESET 3/4"X4' IRON PIN WHERE OLD STAKE WAS FD. AT MP.
- 1961 BATTERMAN #14163,10294,&10295 1" PIPE. ANGLE 89-49-20 @ NE COR SEC 20 FROM MP TO NORTH LINE OF NE  $\frac{1}{4}$  SEC 20
- 1962 ELY #7684 "STATE SCHOOL KRAFT" SUB. FD IRON STAKE.
  2484.88 TO S ¼ COR SEC 16, 2660.0 TO W ¼ COR SEC 16, &
  ANGLE 90-24 @ SW COR SEC 16 FROM W ¼ COR SEC 16 TO S
  ¼ COR SEC 16.
- 1962 ELY VOL 6 PG 42 2484.88 TO N 1/4 COR SEC 21.
- 1962 ELY #7682 "STATE SCHOOL KRAFT" SUB STATES NOTHING ABOUT MON.
- 1962 SANDSNES #7670 STATE SCHOOL KRAFT. IRON STAKE FOUND 2660.00 TO W  $^{1}$ 4 COR SEC 16, 2484.88 TO S  $^{1}$ 4 COR SEC 16, & ANGLE 90-24 FROM W  $^{1}$ 4 COR TO S  $^{1}$ 4 COR SEC 16.
- 1963 ELY #7683 "STATE SCHOOL KRAFT" SUB. STATES NOTHING ABOUT MON. NORTH 665.0' TO MON IN CENTER OF RD
- 1968 BATTERMAN VOL 4 PG 488 FD 1 ½" PIPE BY SUNNY BENT OVER. REPLACED JULY 2 1965 AT SOUTH EDGE OF BLACK TOP.SW 43.15', NW 62.17', NE 56.52' TO IRON PIPES.
- 1973 LEE CSM VOL 3 PG 93 FD PIPE.
- 1975 SANDSNES #7680 "STATE SCHOOL KRAFT" SUB FD IRON STAKE. NORTH 2665.00 TO STAKE IN CENTER OF RD.
- 1976 BARNES VOL 5 PG 97 2483.68' TO N 1/4 COR SEC 21 & 2745.63' TO W 1/4 COR SEC 21
- 1980 BARNES VOL 6 PG 42 NO-33-38E 2656.20' TO W 1/4 COR SEC 16.
- 1980 NORTHROP CSM 10 PG 21FD 1" PIPE OF REC 2656.20 TO W  $\frac{1}{4}$  COR SEC 16.
- 1981 AERO-METRIC PHOTO CONTROL NGVD 29 ELEVATION 796.48'
- 1981 BARNES VOL 6 PG 202 FD 1" IRON PIPE. REPLACED WITH ALUM. MON. FD 3 TIES & SHOWS RECORD DISTANCES.
- 1981 AERO-METRIC PHOTO CONTROL NGVD 29 ELEVATION 796.48'
- 1983 NORTHROP #9007 "STATE SCHOOL KRAFT" SUB TIES TO MANY LOT CORNERS. FD ?
- 1984 SANDSNES #13114 "STATES SCHOOL KRAFT" SUB. FD ALUM
- 1987 BARNES #12826 FD ALUM. 2483.28 TO N 1/4 COR SEC 21
- 1991 SCHROEDER CSM VOL 15 PG 100 & 262 CREATED LOTS LONG SOUTH LINE OF SE 1/4 SEC 17. STATES NOTHING ABOUT MON.
- 1994 SCHROEDER #9936 CALLS FOR COR BUT STATES NOTHING ABOUT TYPE OF MON.
- 1994 SCHROEDER #9935 CALLS FOR COR BUT STATES NOTHING ABOUT TYPE OF MON.
- 1995 LATHROP CSM VOL 18 PG 123 FD 1" PIPE 2656.20 TO W 1/4 COR SEC 16.
- 1998 NORTHROP CSM VOL 22 PG 83 FD 1" PIPE 2656.20 TO W  $\frac{1}{4}$  COR SEC 16.

SHEET 3 OF 4 CORNER CODE N-9(1)

Word Barnes 11/08/07

## FU565

- 1999 SLLL CSM VOL 22 PG 213 CALLS FOR IRON PIPE. 2656.20 TO ALUM 0 W  $\frac{1}{4}$  COR SEC 16.
- 2002 BARNES #14164 FD ALUM. 2483.28 TO N  $\frac{1}{4}$  COR SEC 21
- 2002 BARNES N-9 & N-11 FD ALUM. MON. & 3 REFERENCE TIES. ACCEPTED FOUND PERPETUATED ALUM. MON. 313,133.13N/S; 474,785.26E/W, 5' NORTH OF SOUTH PVMT EDGE, ON LINE WITH CENTER N /S PVMT, S89-05-51E 2483.30 TO DISK IN MON BOX @ N  $\frac{1}{4}$  COR SEC 21.
- 2004 BARNES CSM VOL 28 PG 76 FD ALUM. EASTERLY 229.39 TO MP.
- 2004 COMBS CSM VOL 28 PG 154 FD ALUM. 2483.14 TO DISK IN CONC. @ N  $\frac{1}{4}$  COR SEC 21.

## FD ALUM. MON.

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED FD ALUM.

Donal's Remissiones 11/08/07

D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.

IT WAS IMPOSSIBLE FOR HARRISON IN APR. 1834 TO RUN THE WEST LINE OF SEC 21 FROM THE SW COR OF SEC 21 BECAUSE BURNHAM ESTABLISHED THE SW COR OF SEC 21 TWO YEARS LATER IN JULY 1836.

- (E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.
- I, **Donald Barnes**, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

SHEET 4 OF 4

CORNER CODE N-9(1)

A.E. 7.08 REQUIREMENT