

Of a Survey on Section 9, 16 T 3 R 14 E. of the 4 P. M. in JOHNSTOWN Township

Rock County, Wisconsin, made JUNE the 7 19 79

I hereby certify that the following is a correct record of said survey as made by me.



*Ronald James*  
County Surveyor.

W1/4 COR SEC 16

THE CORNER AND PIPES WERE DESTROYED BY ROAD CONSTRUCTION IN 1975. SET ALUM. MON. I PROJECTED THE 1/16th CORNER AND SET THE W1/4 CORNER ON THIS LINE AT SINGLE PROPORTIONATE DISTANCE.

SW COR SEC 16

THE CORNER AND REFERENCE PIPES WERE DESTROYED BY ROAD CONSTRUCTION. I RE-ESTABLISHED THE CORNER FROM CSM VOL 2 PAGE 253. SET ALUM MON.

MICROFILMED

E 1/4 COR SEC 16

THE OCCUPATION IS IN HARMONY WITH RECORDED DISTANCES. SET CAST IRON MONUMENT.

SE COR SEC 9

OCCUPATION IS IN HARMONY WITH RECORD DISTANCES. SET ALUM MON.

E1/4 COR SEC 9

FOUND CONCRETE POST +2 SQUARE AND 3' HIGH. SET PK IN THE MIDDLE OF THE TOP. THIS IS IN HARMONY WITH RECORD DISTANCES.

NE COR SEC 9

FOUND CONCRETE POST +2' ROUND AND 3' HIGH. SET PK IN THE CENTER OF THE TOP. THIS IS IN HARMONY WITH RECORD DISTANCES.

N 1/4 COR SEC 9 FD 3/4 X 3/4 X 30 AXLE RD @ 4HD  
1.5 DEEP. REPLACED WITH ALUM MON

