

MICROFILMED

PLAT AND RECORD

COUNTY BUILDING
CITY OF JANESVILLE

Of a Survey on Section T R E. of the 4 P. M. in Township

Rock County, Wisconsin, made the 19

I hereby certify that the following is a correct record of said survey as made by me.

Bench	Backsight	Instrument	foresight	Page	Inter-Sight	Heights	Remarks	County Surveyor.
			3.356	10.294				
	2.844	13.138						
			1.336	11.802			Aug. 28-1874	
	1.440	13.242						
			2.890	10.352				
	5.995	16.347						
15.194			1.153				Leaning Elm. 16 East Bank, North of Stone's Bridge	
					6.920	9.427	Surface of water just North of Stone's Bridge.	
						10.352		
	5.360	15.712						
			5.619	10.093				
	4.502	14.595						
			3.572	11.023				
	5.176	16.199						
			3.570	12.629				
	4.295	16.924						
					5.380	11.544	Surface of water 1 mile below Indian Ford	
			1.642	15.282				
	2.884	18.166						
			3.781	14.385				
	3.680	18.065						
					5.683	12.382	Surface of water below dam at Indian Ford.	
			2.339	15.726			on stone East bank	
			1.127	16.938			on stone West bank	
					0.186	17.879	Average top surface of East section of dam at Indian Ford	
					1.495	16.570	Top surface of chute of dam at Indian Ford	
					0.538	17.527	Average top surface of west section of dam at Indian Ford	
	7.545	24.483						
					7.530	16.953	Surface of water above dam at Indian Ford	
			6.203	18.280				
	3.812	22.092					Dam at Indian Ford Stone abutment West end 45 ft. long dry rubble wall	
			4.039	18.053			West section of dam proper 207 ft. long	
	5.305	23.358					West abutment of chute 10 ft. long.	
			5.355	18.003			Chute 27 ft. long.	
	5.674	23.677					East abutment of chute 21 1/2 ft. long.	
			4.183	19.494				
	3.881	23.375					East section of dam proper 50 ft. long	
			4.000	19.375			East abutment of dam 31 ft.	

Copied from Page 125 Vol. 2. Original County Surveyors Record.