U.S. PUBLIC LAND SURVEY MONUMENT RECORD

For Public Land Survey Corners In:

WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT

T. 4N. R. 14 E.

CORNER CODE INDEX 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 В В 6 K \mathbf{C} C D D F \mathbf{G} H J K K N O o P Q Q R S R S T U T U V w X Y 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 PLACE MONUMENT SYMBOL AT PROPER LOCATION ON ABOVE INDEX

LIMA		TWI
ROCK	COUNTY	WI

IF AVAILABLE ROCK COUNTY COORDINATES PERFERRED

North	Elev.	
East		
Hor. Datum _	Vert. Datum	
LATITUDE	ELLIPS. HT	
LONGITUDE		
GPS (X)	TRAVERSE (X)	
BASED ON TH	HE FOLLOWING CONTROL:	

◆ CORNER MONUMENT

O WITNESS MONUMENT

BEARINGS ARE BASED ON:

(a)

LI560

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

NORTH EAST SIDE SECTION 13 1836 BRINK

2046 LEAVE MARSH @ EAST

2640 SET QUARTER SECTION POST BUR DAK 12 S23 1/2 W 21.12' BUR DAK 17 N54W 53.46'

2838 ENTER PRAIRIE NE

- 5280 SET POST CORNER SECTIONS 12 & 13 BUR DAK 24 S40 ½ E 323.4' NO OTHER NEAR LAND LEVEL EXCEPT MARSH SECOND RATE WHITE BUR AND BLACK DAK-RED ROOT PRAIRIE GRASS & C
- 1876 L-25 FIELD NOTES FROM 1876 BK 135 PG 5 STATES, "STAKE SURROUNDED BY 4 HH WITH STONES. 5'8" E OF SAID CORNER. BTS OAK S12-23 1/2 W 32? N17-54W 21?. L-23 @ CENTER OF SEC 13 "FORMER COUNTY SURVEYOR FD STAKE SURROUNDED BY 4 LIME HH. CORNER IS 4' B" W OF EAST GATE FRONT IN S RD FENCE, 32' N OF THE N FACE OF THE S. ROAD FENCE
- 1876 RUGER VOL 2 PG 213 FD OLD STAKE & STUMP OF N.W. BT & WHERE STUMP OF SW BT HAD BEEN DUG UP. DROVE NEW STAKE IN PLACE OF OLD ONE SURROUNDED IT BY 4 HH STONES. MR. BANKS DROVE A STAKE 5' 8" EAST OF THE CORNER TO DECEIVE HIS NEIGHBORS AS THEY WOULD NOT HELP PAY. VAR 4-48 2642.31 TO SE COR SEC 13, VAR 5-04 ON E/W CENTER OF SEC 13, VAR 4-39 2656.83 FROM CENTER TO 5 1/4 COR SEC 13
- 1971 LEE FB176 PG 1 TIE FROM NW TO NE REFERENCE PIPE IS "52.42" & NOT "57.47" AS IN VOL 5 PG 24. SET COR BY PRORATION. HWY IS CONCRETE THUS NO MON CAN BE SET. SET PK. COR IS 26"+/- WEST OF FENCE LINE EXTENDED.
- 1974 LEE VOL 5 PG 24 FD NOTHING. SET C.I. MON BY PRORATION. SET TIES. DISTANCE FROM NW TO NE REFERENCE PIPE IS IN ERROR WITH DRAWING BUT CORRECT DISTANCE IS IN FIELD NOTES ..
- 1981 JENSEN #2616 TIES. EXCAVATED RD & FD 4-8" HARDHEAD STONES IN A CIRCLE WITH REMAINS OF A ROTTEN WOOD STAKE IN CENTER OF CIRCLE. EVIDENCE 30" BELOW RD SURFACE. SET CONC. CO. MARKER. 0.9' NORTH OF CENTER OF PVMT. REFERENCED COR. TO TREES & POWER POLES.
- 1983 WIDOT STH59 R/W PLANS PROJECT #3143-00-21 SHEET #4.17 CAST IRON MON 295,981.86; 2,328,066 STA 562+07.5 0.37'N & 871.27' W OF THE E 1/4 COR SEC 13. INVERSE BETWEEN STATE PLANE COORDINATES IS NO-40-19W 2633.36

1986 WIDOT L-25(1) SET TIES. CALLS FOR C.I. 1992 WOODMAN #11479 FD C.I.

IN THE FALL OF 2001, JUST PRIOR TO THE GRINDING & RESURFACING OF THE PAVEMENT I FD A CONC. MON. WITH STEEL RISER RING. I FO WIDOT REFERENCE CAPPED PINS/SIGN & LEE'S SW, NE, & NW REFERENCE PIPES. I WAS AT THE LOCATION WHEN THEY GROUND THE TOP 2" OF THE SURFACE. I DID NOT FIND THE C.I. OR ANY SOUND OF THE C.I. AT THE COMPUTED LOCATION. USING WIDOT'S STATE PLANE COORDINATES ALONG STH 59 IN A LEAST SQUARES ROTATION PROGRAM, THE COUNTY COORDINATES FOR THE E 1/4 COR OF SEC 13 WHERE THEY STATE THEY FOUND A CI MON. IS 313,951.26 N/S; 559,067.92 E/W.

THE LIMA TOWNSHIP PROJ. COORDINATES ARE 313,951.14'; 559,67.89 E/W. WIDDT PROBABLY HAD THE WALWORTH COUNTY MON.

THE FOLLOWING IS BASED ON THE MOST RECENT ADJUSTMENT OF LIMA TWP PROJ.:

Donald Bames 5/24/02

бнеет 1 ог з L-25(2)

LI560

NO-50-33E 2644.15 TO NE COR SEC 13, S1-18-46W 2633.42 TO SE COR SEC 13, & 10.83 EAST OF LINE BETWEEN SE & NE CORNERS SEC 13. IN THE SPRING OF 2002, I FOUND THE CONC. MONUMENT & RING UNDISTURBED. THE RESURFACING PROJECT ENDED A FEW FEET FROM THE MONUMENT.

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED FOUND CONC. MON.

D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.

THERE IS MAJOR DISCREPANCY BETWEEN LEE'S & JENSEN'S LOCATION. I FO LEE'S 3 REFERENCE PIPES. THE INTERSECTION OF THE RECORD DISTANCES AGREE WITH ALL 3 REFERENCE PIPES AND THE COMPUTED POSITION OF THE 4TH RECORD REFERENCE PIPE. THIS POSITION IS 26.7' WEST OF THE CONC. MON. I DID NOT ACCEPT LEE'S LOCATION WHERE HE SET A C.I. MON BY PRORATION, BECAUSE THE CONC. MON. IS ON LINE WITH THE N/S FENCE. ALSO BECAUSE LEE'S LOCATION IS 15.8' WEST OF A STRAIGHT LINE BETWEEN THE NE & SE CORNERS SEC 13. JENSEN'S CONC. MON. IS ONLY 10.8' EAST OF THE LINE.

I, **Donald Barnes**, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Seal

SHEET 2 OF 3

CORNER CODE L-25(2)

A.E. 7.08 REQUIREMENT

