

Paper weight-110# (minimum)

Black nonfading ink required

U.S. PUBLIC LAND SURVEY MONUMENT RECORD

For Public Land Survey Corners In:

WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT

T. 4N. R. 12E. 4th P.M.

REV 10/23/2004

USMONREC.DWG

CORNER CODE INDEX

FULTON TWP

ROCK COUNTY WI

IF AVAILABLE

ROCK COUNTY COORDINATES PREFERRED

North _____ Elev. _____

East _____

Hor. Datum _____ Vert. Datum _____

LATITUDE _____ ELLIPS. HT. _____

LONGITUDE _____

NAD83(91) _____ NETWORK ADJ. YR _____

GPS (X) _____ TRAVERSE (X) _____

BASED ON THE FOLLOWING CONTROL:

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	
A																									A
B																									B
C	6					5					4				3					2				1	C
D																									D
E																									E
F																									F
G																									G
H																									H
J																									J
K																									K
L																									L
M																									M
N																									N
O																									O
P																									P
Q																									Q
R																									R
S																									S
T																									T
U																									U
V																									V
W																									W
X																									X
Y																									Y
Z																									Z

PLACE MONUMENT SYMBOL AT PROPER LOCATION ON ABOVE INDEX

CORNER MONUMENT

WITNESS MONUMENT

BEARINGS ARE BASED ON: _____

MP

FIELD BOOK _____ PAGE # _____

SHEET 1 OF 1

SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.

PLANNING & ZONING COMMITTEE ADOPTED THIS FORM ON 12/2/1982

CORNER CODE J-19/20

FU_M.P.639

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

1834 HARRISON EAST BETWEEN SECS 11 & 14

2194.5 TRAIL CRS NE

2483.58 INT. RIGHT BANK OF ROCK RIVER SET MEANDER
POST BEARINGS {W.O. 18 N74W 82.5' W.O. 18
S51W 132.00' LAND & SAME

1836 (JULY/AUG) BURNHAM WEST RANDOM BETWEEN SEC 11 & 14

1808.4 TO LEFT BANK ROCK RIVER

2534.4 INT RIGHT BANK 28.38' SOUTH OF M.P. FIRST RATE
BUR OAK OPENINGS

CORRECTED BETWN 14 & 11

726 SET MP ON LEFT BANK BUR OAK 8 S21½E 19.8'
BUR OAK 8 N46E 67.98'

858 BUR OAK 10 IN DIA

2534.4 TO CORNERS

1836 (JULY/AUG) BURNHAM WEST RANDOM BETWEEN SEC 11 & 14

1808.4 TO LEFT BANK ROCK RIVER

2534.4 INT RIGHT BANK 28.38' SOUTH OF M.P. FIRST RATE
BUR OAK OPENINGS

CORRECTED BETWN 14 & 11

726 SET MP ON LEFT BANK BUR OAK 8 S21½E 19.8'
BUR OAK 8 N46E 67.98'

858 BUR OAK 10 IN DIA

2534.4 TO CORNERS

1984 BARNES J19/20 SET POLY. 24 EAST OF TOP OF BANK OF
ROCK RIVER. REFERENCED SAME. ON LINE WITH NORTH FACE
OF HOUSE PROJECTED WEST. ON LINE WITH NE & NW COR SEC
14, NB9-28-10E 1789.65 TO NE COR SEC 14, SB9-28-10W
829.80 TO MP ON RIGHT BANK OF ROCK RIVER. BEARINGS
ARE BASED ON GRID NORTH. GRID NORTH IS 0-39-35 EAST OF
TRUE NORTH. THE PRORATED DISTANCE IS IN THE RIVER.
FIELD SEARCH FOR THE CORNER. IT IS VERY UNLIKELY THAT
THE 1833 WOOD POST SURVIVED THE LAWN WORK.

FD POLY & REFERENCE MONUMENTS

(C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED MONUMENTS.

(D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.

(E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.

I, **Donald Barnes**, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Seal

Embloss
Donald Barnes
11/07/07

SHEET 1 OF 1

CORNER CODE

J-19/20

A.E. 7.08 REQUIREMENT