Paper weight-110# (minimum)

Black nonfading ink required

U.S.

PUBLIC LAND SURVEY MONUMENT RECORD

For 1			Survey C				WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT REV 10/23/2004 USMONREC.DWG			
	2 4 5		RNER C			UNION TWP				
В	0	6	9 10 11 12 1	3141316	718 19 20 2	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	ROCK COUNTY WI IF AVAILABLE ROCK COUNTY COORDINATES PERFERRED			
G H		4	9				- G н North Elev			
J K L	8	~	16	1 15		₹	K East			
M N							M N Hor. Datum Vert. Datum			
O P Q	0	10		2)	3	7	$egin{array}{cccccccccccccccccccccccccccccccccccc$			
RST	0	19	28	2	76	05	R S LONGITUDE			
v	7	' ' '					U NAD83(91)NETWORK ADJ. YR 2010			
	3	3	3	70	35	36	$\begin{bmatrix} w \\ x \end{bmatrix}$ GPS (X) TRAVERSE (X)X			
	ACE M	ONUME	9 10 11 12 1 VT SYMBOL BOVE INDEX	AT P	17 18 19 20 2 ROPER	1 22 23 24	BASED ON THE FOLLOWING CONTROL:			
(a)		• (CORNER	MONU	MENT	(WITNESS MONUMENT			

BEARINGS ARE BASED ON: ROCK COUNTY PROJECTION

FIELD BOOK PAGE # OR OBSERVATION SHEET	SHEET .		OF	3
SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND S	URROUND	ING		
PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.				
PLANNING & ZONING COMMITTEE ADOPTED THIS FORM ON 12/2/1982		/	, 2	1

UN557 E1/4CORSEC16

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

HARRISON NORTH BETWEEN SECS 15 & 16

1633.50 BURR 0 14

2640.00 QUARTER SEC COR (BURR O 12 S24W 30.36'; BURR 0 12 N35E 56.76 BURR 0 12 & BURR 0 12}MARKED

5082.00 ROAD E & W

5280.00 COR TO SECS 9,10,15,16 IN THE SOUTHERN EDGE OF MARSH {BURR O 12 N52W 308.22'; BURR O 12 N78E 472.56'; BURR O 12 535E 199.98'; BURR O 12 S63W 214.50' LAND ROLLING 2ND RATE TIMBER GENERLY BURR, UNDERGROWTH GRUB, GRASS & WEEDS

CHURCH VOL 1 PG 60 STATES NOTHING ABOUT MON. USED TO SUBDIVIDE SEC 16. VAR 8-15 5287.92 TO W 1/4 COR SEC 16 & 2645.96 TO CENTER OF SEC 16

RUGER AUG REMON-93 SOUTH ON EAST LINE OF NE 1/4 1870 SEC 16 ON A VAR 6-20; OFFSET WEST

8.91' OFFSET WEST 1.65' OFFSET WEST 6.27' AT

2650.23 INTERSECTED QUARTER LINE 8.14' WEST OF QUARTER CORNER FOUND STAKE AT CORNER. **COR VAR 6-09**

> SOUTH ON EAST LINE OF SE 1/4 SEC 16 ON A VAR 6-15; OFFST EAST 3.96' AT

2656.17 INTERSECTED SOUTH BOUNDARY LINE 7.26' EAST OF CORNER. FOUND OLD STAKE AT CORNER. COR VAR 6-11

- 1890 BLEEDORN VOL 2 PG 430 MON. USED TO SUBDIVIDE SEC 16. 2657.16 TO SE COR SEC 16
- BATTERMAN VOL 3 PG 516 FD CUT STONE 2664.81 TO CUT 1957 STONE @ SW COR SEC 15 & 2658.98 TO FD MON. @ NW COR SEC 15
- SCHROEDER #12785 STATES NOTHING ABOUT MON. 1987
- 1993 SCHROEDER #10277 SEC COR MON. EAST TO NE COR SEC 16 & FROM NE COR SEC 16 TO E 1/4 COR SEC 16 IT IS 501-31W
- 1993 COMBS #10149 MORTGAGE INSPECTION. STATES NOTHING ABOUT MON.
- COMBS #14246 FD STONE MON. NB9-51W 2656.38 TO SET 2001 PIN @ CENTER OF SEC 16 & N89-51W 5343.13 TO STONE MON @ W 1/4 COR SEC 16
- THOUSAND #15024 CUT STONE FD. S01-45-00W 1328.27 2005 TO SET REBAR & THENCE S1-45-00W 1335.05 TO CUT STONE @ SE COR SEC 16
- THOUSAND L-13 FD CUT STONE, LOCATION FITS 2005 OCCUPATION & RECORD SECTION SUMMARY, BASED ON TRAVERSE FROM SE COR SEC 16. REFERENCED SAME. @ FENCE INT.
- COMBS CSM VOL 33 PG 35 CUT LS S89-25-37E 5264.47 2009 TO SET R/R SPIKE @ E 1/4 COR SEC 15
- COMBS #16188 FD CUT STONE N89-25-37E 5264.47 TO FD 2009 R/R SPIKE @ E 1/4 COR SEC 15.

FD CUT LIMESTONE O.8' ABOVE GRADE. SET CARSONITE ON NORTH FACE OF L.S. L.S. IS ON EAST SIDE OF WOOD FENCE POST.

Emboss Paus May 27 2011

SHEET **Z** OF **3**

CORNER CODE L-13(1)

UN557 E1/4CORSEC16

I DID NOT REALIZE THOUSAND PLACED REFERENCE TIES. AFTER THE FACT I USED HIS DATA TO COMPUTE THE POSITION OF HIS REFERENCE MONUMENTS, SO AN APPROXIMATE DISTANCE BETWEEN HIS AND MINE COULD BE SHOWN.

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED FD LIMESTONE.

D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.

NONE

(E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.

 $N \square$

I, **Donald Barnes**, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

SHEET 2 OF 3

CORNER CODE L-13(1)

Einters

Faces

CORNER O

May 27 20 // A.E. 7.08 REQUIREMENT

