

Paper weight-110# (minimum)

Black nonfading ink required

U.S. PUBLIC LAND SURVEY MONUMENT RECORD

For Public Land Survey Corners In:
T. 4 N. R. 10 E. 4th P.M.
CORNER CODE INDEX

WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT
REV 10/23/2004 USMONREC.DWG

UNION TWP
ROCK COUNTY WI

IF AVAILABLE
ROCK COUNTY COORDINATES PREFERRED

A	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	A
B		6				5				4				3			2				1					B
C																										C
D																										D
E																										E
F																										F
G																										G
H																										H
J																										J
K																										K
L																										L
M																										M
N																										N
O																										O
P																										P
Q																										Q
R																										R
S																										S
T																										T
U																										U
V																										V
W																										W
X																										X
Y																										Y
Z																										Z

North _____ Elev. _____

East _____

Hor. Datum _____ Vert. Datum _____

LATITUDE _____ ELLIPS. HT. _____

LONGITUDE _____

NAD83(91) _____ NETWORK ADJ. YR 2010 _____

GPS (X) _____ TRAVERSE (X) X

BASED ON THE FOLLOWING CONTROL:

PLACE MONUMENT SYMBOL **◆** AT PROPER LOCATION ON ABOVE INDEX

◆ CORNER MONUMENT **○ WITNESS MONUMENT**

BEARINGS ARE BASED ON: ROCK COUNTY PROJECTION

FIELD BOOK _____ PAGE # _____
OR OBSERVATION SHEET _____

SHEET 1 OF 3

SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.

PLANNING & ZONING COMMITTEE ADOPTED THIS FORM ON 12/2/1982

CORNER CODE P-21(2)

UN579 W1/4CORSEC24

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

- 1833 HARRISON (NOV5) T4N R10E NORTH BET SECS 22 & 23
2640.00 QUARTER SEC COR. {BURR O 12 S60W 25.74';
BURR O. 18 N64W 64.68' BURR O 12 & BURR O
12} MARKED
4062.96 BURR O 18
5280 COR TO SECS 14, 15, 22, 23
{BURR O 12 S23W 36.3', BURR O 10 N20E
24.42', BURR O 10 N50W 17.16'; BURR O 12
S65E 14.52' LAND ROLLING 2ND RATE TIMBER
ALL BURR O. MOSTLY SCRUB GRASS & WEEDS
- 1870 RUGER AUG REMON-74 SOUTH ON WEST LINE OF NW
1/4 SEC 24 ON A VAR 7-07 AT
2661.78 INTERSECTED QUARTER LINE 4.62' EAST OF
QUARTER CORNER FOUND OLD STAKE AT
CORNER. ALSO FOUND STUMP OF EAST
BEARING TREE. COR VAR 7-01'
SOUTH ON WEST LINE OF SW 1/4 SEC 24
ON A VAR 6-53 OFFSET EAST 11.55' AT
2650.06 INTERSECTED SOUTH BOUNDARY LINE 3.3' EAST
OF CORNER. COR VAR 7-04'
- 1875 RUGER VOL 2 PG 201 STONE MON. USED TO SUBDIVIDE
SEC 23
- 1884 RUGER VOL 2 PG 294 USED TO SUBDIVIDE SEC 23. BR.
OAK 18 29E 33'; BR OAK 10 N35W 33' VAR 5-4 2640.00 TO
CEN OF SEC 23
- 1940 SUNNY VOL 3 PG 463 DUG 8'X8' HOLE 2.5' DEEP FD REMAINS
OF DECAYED STAKE. NO STONE. 2668.1 TO FD 6X6 CUT
STONE @ M NE COR SEC 23 & 2656.2 TO FD STONE MON @
SE COR SEC 23
- 1968 BATTERMAN FB #142 PG 46 DUG VERY LARGE HOLE &
FOUND NOTHING 2 1/2' DEEP. STONE PROBAQBLY
DESTROYED BY ROAD CONSTRUCTION.
- 1970 BATTERMAN VOL 4 PG 449 DUG & FD NOTHING. MEAS IN &
SET CI. REF. SAME. 2656.73 TO FD LS @ SW COR SEC 24 &
2668.45 TO CUT LS @ NW COR SEC 24.
- 1972 DOT GTH M #7430 PROJ E0624(16) SHEET 4.3 & 4.4.
STATES NOTHING ABOUT MON. SHOWS TIES.
- 1977 WOODMAN BK-29 PG 12 "GOLF ESTATES" FD R/R SPIKE TO
SET SPIKE FROM COUNTY TIES. @ W 1/4 COR SEC 23
- 1978 WOODMAN CSM VOL 7 PG 230 FD SPIKE IN VAVEMENT
- 1981 COMBS CSM VOL 10 PG 477 FD CI USED STONE @ SE COR
SEC 23.
- 1982 COMBS CSM VOL 11 PG 86 FD ALUM.
- 1991 BARNES P-21 FD CI MON 32" DEEP. PLACED POLY MON ON
TOP WITH TOP 2" OF CI 8" DEEP. REF. SAME. 3.5 EAST OF
CENTER OF PVMT & 20' NORTH OF NORTH PVMT EDGE. FB#2
PG 46
- 1991 COMBS CSM VOL 15 PG 253 POLY 2656.94 TO POLY @ SW
COR SEC 24
- 1991 COMBS CSM VOL 15 PG 325 POLY 2656.94 TO POLY @ SW
COR SEC 24
- 1992 COMBS CSM VOL 16 PG 5 FD ALUM MON. 2668.74 TO FD
ALUM @ NE COR SEC 23
- 1992 COMBS CSM VOL 16 PG 41 STATES NOTHING ABOUT MON.
- 1992 COMBS CSM VOL 18 PG 94 ALUM 2656.94 TO CUT STONE @
SE COR SEC 23
- 1993 SCHEEBERGER CSM VOL 17 PG 121 ALUM 2668.77 TO 1"
PIPE @ NW COR SEC 24
- 1995 COMBS CSM VOL 18 PG 252 ALUM 2656.94 TO CUT STONE @
SE COR SEC 23
- 1995 COMBS CSM VOL 18 PG 468 ALUM 2656.94 TO CUT STONE @
SE COR SEC 23 R/W LINE OF TERRITORIAL RD.

SHEET 1 OF 3

CORNER CODE P-21(非)

2

Carol Barnes

Barnes

Nov 1, 2011

UN579 W1/4CORSEC24
 1996 COMBS #8684 FD POLYSTRENE MON. S1-45-35W 34.35 TO
 CENTER OF TERRITORIAL RD
 1998 COMBS #8122 FD ALUM MON. S1-45-55W 34.35 TO NORTH
 1998 WALKER #8250 ALUM. MON. S01-46-00W 2656.96 TO
 STONE MON @ SW COR SEC 24. S1-46-00W 34.35 TO INT
 OF CENTER OF TERRITORIAL RD & GTH M
 1999 COMBS #7453 FD CUT STONE. NO-05-05W 2668.75 TO FD
 PIPE @ NE COR SEC 23
 2002 COMBS CSM VOL 26 PG 52 POLY 5295.97 TO FD SPIKE NAIL
 @ W 1/4 COR SEC 23
 2005 COMBS #15121 POLY MON. 2668.71 TO PIPE @ NE COR SEC
 23.
 2006 COMBS #15546 FD POLY. STATES W 1/4 COR SEC 33 & IT
 SHOULD STATE E 1/4 COR SEC 23 2668.71 TO FD PIPE NE
 COR SEC 23

FD TIES.

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED PERPEUTATED POSITION OF CUT LIMESTONE.

D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.

NONE

(E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.

NO

I, **Donald Barnes**, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Donald
 Barnes
 Nov 1, 2011

SHEET 2 OF 3

CORNER CODE P-21 (3)
 A.E. 7.08 REQUIREMENT (2)

