

Paper weight-110# (minimum)

Black nonfading ink required

U.S.

PUBLIC LAND SURVEY MONUMENT RECORD

For Public Land Survey Corners In:

WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT

T. 4 N. R. 10 E. 4th P.M.

REV 10/23/2004

USMONREC.DWG

CORNER CODE INDEX

UNION TWP

ROCK COUNTY WI

IF AVAILABLE

ROCK COUNTY COORDINATES PREFERRED

A	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	A
B		6																								B
C			5																							C
D				4																						D
E					3																					E
F						2																				F
G							1																			G
H								7																		H
I									8																	I
J										9																J
K											10															K
L												11														L
M													12													M
N														13												N
O															14											O
P																15										P
Q																	16									Q
R																		17								R
S																			18							S
T																				19						T
U																					20					U
V																						21				V
W																						22				W
X																						23				X
Y																							24			Y
Z																							25			Z

PLACE MONUMENT SYMBOL AT PROPER LOCATION ON ABOVE INDEX

North _____ Elev. _____

East _____

Hor. Datum _____ Vert. Datum _____

LATITUDE _____ ELLIPS. HT. _____

LONGITUDE _____

NAD83(91) _____ NETWORK ADJ. YR 2010

GPS (X) _____ TRAVERSE (X) X

BASED ON THE FOLLOWING CONTROL:

CORNER MONUMENT

WITNESS MONUMENT

(2)

BEARINGS ARE BASED ON: ----- ROCK COUNTY PROJECTION -----

FIELD BOOK _____ PAGE # _____

OR OBSERVATION SHEET _____

SHEET 1 OF 3

SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.

PLANNING & ZONING COMMITTEE ADOPTED THIS FORM ON 12/2/1982

CORNER CODE T-13(2)

UN597 W1/4CORSEC27

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

- 1833 HARRISON T4N R10E 4TH MER. NORTH BETWEEN SECS 27
& 28
1089.00 ENTER SMALL PRAIRIE
2409.0 LEAVE IT E & W
2640.00 QUARTER SEC COR. [RED O 12 N64W 22.44';
W.O. 8 N36E 16.5' W.O 12 & WO 8} MARKED
5280.00 COR TO SECS 21,22,27,28 {W.O 18 N52W 5.94';
W.O 18 N8E 15.18' {RED O 12 S30E 42.24'; W.O
18 S53W 50.16'
LAND LEVEL 2ND RATE TIMBERED WITH W. RED &
BURR ASPEN. UNDERGROWTH SCRUBS GRASS &
WEEDS.
- 1870 RUGER AUG REMON-71 NORTH ON WEST LINE OF SW 1/4
SEC 27 ON A VAR 7-20 OFFSET EAST 3.96' AT
2659.47 INTERSECTED QUARTER LINE 9.9' EAST OF
QUARTER CORNER. FOUND STONE ON CORNER.
ALSO FOUND REMAINS OF BOTH BEARING
STUMPS. COR. VAR 7-28'
REMON-75 AUGUST 22, 1870 NORTH ON WEST
LINE OF NW 1/4 SEC 27 ON A VAR 7-5 OFFSET
EAST 2.64' AT
2670.69 INTERSECTED NORTH BOUNDARY LINE 22.44'
EAST OF CORNER. FOUND REMAINS OF OLD
STAKE. ALSO FOUND STUMPS OF BOTH
BEARING TREES. COR VAR 8-15
- 1905 KERCH VOL 3 PG 25 MONUMENTS ON MAIN & FOURTH
ST. E 1/4 SEC 28 IS AT INT OF MAIN & 4TH ST.
REFERENCED TO MANY GAS PIPES IN AREA.
- 1919 BATTERMAN VOL 3 PG 82 SEC 28 IN EVANSVILLE LOOK AT
DRAWING ONCE PROJECT STARTS. E 1/4 SEC 28 IS AT INT
OF MAIN & 4TH ST. FD STONE MON WITH DRILL HOLE.
REFERENCED TO MANY GAS PIPES IN AREA.
- 1935 SUNNY VOL 3 PG 264 STATES NOTHING ABOUT MON. @ INT
OF MAIN & 4TH ST.
- 1935 SUNNY ASSESSORS PLAT SHEET 6 SUB #8628 STATES
NOTHING ABOUT MON. CALL TO CLOSE MONUMENTS.
- 1935 SUNNY ASSESSORS PLAT SHEET 6 SUB #8629 STATES
NOTHING ABOUT MON. CALL TO CLOSE MONUMENTS.
- 1947 SUNNY BK14 PG 8 "TAITS ADD" STATES NOTHING ABOUT
MON.
- 1956 CHENY BK18 PG 13 "BRZEZINSKI'S ADD" STATES NOTHING
ABOUT MON.
- 1960 BATTERMAN VOL 4 PG 43 RR SPIKE. REF. SAME. 5/29/74
KEN HENNING CREW CHIEF FROM JENSEN & JOHNSON FD
CUT STONE TIPPED OVER & STRAIGHTENED SAME. STONE
FELL 0.43' SW OF ABOVE REFERENCES. HIGHWAY DEPT TO
FURNISH NEW REFERENCES STONE TO BE SET ACCORDING
TO ABOVE REFERENCES.
- 1960 BATTERMAN Mc EWEN & PULLEN'S ADDITION TO EVANSVILLE"
#8280, #2196, & 10024 ESTABLISHED E 1/4 COR SEC 28
ACCORDING TO REFERANCE TIES NOW RECORDED IN VOL 4
PG 43, ROCK COUNTY SURVEYORS RECORDS. SOUTHERLY
1333.08 TO SET 1" PIPE @ NE COR SE 1/4 OF SEC 28.
SHOWS FINDING KERCH'S INTERIOR PIPES & DIFFERENCES.
- 1960 BATTERMAN #6391 ESTABLISHED E 1/4 SEC 28
ACCORDING TO REFERENCE TIES NOW RECORDED IN VOL 4
PG 43. SOUTH 1333.08 TO SET 1" PIPE @ 1/16TH COR.,
2666.16 TO FD CUT STONE @ SE COR SEC 28
- 1960 RHJ CSM VOL 1 PG 47 FD SPIKE.
- 1965 CADMAN BK 23 PG 9 SPINHIRNE-LIEN-ALGRIM ADD" STATES
NOTHING ABOUT MON.

SHEET 1 OF 3

CORNER CODE T-13(2)

Ronald Barnes

OCT 27, 2011

UN597 W1/4CORSEC27

- 1966 BATTERMAN VOL 4 PG 289 RESET 1/4 COR FROM TIES IN VOL 4. WESTERLY 667.40 TO FD PIPE 0.36 NORTH OF LINE, WESTERLY 1334.80 FROM E 1/4 COR SEC 28 ALONG E/W 1/4 LINE TO FD PIPE 0.72 NORTH OF LINE
- 1966 LEE #5218 SET R/R SPIKE. S89-57-50W 667.40 TO PIPE.
- 1966 THOM BK 23 PG 19 "DARWOOD ADD" PK S89-558W 1334.76 TO PIPE WHICH IS 0.72 OF A LINE BETWEEN THE E 1/4 & W 1/4 CORNERS OF SEC 28.
- 1967 BATTERMAN VOL 4 PG 325 SHOWS PIPE @ MAIN ST & FOURTH ST. 2666.16 TO SE COR SEC 28, WESTERLY 667.40 TO PIPE.
- 1969 JENSEN ASSESSORS PLAT #6 SUB #2183 STONE. WITH SHORT TIES. WEST 2670.72 TO CONC. MON @ CENTER OF SEC 28. N1-06W 2672.40 TO STONE @ NE COR OF SEC 28
- 1969 JENSION #6781 - BARNES VOL 6 PG 307 - SEE COUNTY SURVEYORS RECORDS VOL 6 PG 157. THE FIELD NOTES FOR THE W 1/4 COR SEC 27 ARE FILED IN MILTON TWP SEC 27 FILE. THE NOTES SHOW T4N R13E BUT THE PHYSICALL CALLS INDICATE THE CORNER MAY BE IN UNION TWP. TIES FOR EVIDENCE FD AT CORNER BEFORE DIGGING. PK SPIKE WEST OF MH. SHORT TIES. UNDER BLACK TOP FD 1/2 BRASS ROD, 1/2 STEEL PIN, & RR/ SPIKE. IN CONC. PVMT. FINAL TIES. FD LIMESTONE AT COR WITH TOP 3" BELOW BLACK TOP. SET PK 8.46 TO THE SW & PK 8.11 TO THE NW. FD RAILROAD SPIKE, IRON PIN AND BRASS ROD IN PVMT. DRIVEN AROUND TOP OF STONE. STONE MON. HAD DRILL IN TOP. TOP OF STONE WAS BROKEN SOME. STONE TIPPED TOWEST, EVIDENCE OF HOLE EAST SIDE. STONE SET VERTICAL AND FILLED AROUND WITH CRUSHED STOEN.
- 1973 COMBS BK 26 PG 32 "WARD'S ADD. FD PIPE. WESTERLY 667.38 TO PIPE.
- 1974 BRIDWELL BK 27 PG 8 "JALOMAH-ADD." BRASS CAP TO BE SET BY DOT.
- 1978 RASMUSSEN BK 30 PG 11 JUDD ESTATES" WESTERLY 667.21 TO PIPE
- 1979 KIENBAUM VOL 5 PG 523 FD ALUM. MON
- 1979 LEE BK 31 PG10 "WESTVIEW HILL ADD. STATES NOTHING ABOUT MON. N89-59-16W 1334.99.
- 1982 COMBS CSM VOL 11 PG 21 FD ALUM. S89-53-30E TO FD PK @ E 1/4 COR SEC 27
- 1982 COMBS CSM VOL 11 PG 56 STATES NOTHING ABOUT MON. WESTERLY TO PIPE IN MON. BOX @ 1/16 TH COR
- 1983 BARNES VOL 6 PG 307 SEE COUNTY SURVEYORS RECORDS VOL 6 PG 157. THE FIELD NOTES FOR THE W 1/4 COR SEC 27 ARE FILED IN MILTON TWP SEC 27 FILE. THE NOTES SHOW T4N R13E BUT THE PHYSICALL CALLS INDICATE THE CORNER MAY BE IN UNION TWP.
- 1984 COMBS CSM VOL 11 PG 644 FD ALUM. N89-59-15W 1334.99 TOWARDS STONE @ W 1/4 COR SEC 28.
- 1985 BARNES VOL 6 PG 337 N89-40-46E 5255.42 TO E 1/4 COR SEC 27 & S0-57-18E 2666.57 TO SW COR SEC 27
- 1985 BARNES VOL 6 PG 339 FD ALUM MON. S0-57-18E 2666.56 TO FD CUT L.S. @ SE COR SEC 28 7 S89-33-54W 1334.96 TO FD 2" PIPE IN MON. BOX
- 1985 BARNES T-13 FD ALUM. MON THAT WAS IN HARMONY WITH OLD TIES. REFERENCED SAME. 285,178.59; 2,185,611.17 ELEV 941
- 1986 COMBS CSM VOL 12 PG 359 FD ALUM. N89-59-15W 1334.99 TOWARDS STONE @ W 1/4 COR SEC 28.
- 1987 COMBS BK32 PG 33 "REPLAT OF BLOCK 18 ORIGINAL PLAT" ALUM. S0-06-30W 2666.57 TO LS @ SW COR SEC 27

SHEET 2 OF 3

CORNER CODE T-13(2)

Donald Barnes
8 OCT 27, 2011

UN597 W1/4CORSEC27
1988 COMBS CSM VOL 13 PG 176 ALUM. MON WESTERLY TO PIPE
IN MON BOX @ FIFTH ST.
1995 COMBS CSM VOL 18 PG 269 ALUM MON WESTERLY 1334.99
ON 1/4 LINE.
1996 COMBS BK 32 PG 319 "PETTERSON WEST MEADOW" LS. @ W
1/4 COR SEC 28 5329.46 TO ALUM @ E 1/4 COR SEC 28
1996 COMBS BK 32 PG 355 "PETTERSON WEST MEADOW FIRST
ADD." ALUM. 5329.46 TO LS @ W 1/4 COR SEC 28
1997 COMBS BK 32 PG 406 "WEST KNOLL" LS. @ W
1/4 COR SEC 28 5329.46 TO ALUM @ E 1/4 COR SEC 28
2008 COMBS CSM VOL 32 PG 158 FD ALUM. 2673.13 TO STONE
@ NE COR SEC 28

FD ALUM & REFERENCE MONUMENTS

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

PERPETUATED LOCATION IS THE LOCATION OF THE CUT LIMESTONE.

D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.

(E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.

I, **Donald Barnes**, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Donald Barnes
Business

OCT 27, 2011

SHEET 3 OF 3

CORNER CODE T-13(2)

A.E. 7.08 REQUIREMENT