

Paper weight-110# (minimum)

Black nonfading ink required

# U.S. PUBLIC LAND SURVEY MONUMENT RECORD

For Public Land Survey Corners In:

WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT

T. 4 N. R. 12 E. 4th P.M.

REV 10/23/2004

USMONREC.DWG

### CORNER CODE INDEX

FULTON TWP

ROCK COUNTY WI

IF AVAILABLE

ROCK COUNTY COORDINATES PREFERRED

North \_\_\_\_\_ Elev. \_\_\_\_\_

East \_\_\_\_\_

Hor. Datum \_\_\_\_\_ Vert. Datum \_\_\_\_\_

LATITUDE \_\_\_\_\_ ELLIPS. HT. \_\_\_\_\_

LONGITUDE \_\_\_\_\_

NAD83(91) \_\_\_\_\_ NETWORK ADJ. YR \_\_\_\_\_

GPS (X) \_\_\_\_\_ TRAVERSE (X) \_\_\_\_\_

BASED ON THE FOLLOWING CONTROL:

	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25		
A																											A
B																											B
C																											C
D																											D
E																											E
F																											F
G																											G
H																											H
J																											J
K																											K
L																											L
M																											M
N																											N
O																											O
P																											P
Q																											Q
R																											R
S																											S
T																											T
U																											U
V																											V
W																											W
X																											X
Y																											Y
Z																											Z

PLACE MONUMENT SYMBOL  AT PROPER LOCATION ON ABOVE INDEX

CORNER MONUMENT

WITNESS MONUMENT

BEARINGS ARE BASED ON: \_\_\_\_\_

FIELD BOOK \_\_\_\_\_ PAGE # \_\_\_\_\_

SHEET 1 OF 2

SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.

PLANNING & ZONING COMMITTEE ADOPTED THIS FORM ON 12/2/1982

CORNER CODE 6-1(1)

FU554

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

1833 (SEP 20) MULLETT & BRINK NORTH ON EAST SIDE SEC 13 T4N R11E

82.5 DESCEND TO RIVER BOTTOM  
363 CATFISH CREEK 108.9' @ NE  
1320 CATFISH CREEK 108.9' @ NW  
2112 CATFISH CREEK 108.9' @ NE  
2442 LEAVE RIVER BOTTOM  
2640 SET QUARTER SECTION POST BUR OAK 20 S48W  
87.78' BUR OAK 10 N36W 125.4'  
4369.86 WHITE OAK 20 IN DIAMETER  
5280 SET POST CORNER SECTIONS 12 & 13 BLACK OAK 8  
S40W 23.1' BLACK OAK 8 N55W 12.54'

1851 STEBBINS PORTER RD REC BK 1 PG 5 SURVEY OF A ROAD IN THE TOWN OF PORTER MADE MAY 10<sup>TH</sup> 1851. BEGINNING AT A PT 33' SOUTH OF THE 1/4 POST ON THE EAST LINE OF SEC 13, T4N R11E; THENCE WEST PARALLEL WITH THE 1/4 LINE RUNNING THROUGH SAID SEC 4569.84'; THENCE N11W 858'; THENCE """" COURSE GIVEN ACCORDING TO THE TRUE MERIDIAN. VARIATION OF NEEDLE 7 3/4

1855 PORTER RD REC BK 1 PG 6 BEGINNING AT THE 1/4 POST ON THE EAST LINE OF SEC 13 T4N R1E; THENCE WEST ON THE CENTER LINE OF SEC 13; 4540.8'; THENCE S6E 419.76'; """""" DECLARE THE ABOVE DESCRIBED ROAD TO BE A PUBLIC HIGHWAY 66' WIDE,

1888 TWP RD BK 2 PG 5 BEGINNING AT THE QUARTER POST AT THE SOUTH WEST CORNER OF THE NORTH WEST QUARTER OF SEC 18 OF SAID TOWN OF FULTON AND RUNNING; THENCE EAST 37 NORTH 211.86' TO A STAKE; THENCE EAST 15 1/2 NORTH 224.4' TO A STAKE; THENCE EAST 25 1/2 NORTH 594.99' TO A STAKE TO THE HIGHWAY RUNNING NORTH FROM THE VILLAGE OF FULTON SAID HIGHWAY BEING 66' WIDE BEING 16.5' ON THE SOUTH SIDE OF THIS LINE AND 149.5' ON THE NORTH SIDE OF SAID LINE. VARIATION OF NEEDLE

1965 SCHROEDER CSM VOL 5 PG 347 STATES NOTHING ABOUT MON.

1968 LEE #01281 CONSIDERED LOST AND WAS ESTABLISHED BY SINGLE PROPORTIONATE MEASUREMENT BETWEEN THE NW & SW CORNERS OF SEC 18. 2656.77 TO SW & NW COR SEC 18

1968 LEE CSM 3-167 STATES NOTHING ABOUT MON.

1968 LEE #M14337 & M14336 SIZE 2, SEC 18 "VILLAGE OF FULTON" CONSIDERED OBLITERATED & WAS REST BY PROPORTION MEASUREMENT OF OCCUPATION OF LINES IN THE NW 1/4 OF SEC 18 & BY TESTIMONY THAT THE WEST LINE OF SECTION 19 PASSED THROUGH THE KITCHEN OF A HOUSE 800' SOUTH OF SAID CORNER. NB9-09-06E 2666.86 TO FD CONC. MON @ S 1/4 COR SEC 18 & N00-55-40W 2656.77 TO FD 24X12X4 POINTED HH @ W 1/4 COR SEC 18.

1973 LEE #1286 FD PIPE & ON LINE WITH THE NW & SW COR OF SEC 18. 2657.38 TO THE NW SEC 18, 2657.35 TO SW COR SEC 18.

1976 BARNES VOL 5 PG 115 FD 1" PIPE WITH CAP (RLS 181) & REFERENCED SAME. 34' SOUTH OF SOUTH PVMT EDGE OF CALEDONIA RD

1978 BARNES #13772 & 1275 USED COR FOR A SURVEY IN SEC 18.

1979 BARNES #6182 FD CAPPED PIPE

1981 BARNES VOL 6 PG 201 FD 1" PIPE & REPLACED SAME WITH ALUM. & REFERENCED SAME.

*Donald Barnes*

SHEET 1 OF 2  
CORNER CODE L-1(1)

4/07/07

FU554

1981 AERO-METRIC PHOTO CONTROL NGVD 29 ELEVATION 795.13'  
1987 NORTHOP GCM VOL 12 PG 588 USED COR FOR THE SURVEY  
1992 BARNES L-1 FD ALUM. & REF. SAME. ALUM IN BETWEEN  
CALEDONAI RD & PARK LANE.  
1992 BARNES N-1 2656.96 TO SW COR SEC 18  
1993 BARNES #14426 FD POLY  
1993 JOHNS #10113 & 10194 MON. 2657.04 TO SE COR SEC 13.  
1996 BARNES #8920 & 9042 FD POLY

**FD POLY & REFERENCE MONUMENTS**

*C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?*

ACCEPTED FD POLY. MON.

*D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.*

*(E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.*

I, **Donald Barnes**, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Seal  
Donald  
Barnes  
11/07/07

SHEET 2 OF 2

CORNER CODE **L-1(1)**

A.E. 7.08 REQUIREMENT