## U.S.

## PUBLIC LAND SURVEY MONUMENT RECORD

For			WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT
	,	R. $\angle$ E. 4th P.M.	REV 10/23/2004 USMONREC.DWG
		ER CODE INDEX	BECOIT TWP
A B		11 12 13 14 15 16 17 18 19 20 21 2	ROCK COUNTY WI
С	6 5	× 3 7	
E			D IF AVAILABLE  E ROCK COUNTY COORDINATES PERFERRED
F G	1 8	9 10 11	F G
H			н North Elev
К	28 27	46 AS AN	K East
L M	7 7	<b>Y Y Y</b>	L M
N			N Hor. Datum Vert. Datum
P Q	19 70	2 22 23	Q LATITUDE ELLIPS. HT.
R		<b>8</b>	R
S T	30 39	28 2 26	S LONGITUDE
U V			U NAD83(91)NETWORK ADJ. YR
w x	2	3 3 35	w GPS (X) TRAVERSE (X)
Y			+
1 2	3 4 5 6 7 8 9 10 LACE MONUMENT S	11 12 13 14 15 16 17 18 19 20 21 2 YMBOL AT PROPER	BASED ON THE FOLLOWING CONTROL:
I	OCATION ON ABOVE	E INDEX *	
(a)	♦ COF	RNER MONUMENT	O WITNESS MONUMENT
. (-)			
*			
ا. ا			
NO			
a			
ARE BASED			
B			
RE			
A			
Ş			
Z.			
BEARINGS			
BI			
			[14] [14] [15] [16] [16] [16] [16] [16] [16] [16] [16
FIEI	LD BOOK	_ PAGE #	SHEET $\sqrt{\text{OF}}$
			E CORNER MONUMENT AND SURROUNDING

PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.
PLANNING & ZONING COMMITTEE ADOPTED THIS FORM ON 12/2/1982

CORNER CODE R-15(1

## BE588

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

1834 HARRISON EAST ON RANDOM BET. SECS 22 & 27

2640 TEMPY QUARTER SEC COR.

5131.5 TO THE TRAIL TO TURTLE VILLAGE ON LEFT BANK OF ROCK RIVER HERETOFORE MENTIONED AS LEADING FROM PRAIRIE DE CHEIN TO CHICAGO

5220.6 INT E BDY 14.52 NORTH OF POST.

1920 BATTERMAN BK 9 PG 40. S89-27-20E 1307.45 TO THE CENTER LINE OF MCKINLEY ST. AND S0-15-40W 2657.87 TO CENTER OF SECTION 27 AT TOWNLINE RD & WHIPPLE ST.

1955 SHIMEALL SUBDIVISION PLAT BK 17 PG 3 FOUND 5/8 PIN.

1956 SHIMEALL SUBDIVISION PLAT BK 17 PG 29 FOUND 5/8 PIN

1957 TRIELOFF SUBDIVISION PLAT BK 18 PG 34 FOUND MONUMENT BUT STATED NOTHING ABOUT IT.

1957 SHIMEALL SUBDIVISION PLAT BK 18 PG 35 FOUND 5/8 PIN. ANGLE OF 90-23-55 FROM S 1/4 COR SEC 27 TO NW COR SEC 27 AT N 1/4 COR SEC 27.

SHOWS SHORT TIES TO BLOCK CORNER.

1962 SHIMEALL SUBDIVISION PLAT BK 21 PG 26 FOUND IRON PIN.

1962 SHIMEALL SUBDIVISION PLAT BK 21 PG 27 FOUND 1" PIN.

1962 BATTERMAN CSM V 1 PG 72 FOUND 1" PIPE

1970 BATTERMAN CSM V 1 PG 339 FOUND PIPE

1978 LEE CSM V 8 PG 338 CONNECTED TO CORNER.

1997 BARNES R-15 MAN HOLE COVERS IN BURTON INDICATES SEWER LINE DESTROYED RECORD MONUMENTS. USED LOCAL RECORD PROPERTY CORNERS TO RECONSTRUCT LOCATION OF CORNER.

FOUND R/R SPIKE WITH DRILL HOLE IN SE TOP OF R/R HEAD & REFERENCE MONUMENTS.

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED FOUND R/R SPIKE WITH DRILL HOLE IN SE TOP OF R/R HEAD.

D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.

NONE

(E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.

NO

I, **Donald Barnes**, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Emboso

Try 22,2008

SHEET 1 OF 2

GORNER GODE R-15(1)

A.E. 7.08 REQUIREMENT

