U.S.

BEARINGS ARE BASED ON: --

SURVEY MONUMENT RECORD

For	Public Land Survey Corners In: T N. R E. 4th P.M.						WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT REV 10/23/2004 USMONREC.DWG						
	T	N.	R. 4	E. 4	th P.M.	•							
			RNER C					C/12	TON	TWF)		
$A^{\frac{1}{2}}$	3 4 5	6 7 8 9	10 11 12 1	8 14 15 16 1	7 18 19 20 21	22 23 24 25 _A	_						
В	6	5		2	N	B		ROCK	COUNTY	(WI			
C)		IF AVAILABI				
E						F F		CK COUNT	Y COORDINAT	res perfer	RED		
F	1	8	9	10	1,7	7 6	2						
H	+					I I			E	lev			
J K L	48		16	15	A	J)	East						
M N	7	Y	7	Y				ım	Vert.	Datum _			
0	- a-	0			73						·		
P Q	>	\\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\	- 'V'					E		ELL	JPS. HT.		
R -						F		IDE					
т —	70	3	28	1 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	70	- √?- ₁	Γ						
U V							NAD83(91))	NETWOF	K ADJ. Y	R 2010		
w		2	2		25		w x GPS (X)		TRAVER	SE (X)	X		
X Y	7	77	7	7	7	 `	7		FOLLOWI				
	2 3 4 5	6 7 8	9 10 11 12 1	3 14 15 16 1	17 18 19 20 2	1 22 23 24 25	z BASED O)N IHE	FOLLOWI	AG COMI	KUL.		
]	PLACE M LOCATIO	IONUMEN' N ON AB	T SYMBOL OVE INDE	X ◆ AT P	PROPER								
		• (CORNER	MONU	MENT	0	WITNESS M	IONUME	NT				
(a)		•											
,	1												
	1												
Z											*.		
110	1												
ROJECTION	į												
Q.	l i												
	į												
Z	1												
OU	1												
KC	1												
ROCK COUNTY P	 												
×	i												

FIELD BOOK PAGE #		/		フ
OR OBSERVATION SHEET	SHEET		OF	
SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND S	SURROUN	DING		
PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.				
PLANNING & ZONING COMMITTEE ADOPTED THIS FORM ON 12/2/1982				
		Δ	,	~

CL507 NECORSEC4

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

ROAD PAVEMENT WAS RELOCATED. BATTERMAN'S ENGINEER WAS IN CHARGE OF THE PROJECT. ROCK ROAD DID THE PAVING & EXCAVATION. HE STATED HE FOUND A CAST IRON MONUMENT, WHICH HE MARKED SO IT WOULD BE SAVED. HE PLACED A LATH 36' TO THE NW OF CI & 20' TO THE NE. THE NEXT DAY IT WAS REMOVED. I DUG 2.0' DEEP & DID NOT FIND THE BOTTOM OF THE CI. I PLACED AN ALUMINUM MONUMENT AT HARMONY DISTANCES TO THE FD MONUMENTS. THIS IS ALSO IN HARMONY WITH BATTERMAN'S LATH. THE MAP IN THE JANESVILLE COUNTY SURVEYORS' VOL 4 PAGE 450 SHOWS THE CORNER WEST OF THE N/S FENCE LINE. THE BELOIT SET CORRECTLY SHOWS THE LOCATION NEAR THE N/S FENCE LINE.

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED FD OBLITERATED EVIDENCE LOCATION.

- D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.
- (E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.
- I, **Donald Barnes**, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Sep 7 2010

SHEET 1 OF 2

CORNER CODE A-13 A.E. 7.08 REQUIREMENT

