

U.S. PUBLIC LAND SURVEY MONUMENT RECORD

For Public Land Survey Corners in:

WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT

T. 1N., R. 11E

CORNER CODE INDEX

A	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25
B																									
C	6																								
D																									
E																									
F																									
G	7																								
H																									
I																									
J																									
K																									
L	18																								
M																									
N																									
O																									
P	19																								
Q																									
R																									
S																									
T	30																								
U																									
V																									
W																									
X	31																								
Y																									
Z																									

NEWARK TWP

ROCK COUNTY WI

IF AVAILABLE
ROCK COUNTY COORDINATES PREFERRED

North _____ Elev. _____

East _____

Hor. Datum _____ Vert. Datum _____

LATITUDE _____ ELLIPS. HT. _____

LONGITUDE _____

GPS (X) _____ TRAVERSE (X) _____

BASED ON THE FOLLOWING CONTROL:

PLACE MONUMENT SYMBOL AT PROPER LOCATION ON ABOVE INDEX

CORNER MONUMENT

WITNESS MONUMENT

(a)

BEARINGS ARE BASED ON:

Fd EXISTING TIES

OBSERVATION SHEET 578 of 478

FIELD BOOK _____ PAGE # _____

SHEET 1 OF 1

SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.

PLANNING & ZONING COMMITTEE ADOPTED THE ABOVE FORM ON 12/2/1982

CORNER CODE P17-11

NE578

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

- 1834 MILLER PG 16 NORTH BETWEEN 22 & 23
300.96 BUR OAK 12 IN
627 BROOK 6.6' SW
676.5 SAME BROOK NE
722.7 SAME BROOK S.W.
2640 SET 1/4 SEC POST BUR OAK 8 IN S19E 59.4'; YELLOW OAK 10 N6W 66'
2814.9 YELLOW OAK 10 IN
4643.76 BUR OAK 18 IN
5256.24 BUR OAK 12 IN
5280 SET POST COR OF SEC 14,15,22,23 BUR OAK 18 S50E 29.04'; BUR OAK 15 N60W 23.76' LAND ROLLING (SLIGHTLY) 2ND RATE TIMBER OAK & HICKORY. OAK & HAZEL UNDERGROWTH
- 1871 COLLINS REMONUMNETATION NOTES PG 153 NORTH BETWEEN 22 & 23 VARIATION 4-30
620.4 CREEK
2620.2 INTERSECT 1/4 LINE 5.94' EAST OF CORNER. SET 1/4 STONE BY STUMP OF WITNESS TREE. CORRECTED VARIATION 4-22
CONTINUED NORTH VARIATION 5
5249.64 SET STONE FOR CORNER OF 14,15,22,23 BY ROOTS OF WITNESS TREES.
- 1963 BATTERMAN VOL 4 PG 168 FD 6X6 CUT ST. SET MON BOX OVER STONE & REFERENCED SAME.
- 1971 SHIMEALL #3189 1317.00 EAST TO 1/16TH COR & AN ANGLE OF 87-24-20 @ THE N 1/16TH COR OF THE SW 1/4 SEC 23 FROM THE SOUTH TO THE W 1/4 COR SEC 23
- 1991 BARNES P-17 ROAD PAVING PROJECT WILL INVOLVE THIS CORNER. DID NOT ACCEPT NOR REJECT MONUMENT. REFERENCE FOUND MONUMENT SO IT WOULD NOT BE DESTROYED BY THE PAVING PROJECT. DIAGRAM SHOWS ALL 4 OF BATTERMAN'S REFERENCE PIPES WERE FOUND.

TOP OF MON. BOX 1.0' DEEP. FD CUT L.S. WITH DRILL HOLE 16" DEEP IN MON. BOX. SET ALUM. EXTENSIONS ON TOP OF L.S. MON. IS 2' WEST OF CENTER OF PVMT. SET PK 2.00 TO THE EAST & NORTH.

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED FOUND CUT L.S

D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.

(E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.

I, Donald Barnes, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Donald Barnes

emboss

7-2-01

Number of included sheets **D**

CORNER CODE **P-17(1)**