

# U.S. PUBLIC LAND SURVEY MONUMENT RECORD

For Public Land Survey Corners in:

WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT

T. 1 N., R. 4 E

CORNER CODE INDEX

A	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25
B																									
C	6																								
D																									
E																									
F																									
G	1																								
H																									
I																									
J																									
K																									
L	18																								
M																									
N																									
O																									
P	19																								
Q																									
R																									
S	30																								
T																									
U																									
V																									
W																									
X	31																								
Y																									
Z																									

NEWARK TWP

ROCK COUNTY WI

IF AVAILABLE  
ROCK COUNTY COORDINATES PREFERRED

North \_\_\_\_\_ Elev. \_\_\_\_\_

East \_\_\_\_\_

Hor. Datum \_\_\_\_\_ Vert. Datum \_\_\_\_\_

LATITUDE \_\_\_\_\_ ELLIPS. HT. \_\_\_\_\_

LONGITUDE \_\_\_\_\_

GPS (X) \_\_\_\_\_ TRAVERSE (X) \_\_\_\_\_

BASED ON THE FOLLOWING CONTROL:

PLACE MONUMENT SYMBOL  AT PROPER LOCATION ON ABOVE INDEX

CORNER MONUMENT

WITNESS MONUMENT

(a)

BEARINGS ARE BASED ON:

USED DATA FROM  
FIELD BOOK 1 PG 67

OBSERVATION Sheet 61

FIELD BOOK \_\_\_\_\_ PAGE # \_\_\_\_\_

SHEET \_\_\_\_\_ OF \_\_\_\_\_

SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.

PLANNING & ZONING COMMITTEE ADOPTED THE ABOVE FORM ON 12/2/1982

CORNER CODE N7 (1)

NE564

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

- 1834 MILLER PG 34 EAST RANDOM BETWEEN SECS 17 & 20  
330 ENTER MARSH C S.E.  
2112 LEAVE SAME  
5272.74 SEC LINE 13.2' NORTH OF POST LAND 2ND RATE  
WEST CORRECTED BETWEEN SECS 17 & 20  
2636.04 SET 1/4 SEC POST YELLOW OAK 5 IN N20E 30.36'; BUR OAK 22  
S30W 9.24'  
5272.74 SEC COR
- 1851 Mc VEAN VOL 1 PG 6 USED CORNER TO SUBDIVIDE SECTION 20. STATES NOTHING ABOUT CORNER. VAR 6E 2644.62 TO THE CENTER OF SECTION 20 5279.34 TO S 1/4 COR SEC 20.
- 1871 COLLINS. REMONUMENTATION FIELD NOTES  
PG 191 EAST BETWEEN 17 & 20 VARIATION 7  
2651.88 SET 1/4 STONE IN LINE WITH FENCES NORTH & SOUTH BY ROOTS OF WITNESS TREES.  
CONTINUED EAST VARIATION 8- 15  
5305.74 SECTION CORNER NOV 1, 1871
- 1958 SHIMEALL PLAT OF SURVEY CALLS FOR AN ANGLE OF 88-50 AT THE SOUTHWEST CORNER FROM THE WEST QUARTER CORNER TO THE SOUTH QUARTER CORNER OF SECTION 17. HAROLD COMBS STATED THAT HIS FIELD NOTES CALLED FOR NOTHING AT THE SOUTH QUARTER CORNER OF SECTION 17. FOR LINE HE USED A MID POINT OF THE EAST/WEST FENCES ON THE NORTH AND SOUTH SIDE OF THE ROAD AT THAT LOCATION.
- 1989 BARNES VOL 6 PG 401 N89-03-13E 2653.28 TO NE COR SEC 20, S89-07-18W (SOLAR OBSERVATION) 2651.09 TO NW COR SEC 20, S1-24W 2645.5 TO COMPUTED CENTER OF SEC 20
- 1989 BARNES N-7 AN ELDERLY MAN STATED THAT A LONG TIME AGO THE HIGHWAY DEPARTMENT REMOVED THE STONE WHILE WORKING ON ROAD. HE SAID THAT THEY THREW THE STONE IN THE SOUTH DITCH. HE SAID THAT THE STONE WAS ABOUT 4' SOUTH OF THE CENTER OF THE PAVEMENT AND ON LINE WITH THE FENCES TO THE NORTH AND SOUTH. I DUG A HOLE 3' DEEP AND FOUND NOTHING. THERE WAS NO BLACK DIRT IN THE HOLE. THE TERRAIN ON BOTH SIDES OF THE ROAD INDICATES THAT THE ROAD WAS CUT AND THE STONE WAS PROBABLY REMOVED AS THE WITNESS CLAIMED. FOR THE EAST/WEST LOCATION, I USED COLLINS DISTANCES TO THE SW CORNER OF SECTION 17 AND THE SOUTH QUARTER CORNER OF SECTION 16 FOR PRORATION. I USED THE WITNESS'S STATEMENT AND KEPT THE CORNER ABOUT 4' SOUTH OF THE CENTER OF THE PAVEMENT. THIS IS IN HARMONY WITH McVEANS DISTANCE TO THE EAST/WEST QUARTER LINE OF SECTION 20. I PLACED AN ALUMINUM MONUMENT & REFERENCED SAME.

USED 1989 FIELD OBSERVATIONS TO ALUM. MON.

(C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED PERPETUATED LOCATION.

I, Donald Barnes, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Donald  
Barnes

6-29-01

SHEET 1 OF 1

CORNER CODE N7-1(1)

A-E 7.08 REQUIREMENT