

Paper weight-110# (minimum)

Black nonfading ink required

U.S. PUBLIC LAND SURVEY MONUMENT RECORD

For Public Land Survey Corners In:

WI ADMINISTRATIVE CODE A-E 7.08 REQUIREMENT

T. 3 N. R. 14 E. 4th P.M.

REV 10/23/2004

USMONREC.DWG

2 CORNER CODE INDEX

BRADFORD TWP

ROCK COUNTY WI

IF AVAILABLE

ROCK COUNTY COORDINATES PREFERRED

	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25
A																									
B																									
C																									
D																									
E																									
F																									
G																									
H																									
J																									
K																									
L																									
M																									
N																									
O																									
P																									
Q																									
R																									
S																									
T																									
U																									
V																									
W																									
X																									
Y																									
Z																									

North _____ Elev. _____

East _____

Hor. Datum _____ Vert. Datum _____

LATITUDE _____ ELLIPS. HT. _____

LONGITUDE _____

NAD83(91) _____ NETWORK ADJ. YR _____

GPS (X) _____ TRAVERSE (X) _____

BASED ON THE FOLLOWING CONTROL:

PLACE MONUMENT SYMBOL AT PROPER LOCATION ON ABOVE INDEX

CORNER MONUMENT

WITNESS MONUMENT

BEARINGS ARE BASED ON: ROCK COUNTY PROJECTION

FIELD BOOK _____ PAGE # _____
OR OBSERVATION SHEET _____

SHEET 1 OF 2

SHOW A PLAN VIEW DRAWING DEPICTING THE CORNER MONUMENT AND SURROUNDING PHYSICAL FEATURES, INCLUDING THE EXCAVATION AREA AND DEPTH.

PLANNING & ZONING COMMITTEE ADOPTED THIS FORM ON 12/2/1982

CORNER CODE A-25(1)

BR513 NECORSEC1

(B) Describe any record evidence, monument evidence, occupational evidence, testimonial evidence or any other material evidence you considered, and whether the monument was found or placed.

- 1937 SUNNY VOL 3 PG 361 DUG 6X8X3' DEEP HOLE & FD NO MON.
- 1972 JENSON VOL 6 & 6497 PG 116 FD OLD WOOD STAKE HOLE IN SUBSOIL, DOWN 18". REFERENCED SAME. TIES ARE TO TREES & FENCE POSTS
- 1973 JENSON CSM VOL 3 PG 40 FD COUNTY MON. SOUTH 270.00 ALONG SEC LINE TO NE PROPERTY CORNER WITH R/W PIPE EAST 33 OF THIS LOCATION.
- 1977 BARNES VOL 5 PG 356 FD CONC. MON. WITH BRASS DISK. REFERENCED SAME.
- 1980 BARNES VOL 6 PG 31 FD CONC MON 2751.14 TO FD CON MON @ SE E 1/4 COR SEC 1, 2637.70 TO FD ALUM @ E 1/4 COR SEC 36 JOHNSTOWN TWP
- 1982 BARNES BRADFORD TWP PROJ. SO-14-39W 2751.10 TO E 1/4 COR SEC 1 & N88-40-01W 2665.93 TO N 1/4 COR SEC 1.
- 1983 BARNES JOHNSTOWN TWP PROJ. ELEV 940 N1-28-50W 2637.67 TO E 1/4 COR SEC 36.
- 1994 BARNES A-25 WIDOT PROVIDED THE NAD83(91) STATE PLANE COORDINATES AND DESCRIBED THE MONUMENT THEY FOUND. THEY ESTABLISHED THE COORDINATES BY TRAVERSING FROM GPS STATIONS THAT THEY ESTABLISHED PRIOR TO THE ROCK COUNTY GPS NEWTORK. I TRANSCRIBED THEIR INFORMATION TO THIS SHEET. I ALSO CONVERTED THE STATE PLANE COORDINATES TO THE LATITUDE/LONGITUDE AND ROCK COUNTY COORDINATES THAT ARE SHOWN.
LATITUDE 42-40-03.15627 LONGITUDE 88-46-35.60787
COUNTY SYSTEM 263,668.696; 559,524.662
CONC. MON. STATE PLANE 245,716.34; 2,297,549.95
NAD83(91)
- 2002 LATHROP CSM VOL 25 PG 98 FD BRASS CAP. SOUTH 2751.12 TO FD BRASS CAP @ E 1/4 COR SEC 1, N89-01-25W 40.01 TO NE PROPERTY COR. LOT IS 270.06 WIDE.
- 2012 BARNES COUNTY READJUSTMENT N1-37-E 2637.69 TO E 1/4 COR SEC 36, SO-05-54W 2751.12 TO E 1/4 COR SEC 1 BRADFORD TWP, & N88-55-16W 2665.93 TO N 1/4 COR SEC 1 BRADFORD TWP

FD CONC. MON. / BRASS CAP.

C) Was the corner restored through acceptance of (1) an obliterated evidence location, or, (2) a found perpetuated location?

ACCEPTED FD CONC. MON.


D) Describe any material discrepancy between the location of the corner as restored or reestablished and the location of that corner as previously restored or reestablished by distance and direction. Show the discrepancy on the plan view drawing under (a), above. Show the distances between the corner as previously restored or reestablished and (1) the corner as restored or reestablished, and (2) to at least 4 of the witness monuments shown on the drawing in (a), above.

NONE

(E) Was the corner reestablished through lost corner proportionate methods? If so, show the method, including the directions and distances to other public land survey corners used as evidence or used for proportioning the corner location.

NO

I, Donald Barnes, hereby certify that the corner location as identified by the corner code index was determined by me under my direction and control and that this U.S. Public Land Survey Monument Record is correct and complete to the best of my knowledge and belief.

Seal
Emboss


SHEET 1 OF 2

CORNER CODE **A-25**
A.E. 7.08 REQUIREMENT

6-20-2012

ELEV 939.9 S87-57-03E 64.85 ELEV 939.2

N49-37-46W 22.715' CELL
N3-35-10W 74.40

S25-18-09E 79.21

CTH M

N24-04-04E 75.89

FD PIPE LEANING

1972 4" STEEL POST

- 3/4X24 REROD
- FD CONC MON
0.65'
DEEP
PHOTO ELEV 941
1983 TWP PROJ
940
- ◇ I BEAM

FD NOTHING

FD REROD
CSM N89-01-25W 40.01

S84-49-23W 29.32

1977 64.56

1977 52.43

N66-48-44E 17.372' CELL

R & D TOWNLIN RD

CSM 25-98

NE COR
SEC 1
BRADFORD TWP
T2N R14E

ELEV 940.7
1972 TOP OF TELE PED.

1977 45.30
1977 4
1977 2

1977 37.45

1972 44.73

1977 92.84

S75-47-17E CELL

S0-58-52E 139.11
1977 64.15
S25-31-32E 77.35
1972 78.27

1977 26
1977 26

S42-57-30E 91.76
CSM25-98 270.06

ELEV 940.4
6"

1' FD PIPE LEANING

OBSERVATION SHEET #633 JOHNSTOWN

1977 BARNES VOL 5 PG 356
1972 JENSEN #6497

EMBOSSED SEAL
Barnes
6-20-2012

SHEET 2 OF 2

A-25